

ASSIGNMENT

From: Date:

Estimated Cost:

OD (TP) / WS / TP RES / OD RES / EVA / INV / MY

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No. DM21HO01494/JT

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Rpt:

GIA / PR Seen:

Est. Repairs:

days

Res.:

Lum Sum:

%

3 Val.:

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

The UIC / Chassis frame / Body Structure affected due to collision.

Days Of Repair: 5

Resurvey No. of Trip: 3

Survey Fee:

Transportation:

) S + RS. SI

) Photos

) Others

TOTAL

Date/Time, File Pass to?

☐

Preli. Report

1)

☐

Final Report

Date/Time, File Return to?

2) 18/10/21-typist

Add Fee: ☐ Site Insp (\$☐ Interview (\$☐ Tech. Invs (\$☐ Weekend (\$

Report Format: TP

Lump Sum / I.B.I: (\$ 2582.28

ASS. REC BY: Maria

Veh No: GBH 43403 Yr Regn: 31/5/18
Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Nissan NV350 C.C. 2488

Colour: Grey A/C: Insured / Std / NI / NA

Sp. Reading: 91624 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Worder / Jammed / Leaked / Burnt or

Brake: Worder / Jammed / Leaked / Burnt or

Modi: N/S / Rim / STD A/Rim or

Tyre Size: F: 195 R15

R:

BS/ DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 7 mm R/Bal. 7 mm

L/Bal. 7 mm L/Bal. 7 mm

D.O.A. 5/10/21 D.O.I. 11/10/21

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear O/S.

The UIC / Chassis frame / Body Structure affected due to collision.

Date/Time, File Pass to?

☐

Preli. Report

1)

☐

Final Report

Date/Time, File Return to?

2) 18/10/21-typist

Add Fee: ☐ Site Insp (\$☐ Interview (\$☐ Tech. Invs (\$☐ Weekend (\$

Report Format: TP

Lump Sum / I.B.I: (\$ 2582.28

TOTAL

18/10/21 No second hand parts
P/P \$2582.28 confirmed with Susan (Red 3067.22, 54%)



LIU'S BROTHER AUTO ENGINEERING WORKSHOP
No. 1 Kaki Bukit Avenue 6 #01-01 Auto Bay @ Kaki Bukit Singapore 417883
ROB No: 53291793J . Tel: 6741-1730 / 731 Email: liusbros@gmail.com

Invoice/Ref No: GBH4340B211005

Estimate

Customer		Date:	11-10-21
Name:	EQ Insurance Company Limited	Vehicle No:	GBH4340B
Address:	Motor Claims Department 5 Maxwell Road #17-00 Tower Block MND Complex Singapore 069110	Model/Make:	Nissan NV350 Panel Van 5DR 2.5 5AT

Item No.	Descriptions Of Parts	Original Quotation / Estimation	Revised Quotation / Cost Of Repair
1	Rear Tailgate	\$ 1,998.30	N X
2	Tailgate "Nissan" Logo Motif	\$ 59.00	N X
3	Tailgate "NV 350" Emblem	\$ 59.90	N ✓
4	Tailgate "70 KM/H" Emblem	\$ 10.00	SN ✓ s/n
5	Tailgate "Urvan" Emblem	\$ 101.30	N ✓
6	Bumper	\$ 667.20	N ✓
7	Bumper Clip 1 Set	\$ 30.00	N ✓
8	Bumper Side Holder	\$ 48.00	N ✓
9	Tail Lamp Rh	\$ 224.80	N ✓
10	End Panel Outer	\$ 168.00	N X
11	Tail Lamp Housing Panel Rh	\$ 195.00	N X
12	Air Vent Rh	\$ 38.00	N ✓
13	Bumper Reverse Sensor	\$ 220.00	SN 200 s/n
To check all wiring & electrical component for proper function		\$ 40.00	- 20
Remove and refix rear bumper reverse sensor		\$ 50.00	- 50
Labor for Panel Beating, Cut, Weld, Straighten & Replacing Parts Etc		\$ 850.00	- 600
To putty & spray painting & including touch up paint on accident affected area		\$ 850.00	- 650
To apply Rust Proofing, reseal tuff-coating treatment on accident area		\$ 40.00	- nux

Total Parts & Labour of estimate for damaged vehicle

\$ 5,649.50

Total amount in Lump Sum Basis for repaired vehicle

SDLS:



M/s Liu's Bro Auto Engrg Wks

not allowed
LKR
P/P 2582-28
11/10/21
take photo before painting
5 days.

submit to insurance.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

P-1169-20
102
P-1082-28
S-N-210
L-1320
\$2582-28