

ENG HENG AUTOMOBIL TRADING CO

Not Withain
 11 Pny @ 9500/h
 Recovery After Pain
 10 days

2009

Date: 8-Oct-21

LEXUS IS200 JTHBK262505099598

Estimate Quote SJT 3160C

SN	QTY	DESCRIPTION				
1	1 pc	REAR BOOT LID			\$ By 937.24	✓
2	1pc	REAR BOOT LID WEATHERSTRIP	175-350N	Di	\$ 250.62	50/50
3	2 pc	REAR BOOT LID HINGE - RIGHT/ LEFT		\$ 132.00	\$ K 264.00	X
4	1 pc	REAR BOOT LID LOCK - UPPER			\$ R 499.00	X
5	1 pc	REAR BOOT LID LOCK - LOWER			\$ A 322.00	X
6	1 pc	"LEXUS" BADGE	70		\$ M 120.00	✓
7	1 pc	"IS 250" BADGE	80		\$ M 120.00	✓
8	1 pc	LEXUS EMBLEM	90		\$ M 120.00	✓
9	1 set	NO PLATE N BRACKET		NETT	\$ M 80.00	45/50
10	1 pc	NO PLATE GARNISH			\$ CM 254.00	✓
11	1 pc	TAIL LAMP LH - BOOT LID	484.30		\$ CM 654.89	✓
12	1pc	TAIL LAMP RH - BOOT LID			\$ M 654.89	X
13	1pc	TAIL LAMP LH - FENDER			\$ CM 569.40	✓
14	1pc	TAIL LAMP RH - FENDER			\$ M 569.40	✓
15	1 pc	REAR BUMPER			\$ M 921.30	✓
16	1pc	REAR BUMPER REFLECTOR - RIGHT			\$ CM 120.00	✓
17	1pc	REAR BUMPER REFLECTOR - LEFT			\$ CM 120.00	✓
18	1pc	REAR BUMPER SIDE RETAINER (RH / LH)		\$ 60.00	\$ D 120.00	✓
19	1pc	REAR BUMPER SPONGE			\$ CM 235.00	✓
20	1pc	REAR BUMPER REINFORCEMENT			\$ M 465.00	✓
21	1pc	REAR BUMPER TOW COVER			\$ M 21.65	✓
22	1 SET	REVERSE SENSOR		NETT	\$ 380.00	✓
23	1pc	REAR LEFT SIDE PANEL SIDE TRIM			\$ 185.00	✓
24	1pc	REAR RIGHT SIDE PANEL TRIM			\$ M 185.00	X
25	1pc	TYRE COMPARTMENT SPARE WHEEL COVER			\$ M 178.00	✓
26	1pc	REAR END PANEL			\$ M 665.00	✓
27	1pc	REAR END PANEL TOP GARNISH	342		\$ CM 365.00	✓
28	1pc	SPARE TYRE PANEL			\$ M 565.00	X
29	1pc	TYRE COMPARTMENT TRAY COVER			\$ 205.80	✓
30	1pc	REAR FENDER - LH			\$ M 1,124.90	✓
31	1pc	REAR FENDER SHIELD - LH			\$ M 210.00	X
32	1pc	LEFT REAR DOOR - INNER LOCK			\$ M 515.00	X
33	1 SET	ENGINE MOUNTING			\$ 362.10	X
34	1SET (03)	GEAR BOX MOUNTING			\$ M 145.00	X
35	1	REAR EXHAUST ASSEMBLY	2014.50		\$ M 2,446.70	✓
36	6	EXHAUST 'O' RINGS			\$ M 201.60	✓
					\$ 15,152.49	

108

ENG HENG AUTOMOBIL TRADING CO

		BALANCE B/F		\$ 15,152.49	
37	1 pc	TYRE COMPARTMENT UNDERCOVER		\$ <i>in</i> 365.80	X
38	1 pc	SPARE TYRE LOCK		\$ <i>CM</i> 188.90	✓
39	1 pc	REAR LEFT FENDER LAMP GARNISH LOWER	<i>NC</i>	\$ 78.50	✓
40	1 pc	REAR LEFT FENDER LAMP GARNISH UPPER	<i>NC</i>	\$ 92.15	✓
41	1pc	REAR RIGHT FENER LAMP GARNISH LOWER	<i>NC</i>	\$ 78.50	✓
42	1pc	REAR RIGHT FENER LAMP GARNISH UPPER	<i>NC</i>	\$ 92.15	✓
43		FRONT HEADLAMP HID BULB	<i>NC</i>	\$ 380.00	X
44		WORKMANSHIP TO CHANGE ENGINE MOUNTING & GEAR BOX MOUNTING		\$ <i>NN</i> 250.00	X
45		WORKMANSHIP TO PANEL BEAT, REPLACE RAR END PANEL, REAR BOOT LID, REAR BUMPER. REINFORCEMENT, REAR LEFT FENDER, STRAIGHTEN AND REALIGN		\$ 1,800.00	1200
46		WORKMANSHIP TO DISMANTLE WIRINGS, FITTINGS AND REFIT	<i>Sparks</i>	\$ 350.00	1200
47		RESPRAY PAINT REAR BOOT LID, LUGGUAGE COMPARTMENT, REAR BUMPER, REAR LEFT FENDER.		\$ 1,500.00	1200
48		COMPUTERISED WHEEL ALIGNMENT		\$ <i>nn</i> 120.00	X
				\$ 20,448.49	

DOLLARS: TWENTY THOUSAND FOUR HUNDRED FORTY EIGHT & CENTS FORTY NINE ONLY

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: