

55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/TP/0829/2021/GW
DATE : 11-Oct-21
WIP :

VEHICLE IN WORKSHOP. KINDLY ARRANGE SURVEY
YOUR INSURED VEH NO : XE 3551 X

CHINA TAIPING INSURANCE (SG) PTE LTD
105 CECIL STREET
#19-00 THE OCTAGON
SINGAPORE 069534
Attn: Ms Angie - Motor Claims Dept/Windscreen
Tel: 6389 6541 - Fax: 6224 7175

OWNER'S NAME : MR CHRIS ANG PECK YEOW
ADDRESS : 30 LORONG, 107 CHANGI
#04-04
SINGAPORE 426446
TELEPHONE : HP +65 98778902
TYPE OF CLAIM : THIRD PARTY CLAIM
POLICY NO : P10515833R00
VEHICLE NO : **SMK 5775 C**
MODEL CODE : AUDI A3 SB 1.0 TFSI S TRONIC LED
MODEL YEAR : 25/3/2019
ENGINE NO : CHZC 27295
CHASSIS NO : WAUZZZ8V9KA055901
MILEAGE : 45388 KM
DATE IN : 8-Oct-21
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 8-Oct-21
PLACE OF ACCIDENT : ECP TOWARDS CITY (LAMP POST 234)

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SMK 5775 C (FRONT)

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORN, OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY.	S/N \$ 360.00	
2	TO REMOVE AND TRANSFER LHS HEADLIFHT'S CONTROL UNIT AND POWER MODULE.	S/N \$ 350.00	
3	TO REMOVE AND REINSTALL BOTH FRONT DOOR PANEL TRIM. TO REMOVE AND REINSTALL BOTH WING MIRROR ASSY TO FACILITATE RESPRAY OF RHS FRONT DOOR.	S/N \$ 560.00	
4	TO DISMANTLE AND RENEW FRONT BUMPER, LHS FRONT FENDER AND LHS HEADLIGHT. TO REPAIR BOTH FRONT DOORS. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$ 2,800.00	
5	TO RESPRAY FRONT BUMPER, LHS FRONT FENDER, BONNET AND BOTH FRONT DOORS.	\$ 4,000.00	
SUB TOTAL LABOUR CHARGES (FRONT)		: \$ 8,070.00	

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SMK 5775 C (REAR)

S/N	NATURE OF JOBS		ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
6	TO REMOVE AND REINSTALL REAR PARKING AID. CHECK FUNCTION.	S/N \$	280.00	
7	TO RENEW RHS 1/4 GLASS TO FACILLITATE FOR FENDER RENEWAL	S/N \$	300.00	
8	TO INSTALL SOLAR FILM FOR RHS REAR DOOR WINDOW GLASS AND RHS SIDE 1/4 GLASS.	S/N \$	400.00	
9	TO CARRY OUT WATER SEEPAGE TEST ON 1 /4 GLASS.	S/N \$	200.00	
10	TO DISLODGE AND REINSTALL REAR WIRE HARNESS FOR LIGHTS, BATTERY MANAGER, FUSE AND RELAY TRAYS, ELECTRICAL AND AUDIO EQUIPMENT. INSPECT FOR DAMAGE AND RENEW WHERE NECESSARY.	S/N \$	1,400.00	
11	TO REMOVE AND REINSTALL REAR SEAT, BACK REST, HAT TRAY, ABCD PILLAR TRIMS, LUGGAGE COMPARTMENT TRIMS. DISLODGE ROOF LINER AND DISENGAGE CURTAIN AIRBAG ETC.	S/N \$	1,400.00	
SUB TOTAL LABOUR CHARGES (REAR)		:	\$ 3,980.00	

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SMK 5775 C (REAR)

S/N	NATURE OF JOBS		ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
12	TO REMOVE AND TRANSFER RHS REAR DOOR'S MULTI - LOCK SYSTEM AND POWER WINDOW DEVICES. INSPECT FOR DAMAGES.	S/N \$	350.00	
13	TO DISMANTLE AND RENEW REAR BUMPER AND RHS REAR DOOR. TO CUT OUT AND WELD RHS REAR FENDER. RE-ORGANISE CRASH MANAGEMENT COMPONENTS.	\$	5,600.00	
14	TO RESPRAY REAR BUMPER, RHS REAR FENDER, RHS REAR DOOR, DOOR HANDLE, RHS SILL PANEL, DRAIN CHANNEL, ROOF CHANNEL, DOOR ENTRANCE AND REAR END PANELLING.	\$	5,500.00	
15	TO RENEW LHS FRONT RIM AND RHS REAR RIM. TO CARRY OUT PRE/POST WHEEL ALIGNMENT.	S/N \$	560.00	
16	TO CARRY OUT PRE/POST DIAGNOSTIC CHECK	S/N \$	384.00	
TOTAL LABOUR CHARGES (FRONT + REAR)		:	\$ 24,444.00	

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMK 5775 C (FRONT)

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
1	FRONT BUMPER	1	\$ 2,016.00	
2	FRONT BUMPER FIXING PARTS	1	\$ 187.00	
3	FRONT BUMPER GUIDE SECTION - LH	1	\$ 39.00	
4	FRONT BUMPER GRILLE - CENTER	1	\$ 160.00	
5	FRONT BUMPER CLOSING ELEMENT - LOWER CENTER	1	\$ 297.00	
6	FRONT BUMPER CLOSING ELEMENT - LH	1	\$ 297.00	
7	FRONT AIR GUIDE GRILLE - LH	1	\$ 188.00	
8	FRONT REINFORCEMENT BEAM	1	\$ 795.00	
9	FRONT FOAM FILLER PIECE	1	\$ 189.00	
10	FRONT REINFORCEMENR BEAM FOAM	1	\$ 122.00	
11	FRONT SIGNAL HORN - HIGH TOME	1	\$ 200.00	
12	FRONT FENDER - LH	1	\$ 851.00	
13	FRONT FENDER POP RIVET	8	\$ 27.00	
14	FRONT FENDER ATTACHMENT PARTS	1	\$ 72.00	
15	FRONT FENDER BRACKET - LH CENTRE	1	\$ 48.00	
16	FRONT FENDER BRACE - LH	1	\$ 96.00	
17	FRONT FENDER CLOSING ELEMENT - LH	1	\$ 62.00	
18	FRONT FENDER BRACKET - LH	1	\$ 28.00	
19	FRONT WHEEL HOUSING LINER - LH	1	\$ 169.00	
20	FRONT WHEEL HOUSING LINER ATTACHMENT PART - LH	1	\$ 57.00	
21	LED HEADLIGHT - LH	1	\$ 5,455.00	
SUB TOTAL SPARE PARTS (FRONT)		:	\$ 11,355.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APROVED
 SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMK 5775 C (FRONT)

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
21	LIFT CYLINDER FOR HEADLIGHT WASHER SYSTEM - LH	1	\$ 142.00	
22	HOSE FOR HEADLIGHT WASHER SYSTEM - LH	1	\$ 68.00	
23	FRONT WINDOW SLOT SEAL - LH	1	\$ 270.00	
SUB TOTAL SPARE PARTS (FRONT)		:	\$ 11,835.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMK 5775 C (REAR)

S/N	PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES		REMARKS
			S/NETT		
21	REAR BUMPER	1	\$	2,070.00	
22	REAR BUMPER FIXING PARTS	1	\$	193.00	
23	REAR WHEEL HOUSING LINER ADAPTER - RH	1	\$	38.00	
24	REAR BUMPER LOCKING MECHASNISM - LH	1	\$	14.00	
25	REAR BUMPER LOCKING MECHASNISM - RH	1	\$	14.00	
26	REAR BUMPER GUIDE SECTION - RH	1	\$	67.00	
27	REAR FENDER - RH	1	\$	4,140.00	
28	REAR SIDE WINDOW - RH	1	\$	292.00	
29	REAR SIDE WINDOW TRIM STRIPS - RH	1	\$	261.00	
30	REAR WHEEL SPOILER - RH	1	\$	35.00	
31	REAR WHEEL HOUSING LINER - RH	1	\$	240.00	
32	REAR WHEEL HOUSING LINER ATTACHMENT PART RH	1	\$	57.00	
33	REAR DOOR - RH	1	\$	2,767.00	
34	REAR DOOR OUTER SEAL - RH	1	\$	161.00	
35	BONDING AGENT	1	\$	49.00	
36	CLEANING SOLUTION	1	\$	68.00	
37	APPLICATOR	1	\$	8.00	
38	REAR DOOR ATTACHMENT PART	1	\$	129.00	
39	REAR DOOR CATCH - RH	1	\$	94.00	
40	REAR DOOR INNER SEAL - RH	1	\$	191.00	
SUB TOTAL SPARE PARTS (REAR)		:	\$	10,888.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMK 5775 C (REAR)

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
21	REAR DOOR HINGE HALF UPPER - RH UPPER	1	\$ 44.00	
22	REAR DOOR HINGE HALVES - RH UPPER	1	\$ 46.00	
23	REAR DOOR HINGE HALF UPPER - RH LOWER	1	\$ 47.00	
24	REAR DOOR HINGE HALF LOWER - RH LOWER	1	\$ 48.00	
25	REAR WINDOW REGULATOR WITHOUT MOTOR - RH	1	\$ 268.00	
26	REAR WINDOW REGULATOR MOTOR - RH		\$ 271.00	
27	REAR DOOR CONTROL UNIT - RH	1	\$ 484.00	
28	REAR WINDOW SLOT SEAL - RH REAR	1	\$ 270.00	
29	ROOF MOLDING - RH	1	\$ 591.00	
30	REAR CORNER TRIM - RH	1	\$ 74.00	
31	REAR WINDOW GUIDE - RH	1	\$ 420.00	
32	REAR TRIM FOR PILLAR B - RH	1	\$ 117.00	
33	REAR WINDOW SEPTURE SEAL - RH INNER	1	\$ 113.00	
34	REAR WINDOW - RH	1	\$ 211.00	
35	REAR DOOR INNER PANEL RH	1	\$ 1,651.00	
36	FRONT TRIM FOR PILLAR B - RH	1	\$ 105.00	
37	FRONT WINDOW SLOT SEAL - RH	1	\$ 270.00	
38	FRONT WHEEL RIM - LH	1	\$ 1,166.00	
39	REAR WHEEL RIM - RH	1	\$ 1,166.00	
40	1/4 GLASS SEALANT	S/N	\$ 100.00	
SUB TOTAL SPARE PARTS (REAR)		:	\$ 7,462.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMK 5775 C (REAR)

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
41	ACRYLIC SEALANT	S/N	\$ 180.00	
21	CAVITY WAX	S/N	\$ 140.00	
22	STONE CHIP	S/N	\$ 180.00	
23	METAL FILLIER POWDER	S/N	\$ 280.00	
24	REAR TYRE - RH		TBC	
25	SUNDRIES		\$ 400.00	
TOTAL SPARE PARTS (FRONT + REAR)		:	\$ 31,365.00	
TOTAL LABOUR CHARGES (FRONT + REAR)		:	\$ 24,444.00	
GRAND TOTAL		:	\$ 55,809.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME :
SURVEYED DATE :
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS :

PLEASE NOTE : THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY. FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT