

PREMIUM AUTOMOBILES

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg



Supplementary Estimate-1

Hui Zhen.

GST Reg No. 19-9902271-W

China Taiping Insurance (SG) Pte Ltd
105 Cecil Street
#19-00 The Octagon
Singapore 069534
Attn: Motor Claims Dept
Tel: 6389 6541 - Fax: 6224 7175

Estimate No.
Date
Service Advisor
Pages
Regn No
Model No

PA/TP/0829/2021/GW
18-Oct-21
CHANG
1 of 1
SMK 5775 C
AUDI A3 SB 1.0 TFSI

Quantity	Description	Unit Price	Amount
Labours			
1	TO REMOVE AND REINSTALL AIRCON CONDENSER RADIATOR AND ADDITIONAL RADIATOR. CHECK ELECTRICAL FANS AND CONTROL UNIT. PRESSURISE COLING SYSTEM. TO CARRY OUT VACUUM AND REGAS.	S/N \$ 1,400.00	✓
2	TO RENEW FRONT LOCK CARRIER AND ALIGN TO POSITION.	\$ 2,800.00	2100
Parts			
1	WASH WATER RESERVOIR <i>Pishled</i>	\$ 206.00	✓
2	FRONT LOCK CARRIER <i>could</i>	\$ 727.00	✓
3	COOLANT <i>new</i>	\$ 266.00	✓
4	REAR WHEEL HOUSING TRIM - RH <i>ct</i>	\$ 106.00	✓
GRAND TOTAL		\$ 5,505.00	

For Premium Automobiles Pte Ltd

Adrian L
18/10/21
Sig.

Authorised Signature

Add 3 Days

Car in

12/10/21

wip:

PREMIUM AUTOMOBILES

Kiam / Hong

C-T-Adrian
-19 days-

55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMK 5775 C (FRONT)

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
1	FRONT BUMPER Distorted	1	\$ 2,016.00	✓
2	FRONT BUMPER FIXING PARTS seen	1	\$ 187.00	x
3	FRONT BUMPER GUIDE SECTION - LH Dam	1	\$ 39.00	✓
4	FRONT BUMPER GRILLE - CENTER new	1	\$ 160.00	x
5	FRONT BUMPER CLOSING ELEMENT - LOWER CENTER replaced	1	\$ 297.00	✓
6	FRONT BUMPER CLOSING ELEMENT - LH buld	1	\$ 297.00	✓
7	FRONT AIR GUIDE GRILLE - LH cut	1	\$ 188.00	✓
8	FRONT REINFORCEMENT BEAM ?	1	\$ 795.00	?
9	FRONT FOAM FILLER PIECE buld	1	\$ 189.00	✓
10	FRONT REINFORCEMENT BEAM FOAM ?	1	\$ 122.00	?
11	FRONT SIGNAL HORN - HIGH TONE cut	1	\$ 200.00	✓
12	FRONT FENDER - LH Distorted	1	\$ 851.00	✓
13	FRONT FENDER POP RIVET new	8	\$ 27.00	✓
14	FRONT FENDER ATTACHMENT PARTS new	1	\$ 72.00	+
15	FRONT FENDER BRACKET - LH CENTRE But	1	\$ 48.00	✓
16	FRONT FENDER BRACE - LH But	1	\$ 96.00	✓
17	FRONT FENDER CLOSING ELEMENT - LH Distorted	1	\$ 62.00	✓
18	FRONT FENDER BRACKET - LH But	1	\$ 28.00	✓
19	FRONT WHEEL HOUSING LINER - LH De buld	1	\$ 169.00	✓
20	FRONT WHEEL HOUSING LINER ATTACHMENT PART - LH new	1	\$ 57.00	+
21	LED HEADLIGHT - LH cracked	1	\$ 5,455.00	✓
SUB TOTAL SPARE PARTS (FRONT)		:	\$ 11,355.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

 PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMK 5775 C (FRONT)

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
21	LIFT CYLINDER FOR HEADLIGHT WASHER SYSTEM - LH <i>authd</i>	1	\$ 142.00	<i>✓</i>
22	HOSE FOR HEADLIGHT WASHER SYSTEM - LH <i>Deled</i>	1	\$ 68.00	<i>✓</i>
23	FRONT WINDOW SLOT SEAL - LH <i>Not in</i>	1	\$ 270.00	<i>x-</i>
SUB TOTAL SPARE PARTS (FRONT)		:	\$ 11,835.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.



55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL : NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMK 5775 C (REAR)

S/N	PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES		REMARKS
			S/NETT		
21	REAR BUMPER <i>Defnd</i>	1	\$	2,070.00	✓
22	REAR BUMPER FIXING PARTS <i>seen</i>	1	\$	193.00	X.
23	REAR WHEEL HOUSING LINER ADAPTER - RH	1	\$	38.00	
24	REAR BUMPER LOCKING MECHANISM - LH	1	\$	14.00	
25	REAR BUMPER LOCKING MECHANISM - RH	1	\$	14.00	
26	REAR BUMPER GUIDE SECTION - RH <i>emld</i>	1	\$	67.00	✓
27	REAR FENDER - RH <i>Distorted</i>	1	\$	4,140.00	✓
28	REAR SIDE WINDOW - RH <i>seen</i>	1	\$	292.00	✓
29	REAR SIDE WINDOW TRIM STRIPS - RH	1	\$	261.00	
30	REAR WHEEL SPOILER - RH <i>seen</i>	1	\$	35.00	X.
31	REAR WHEEL HOUSING LINER - RH <i>?</i>	1	\$	240.00	?
32	REAR WHEEL HOUSING LINER ATTACHMENT PART RH <i>seen</i>	1	\$	57.00	X.
33	REAR DOOR - RH <i>Distorted</i>	1	\$	2,767.00	✓
34	REAR DOOR OUTER SEAL - RH <i>seen</i>	1	\$	161.00	✓
35	BONDING AGENT <i>?</i>	1	\$	49.00	?
36	CLEANING SOLUTION <i>?</i>	1	\$	68.00	?
37	APPLICATOR <i>?</i>	1	\$	8.00	?
38	REAR DOOR ATTACHMENT PART <i>seen</i>	1	\$	129.00	X.
39	REAR DOOR CATCH - RH <i>?</i>	1	\$	94.00	?
40	REAR DOOR INNER SEAL - RH <i>seen</i>	1	\$	191.00	X.
SUB TOTAL SPARE PARTS (REAR)		:	\$	10,888.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMK 5775 C (REAR)

			DAMAGED PARTS & PRICES		
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS	
21	REAR DOOR HINGE HALF UPPER - RH UPPER ?	1	\$ 44.00	?	
22	REAR DOOR HINGE HALVES - RH UPPER ?	1	\$ 46.00	?	
23	REAR DOOR HINGE HALF UPPER - RH LOWER ?	1	\$ 47.00	?	
24	REAR DOOR HINGE HALF LOWER - RH LOWER ?	1	\$ 48.00	?	
25	REAR WINDOW REGULATOR WITHOUT MOTOR - RH <i>Good</i>	1	\$ 268.00	✓	
26	REAR WINDOW REGULATOR MOTOR - RH ?	1	\$ 271.00	?	
27	REAR DOOR CONTROL UNIT - RH <i>new</i>	1	\$ 484.00	x.	
28	REAR WINDOW SLOT SEAL - RH REAR <i>wrapped</i>	1	\$ 270.00	✓	
29	ROOF MOLDING - RH <i>new</i>	1	\$ 591.00	x.	
30	REAR CORNER TRIM - RH <i>new</i>	1	\$ 74.00	x.	
31	REAR WINDOW GUIDE - RH <i>new behind</i>	1	\$ 420.00	✓	
32	REAR TRIM FOR PILLAR B - RH <i>new</i>	1	\$ 117.00	x.	
33	REAR WINDOW SEPTURE SEAL - RH INNER <i>new</i>	1	\$ 113.00	?	
34	REAR WINDOW - RH <i>shattered</i>	1	\$ 211.00	✓	
35	REAR DOOR INNER PANEL RH <i>new</i>	1	\$ 1,651.00	x.	
36	FRONT TRIM FOR PILLAR B - RH <i>cut</i>	1	\$ 105.00	✓	
37	FRONT WINDOW SLOT SEAL - RH <i>new</i>	1	\$ 270.00	x.	
38	FRONT WHEEL RIM - LH <i>cut</i>	1	\$ 1,166.00	✓	
39	REAR WHEEL RIM - RH <i>cut</i>	1	\$ 1,166.00	✓	
40	1/4 GLASS SEALANT <i>new</i>	S/N	\$ 100.00	✓	
SUB TOTAL SPARE PARTS (REAR)			:	\$ 7,462.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

Add

NO16 185 7 X 8

WHT 006 772 A X 2

N 90814601 X 2

8V0 805 673 2

8ko 837 199 X 3