



RICKY TEO BATTERY & TYRES TRADING

Steve (Lkk) With Prejudice
12/10/21 4 days
L/S
Resumeny After Sprng

Registration no. 34040800J

BLOCK 1002

BT MERAH LANE 3 #01-91

SINGAPORE 159719

TEL: (65) 90616611

Email: rickyteo56@yahoo.com

Date: 12/10/2021

Attn: Motor Claim Dept

Re: Estimate repair cost of Mercedes Benz E250 SKL919G

SN	DESCRIPTION						AMOUNT
1	Rear bumper	/ DD					1,490.6 1355-
2	Rear bumper lower	/ WT					560.8 489-
3	Rear bumper side guide LH & RH	/ BR					173 /
4	Rear bumper lower bracket LH & RH	/ BR					82.4 41.20-
5	Rear bumper centre bracket	/ BR				3657.20	159 -
6	Rear bumper tow cover	x nn				-10%	68 x
7	Rear bumper reinforcement	/ DD				3291.48	860 780-
8	Rear end panel	x R					1,440 x
9	Rear end panel inner garnish	x nn					255 x
10	Rear PDC sensor (4x)	/ Shorted			250x 2 pcs		1,160 500-
11	Rear PDC sensor spacer ring (4x)	/ REC					90 40-
12	Rear taillamp LH & RH	x nn					1,486 x
13	Rear taillamp bracket LH & RH	/ BR					160 120-
	SUB TOTAL						7,984.8
	LESS TRADE DISCOUNT 10%						-798.48
	SUB TOTAL						7,186.32
	SPECIAL NETT ITEM						30 -
1	Rear bumper clips & rivets	/ REC					80 30-
2	Panel joint sealant	x nn					100 x
	SUB TOTAL						180
	LABOUR						
1	Labour to remove/refit/repair & replace affected parts					1000	1,000 400
2	Spray paint on the affected portion						700 400
3	Labour to remove/replace/refix rear upholstery						200 30
4	Labour to install reverse sensor						100 30
5	To conduct wiring check for rear portion						50 30
6	To apply anti rust coating						200 30
7	To perform system diagnostic & reset ECU.						300 80
	SUB TOTAL						2,550
	GRAND TOTAL						9,916.32