



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
ALLIED WORLD ASSURANCE COMPANY LTD (SINGAPORE BRANCH) 60 ANSON ROAD #08-01 (8th FLOOR) MAPLETREE ANSON SINGAPORE 079914		Ref: CS3/AWA20005574/Evf3e2-1 Date: 26/10/2021 Code: AWA	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	YP 3409E	Veh. Inspected	FBB 8129B
Policy No.	AVCPSB0082391903	Coverage (\$)	0.00
Claim No.	NSV2000159/HLF	Excess (\$)	0.00
Assign From	HEW LEE FONG	Assign Date	11/10/2021
2. Vehicle Particulars & Condition			
Make & Model	BAJAJ PULSAR	c.c	178
Engine No.	HIDDEN	Year of Reg.	2007
Chassis No.	MD2DHDJZZNCH61419	Colour	RED
Odometer	99999 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	FAIR		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	60/70-17	DUNLOP	5 mm
L/H Front Tyre			mm
R/H Rear Tyre	70/80-17	DUNLOP	5 mm
L/H Rear Tyre			mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT AND REAR PORTION. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	24/04/2020	Inspection Date	06/05/2020
Survey held at	EQUATOR BROTHERHOOD 25 KAKI BUKIT ROAD 4 #03-19 SYNERGY @KB SINGAPORE 417800		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days	