

MAH LIAN MOTOR VEHICLE REPAIRER

No 38 Defu Lane 9 Singapore 539278
 TEL: 62823336 FAX: 62893336 Email: mahlian@singnet.com.sg
 GST M90362564P RCB NO 201327339E

M/S : MSIG Insurance (Singapore) Pte Ltd
 4 Shenton Way , #21-01 SGX Centre 2
 Singapore 068807

TEL: 6827 7602 FAX: 6827 2708
 ATTN: Motor Claim Department

Your Ref No: TEE RECYCLING P L
 Claim Type: Third Party
 Accident Date: 08/10/2021
 TP Veh Reg No: XD7044Y

Estimate No: ES1700919
 Date: 08 Oct 2021
 Policy No: 21-MJ001334-R03
 Veh Reg No: XD614Z
 Make/Model: MITSUBISHI
 FV517KM2RDEB
 Chassis No: FV517KA00142
 Engine No: 6D24384864
 Reg. Date: 15/09/2006

Estimate Repair Cost to Vehicle No :XD614Z

Description	U/Price	Quantity	List Price	Amount
			<u>S\$</u>	<u>S\$</u>
List Price				
1 Front Windscreen Glass	2,213.37	1 PC	2,213.37	294.50
2 Front Windscreen Glass Rubber	876.60	1 PC	876.60	502 s/w
3 Front Corner Panel -LH	852.68	1 PC	852.68	X
4 Front Corner Panel Seal -LH	85.78	1 PC	85.78	X
5 Front Door Assy - LH	4,567.80	1 PC	4,567.80	X
6 Front Door Garnish -LH	120.86	1 PC	120.86	X
7 Front Side Lamp -LH	255.53	1 PC	255.53	X
8 Front Side Lamp Rim -LH	252.34	1 PC	252.34	X
9 Step Panel Lower - LH	403.49	1 PC	403.49	X
10 Front Bumper	2,088.37	1 PC	2,088.37	X
11 Front Bumper Side Garnish	120.53	1 PC	120.53	X
12 Side Mirror Stay - LH	708.59	1 PC	708.59	X
13 Side Mirror Lower Bracket - LH	134.03	1 PC	134.03	X
			12,679.97	
	Less 25%		3,169.99	9,510.00
Labour				
14 Labour to remove & refit front windscreen glass ,rubber seal .	120.00	1 JOB	120.00	✓
15 Labour to connect & refocus all light .	280.00	1 JOB	280.00	X
16 Labour to remove & dismantle & weld & refit all above parts .	1,300.00	1 JOB	1,300.00	600
17 To rust proofing at affected area .	380.00	1 JOB	380.00	X
18 To spray & painting at accident affected area .	900.00	1 JOB	900.00	500
			2,980.00	2,980.00

Total S\$ 12,490.00

Add GST @ 7% 874.30

Total Amount Payable S\$ 13,364.30

LKK Auto Consultants hence notify
 the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged parts during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

For MAH LIAN MOTOR VEHICLE
 REPAIRER

AUTHORISED SIGNATURE

2-3055-99
 252
 2291.99
 3806.49

TOTAL SINGAPORE DOLLARS TWENTY THOUSAND THREE HUNDRED SIXTY FOUR AND CENTS THIRTY ONLY