



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

CHINA TAIPING INSURANCE (S) PTE LTD

INV No. AC2200193

3 ANSON ROAD #16-00
SPRINGLEAF TOWER
SINGAPORE 079909

INV Date 10/01/2022
Reference CC6/CTI21010415/Ara3q2
Code CTI

PROFESSIONAL SERVICE FEE

Vehicle No. SGK 319R
Insured Veh. GBJ 483M
Claim No. SNM21D205732/LKKDS
Policy No. DMCVSNW00115662002
Accident Date 07/10/2021
Inspection Date 08/10/2021

Description	Total
Third Party Express Settlement	400.00
Subtotal	400.00
GST (7%)	28.00
Grand Total	428.00

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

LKM



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
CHINA TAIPING INSURANCE (S) PTE LTD 3 ANSON ROAD #16-00 SPRINGLEAF TOWERSINGAPORE 079909			Ref: CC6/CTI21010415/Ara3q2 Date: 10/01/2022 Code: CTI	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	GBJ 483M	Veh. Inspected	SGK 319R	
Policy No.	DMCVSNW00115662002	Coverage (\$)	0.00	
Claim No.	SNM21D205732/LKKDS	Excess (\$)	0.00	
Assign From		Assign Date	08/10/2021	
2. Vehicle Particulars & Condition				
Make & Model	B.M.W. 116D	c.c	1496	
Engine No.	HIDDEN	Year of Reg.	2017	
Chassis No.	WBA1V72040V725533	Colour	WHITE	
Odometer	80786 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	255/35 R18	GOODYEAR	6 mm	
L/H Front Tyre	255/35 R18	GOODYEAR	6 mm	
R/H Rear Tyre	255/35 R18	GOODYEAR	6 mm	
L/H Rear Tyre	255/35 R18	GOODYEAR	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY AND UNDERCARRIAGE. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	07/10/2021	Inspection Date	08/10/2021	
Survey held at	YSK AUTO WORKSHOP 1 KAKI BUKIT AVE 6 @ AUTOBAY #01-71 SINGAPORE 417883			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			5 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SGK 319R

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	REAR BUMPER	TORN	1,020.10	1,020.10
1	REAR BUMPER SIDE HOLDER RH	NOT NECESSARY	102.40	-
1	REAR RH FENDER	DENTED	1,396.80	1,396.80
1	REAR RH FENDER INNER SHIELD	TORN	286.40	286.40
1	REAR RH WHEEL HUB C/W BEARING	DAMAGED	461.50	461.50
1	REAR RH KNUCKLE ARM	NOT NECESSARY	1,012.00	-
1	REAR RH LOWER ARM	BENT	548.20	548.20
1	REAR RH CONTROL ARM	BENT	260.40	260.40
1	REAR RH STAY ARM	BENT	245.40	245.40
1	REAR RH LATERAL LINK (FRONT)	BENT	268.20	268.20
1	REAR RH LATERAL LINK (REAR)	BENT	264.50	264.50
	LESS 10% DISCOUNT		-	-475.15
			5,865.90	4,276.35
<u>SPECIAL NETT ITEMS</u>				
1	REAR BUMPER CLIPS (SN)	NECESSARY	30.00	30.00
1	REAR RH FENDER INNER SHIELD CLIPS (SN)	NECESSARY	30.00	30.00
1	REAR RH LOWER RIM (SN)	CUT	1,080.00	700.00
1	REAR RH TYRE (SN)	NOT NECESSARY	380.00	-
1	REAR RH SHOCK ABSORBER (SN)	NOT NECESSARY	800.00	-
			2,320.00	760.00
<u>LABOUR</u>				
	PANEL BEATING.		1,200.00	600.00
	SPRAY PAINTING.		800.00	500.00
	WIRING.		50.00	30.00
	TO SPRAY TUFF COAT.		150.00	60.00
	TO REMOVE REVERSE SENSOR .		100.00	50.00
	TO REMOVE UPHOLSTERY.		150.00	60.00
	TO REMOVE REAR UNDERCARRIAGE.		380.00	220.00



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO PERFORM WHEEL ALIGNMENT.		150.00	80.00
			2,980.00	1,600.00
GRAND TOTAL			11,165.90	6,636.35
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				5,300.00

Report Ref No. CC6/CTI21010415/Ara3q2

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SGK 319R

INSPECTION






LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SGK 319R

RE-INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

