

SGK319R 2017 Feb.
TP Chim
Jasper
BMW 116D 1496cc
WBAIV72040V725533

Rear Bumper	torn	1020.10 ✓
Rear Bumper Clips	new	30(SN) ✓
Rear Bumper Side Holder RH.	new	102.40 x
Rear RH Fender	Dented	1396.80 ✓
Rear RH Fender Inner Shield	Torn	286.40 ✓
Rear RH Fender Inner Shield Clips	new	30(SN) ✓
Rear RH Wheel Rim	Cut	1080 700(SN)
Rear RH Tyre	XHe new	380(SN) x
Rear RH Wheel Hub c/w Bearing	Dmgd	461.50 ✓
Rear RH Knuckle Arm	new	1012. x
Rear RH Shock Absorber	He new	800(SN) x.
Rear RH Lower Arm	Best	548.20 ✓
Rear RH Control Arm	Best	260.40 ✓
Rear RH Stay Arm	Best	245.40 ✓
Rear RH Lateral Link (Front)	Best	268.20 ✓

SGK 319R.

Rees RH lateral link (Rees)

Bent 264.50

S.N: 760

4751.50

4276.35

Panel Beating

Spray Painting.

Wiring.

To spray tuff coat

To remove reverse sensor 1600

To remove upholstery.

To remove rear undercarriage

To perform wheel alignment.

~~1200~~ 600

~~800~~ 500

~~50~~ 30

~~150~~ 60

~~100~~ 50

~~150~~ 60

~~380~~ 220

~~150~~ 80

total: 6636.35

L/S: SGK.

05 Days.

(SGK)

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: