

ASS. REC. BY: Marcus

REF:

CS/EQ121010416/4uf3

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

SLQ 2781J

at Workshop m/s

Audi/Am 11-30

of

Insured:

SNA 2824E

Policy No.

Claims No.

DM21HO01507/MT


Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

\$ 74k.

IDAC Accident Report:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days Res: Yes or No

Lum Sum:

4 1.31 % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date:

Person Contacted:

Elmer

Date / Time

Action / Instruction

21/11/14. 21/11/14. 46967

Veh No:

SLQ2781J

Yr Regn:

30/6/17

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

CA/

Make:

Nissan X-trail c.c 1997

Colour

Red

A/C: Insured / Std / NI / NA

Sp.Reading

77013

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

JN11ANT3220003237

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

225/60218

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal.

6

mm

Rear

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

8/10/14

D.O.I.

14/10/14

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

25/10/14 confirmed P/P \$ 3246.80 with Elmer 4 repair days
(RED \$1839.12; 36%)

Date/Time, File Pass to?



: Preli. Report

1) 25/10 TYPIST



: Final Report

Date/Time, File Return to?

2)

Report Format : TP

Lump Sum / I.B.I: (\$ 3246.80)

Days Of Repair: 4

Resurvey No. of Trip: 1

Survey Fee:

Transportation:

) \$ + RS. \$1

) Photos

) Others

Add Fee:



: Site Insp (\$



: Interview (\$



: Tech. Invs (\$



: Weekend (\$

TOTAL

AUTOLUTION INDUSTRIAL PTE LTD
19 UBI ROAD 4
SINGAPORE 408623
TEL: 6490 9666 FAX: 68467483

AUTOLUTION INDUSTRIAL PTE. LTD.

ESTIMATE : ACCIDENT/BODY REPAIRS

REFERENCE : INS/IC/EA/0338/21
DATE : 11-OCT-2021

EQ INSURANCE COMPANY LIMITED
5 MAXWELL ROAD
#17-00 TOWER BLOCK
MND COMPLEX S(069110)
TEL : 62239433
FAX : 62234190
ATTN : MOTOR CLAIM MANAGER

OWNER'S NAME : MS LYE MAY FUN
ADDRESS : 32 SELETAR GREEN WALK
S(806257)
TELEPHONE NO : 98430365

not Authorized
to work
on car
12/10/21
to be before parting
4 days

TYPE OF CLAIM : DIRECT SETTLEMENT / THIRD PARTY CLAIM
POLICY NO : 1700023745-04
VEHICLE NO : SLQ2781J
MODEL CODE : JDRNRRT32EWA-----
MODEL/YEAR : X-TRAIL 2.0L ALL MODE 4X4I
ENGINE NO : MR209940088
CHASSIS NO : JN1JANT32Z0003237
MILEAGE : 76922 KM
DATE IN : 11/10/2021
LIABILITY : 0.00
EXCESS CLAUSE : 0.00
ESTIMATE BY : ELMER - 9645 0084 e/mur@fanchong.com
ACCIDENT DATE : 08/10/2021

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE REGN NO SL02781J

S/NO	JOB CODE	NATURE OF JOB	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATION
1	ZZ/001	LABOR CHARGES TO REPAIR RR END PANEL & HATCHBACK DOOR,RENEW REAR BUMPER 390	1560.00	1170
2	ZZ/002	CHARGES TO SPRAY PAINTING,RR END PANEL,DOOR,RR TRUNK HATCHBACK DOOR AND REAR BUMPER 40	1500.00	750
3	ZZ/003	RENEW REVERSE SENSOR	110.00	✓
4	ZZ/004	COMPUTER CHECK DIAGNOSIS (CHECK ENGINE WARNING LIGHT ON)	120.00	✓
5	ZZ/005	REMOVE AND INSTALL BOTH RR COMB LAMP AND CHECK REAR WIRING SYSTEM	48.00	✓
TOTAL LABOUR CHARGES			3338.00	

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SL02781J

DAMAGED PARTS & PRICES

S/NO PARTS DESCRIPTION	PARTS NUMBER	NETT	LIST	S/NETT REMARKS
1 EMBLEM RR X-TRAIL	✓ 84895-4CLOA neu	110.00	✓	
2 EMBLEM RR NISSAN	✓ 84890-4CLOA neu	64.90	✓	
3 CLIP RR BUMPER @ SGD \$1.30 EACH	✓ 01553-10501 neu	13.00	✓	
4 LOWER CENTER FINISHER RR BUMPER	✓ 85070-1KA0A mis	117.50	✓	
5 LH SIDE BRACKET RR BUMPER	85221-4CE0A 11	38.80	X	
6 RH SIDE BRACKET RR BUMPER	85220-4CE0A 11	38.90	X	
7 REINFORCEMENT RR BUMPER	85032-4CC0A mn	596.20	X	
8 REAR BUMPER	✓ 85022-4CE0H 7.5	693.10	✓	
9 REAR LICENCE PLATE	RLP	11	60.00	X
10 SUNDRIES	NPN	11	100.00	X
11 SENSOR-REVERSE	✓ SENSOR	shund	250.00	✓
SUB TOTAL		1672.40	0.00	410.00
LESS DISCOUNT (NETT-20.00%, LIST-30.00%, S/NETT-.00%)		334.48	0.00	0.00
GRAND TOTAL		1337.92	0.00	410.00
OVERALL TOTAL		1747.92		

LEGEND: REMARKS(OK) = APPROVED, REMARKS(X) = NOT APPROVED

P-998.50
 202
 798.80
 250
 3246.80

SUMMARY OF ESTIMATE FOR VEHICLE REGN NO SLQ2781J

TOTAL LABOUR CHARGES	3338.00
TOTAL SPARE PARTS CHARGES	1747.92

GRAND TOTAL	5085.92 *

* All charges do2 not include GST.

SURVEYOR'S PARTICULARS

NAME	:	
SURVEYED DATE	:	
AUTHORIZED DATE	:	
EXCESS CLAUSE	:	0.00
LIABILITY	:	0.00
REMARKS	:	

PLS NOTE : This estimate is based on visual inspection of the affected vehicle. Should we require further labour charges & spare parts in the process of repairs, we shall inform you accordingly.