

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/AIG21010419/AUF3N2**Date:** 10/11/2021REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	7210104256
Claimant Vehicle No :	GBH4775E	Insured Vehicle No :	SNB5300A
Date of Loss:	07/10/2021	Nature of Claim:	TP
		Claim No:	0384248432SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	GBH4775E		
Make & Model:	TOYOTA HIACE, 1.8 D SUPER GL DARK PRIME (A)	Engine No:	1KD2808040
Reg. Date:	18/06/2018 (Man. Year: 2018)	Chassis No:	JTFHT02P600243307
Colour:	White	Odometer:	134136 km
Engine Capacity:	2982 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195R15	Rear Tyre Size:	195R15
Front Left Side:	OHTSU 6 mm	Rear Left Side:	OHTSU 6 mm
Front Right Side:	OHTSU 6 mm	Rear Right Side:	OHTSU 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,643.30	3,179.85	2,463.45	43.65
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,180.00	1,590.00	1,590.00	50.00
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	8,823.30	4,769.85	4,053.45	45.94
Approved Total (Overridden) (S\$)		3,800.00		
Nett Amount (S\$)	8,823.30	3,800.00	5,023.30	56.93

INSPECTION

Date of Assignment:	11/10/2021	2020 Spray Painting Pte Ltd (HQ) 53 UBI AVE 1, #05-15 PAYA UBI INDUSTRIAL PARK Singapore 408934
Date Inspected:	11/10/2021 Inspected At:	
Estimated Period of Repair:	4.0 days	

Adjuster: ADRIAN LING**Manager:** Tan Hui Zhen

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed	496.40 F	*496.40 FL
2	1		*REAR BUMPER SIDE HOLDER	O/s Cracked	132.20 F	*66.10 FL
3	4		*REAR BUMPER LOWER BRACKET	Not Necessary	112.00 F	*- FL
4	1		*TAILGATE	Dented	1,855.00 F	*1,855.00 FL
5	1		*TAILGATE LOCK	Damaged	287.10 F	*287.10 FL
6	1		*TAILGATE WEATHERSTRIPE	Not Necessary	391.20 F	*- FL
7	1		*TAILGATE INNER TRIM BOARD	Not Necessary	165.30 F	*- FL
8	1		*TAILGATE GLASS MOULDING	Necessary	172.50 F	*172.50 FL
9	1		*TAILGATE LOGO	Necessary	64.20 F	*64.20 FL
10	1		*TOYOTA HIACE STICKER	Necessary	38.90 F	*38.90 FL
11	1		*TAILLAMP RH	Cracked	364.80 F	*364.80 FL
12	1		*TAILLAMP LOWER APRON RH	Cracked	94.80 F	*94.80 FL
13	1		*REAR END PANEL	Repair	548.90 F	*- FL
14	1		*REAR BUMPER CLIPS	Necessary	30.00 FS	*30.00 FS
15	1		*REVERSE SENSOR	Damaged	280.00 FS	*200.00 FS
16	1		*TAILGATE INNER TRIM BOARD CLIPS	Not Necessary	20.00 FS	*- FS
17	1		*TAILGATE GLASS SEALANT	Necessary	60.00 FS	*60.00 FS
18	1		*TAILGATE ADVERTISEMENT STICKERS	Necessary	500.00 FS	*280.00 FS
19	1		*70KM/H STICKER	Necessary	15.00 FS	*15.00 FS
20	1		*8 PAX STICKER	Necessary	15.00 FS	*15.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	5,643.30	4,039.80
- List Item Discount on L Items 0.00/25.00% (\$\$)	0.00	859.95
Total Parts (\$\$)	5,643.30	3,179.85

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING	New	1,200.00	600.00
2	SPRAY PAINTING	New	1,200.00	600.00
3	WIRING	New	50.00	30.00
4	TO SPRAY TUFF COAT	New	150.00	60.00
5	TO REMOVE UPHOLSTERY	New	150.00	50.00
6	TO TRANSFER TAILGATE FITTINGS	New	150.00	80.00
7	TO REMOVE TAILGATE GLASS	New	180.00	120.00
8	TO REMOVE REVERSE SENSOR	New	100.00	50.00
Gross Labour Cost (\$\$)			3,180.00	1,590.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >