

Our Job Ref No 305489358

Date : 07/10/21

ComfortDelGro Engineering Pte Ltd  
59 Loyang Drive Singapore 508989  
Fax: 6546 8156

## FINALIZATION FORM

To : LKK

Fax :

Attn : THEVAN

: SHA 958L

DOA: 04/10/21

The survey and estimates of the repairs of the above-mentioned vehicle are as follows:-

- The repair job shall bill to: NTUC --- SJT8900B
- The finalized amount shall be:
  - Spare Parts after List discount
  - Labour Charges
  - Total for Part-By-Part Repair Cost
  - Lumpsum Repair (if applicable)  
Total for Lumpsum repair cost after Less: 20% \$2,150.00  
Final Lumpsum Repair cost
- Estimated normal period for repairs: 3 working days
- We shall treat the above amount as Correct and Confirmed if there is no reply from you within 7 working days
- Thank you for your assistance.

We confirm the estimates and finalized amount

Signature : 

Name : JUMANI

Tel : 6214 8315

Fax : 65468156

Signature : 

Name : THEVAN

Date : 15/10/21

### For Official Use Only

Item	Amount	Document Attached Yes or No	Confirm By (Signature)	Remarks
1. Rental Rate P/Day		YES		
2. Loss of Income Paid	-	N		
3. Survey Fees	-	-		
4. LTA Search Fee	7.49 / 2.00	YES		
5. Medical Fees (on behalf of driver, if applicable)				
6. Overrun				

Remarks:

NTUC - C&S

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE

Date: 04.10.2021

Time: 13:53:33

Page: 1

COMPANY : THIRD PARTY'S CLAIMS (CAS)  
CUSTOMER: 7010070  
ADDRESS : CITYCAB PTE LTD  
383 SIN MING DRIVE  
SINGAPORE SINGAPORE 575717  
65551188

JOB NO : 305489358  
REGN NO : SHA 958L ✓  
MILEAGE : 000000000  
MAKE : TOYOTA  
MODEL : PRIUS HYBRID(G4)  
DATE OF REGN : 09.12.2016  
DATE/TIME IN : 04.10.2021 10:45  
ACCIDENT DATE : 04.10.2021

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

PART REQUISITION

0001 04-01-0302-2282-G	COVER REAR BUMPER%	1	458.60	25.00	343.95	Xr
0002 04-01-0302-3809-G	PANEL SUB-ASSY QUARTER LH	1	836.70	25.00	627.52	/Def
0003 04-01-0302-2267-G	BUMPER PIECE	10	22.00	25.00	16.50	/nec
0004 03-01-0302-2057-G	CAP WHEEL^	1	177.70	25.00	133.27	/scr
0005 28-01-9999-2024-A	APP LOGO REAR DOOR L/R CC	1 N	80.00	10.00	72.00	/nec
0006 04-01-0302-2865-G	FILLER-REAR BUMPER EXTENS	1	148.40	25.00	111.30	Xr
0007 04-01-0302-3837-G	RETAINER RR BUMPER SIDE L	1	112.70	25.00	84.52	Xsuc
0008 28-01-0302-2018-A	FUEL TANK LID (PETROL ONL	1 N	15.00	10.00	13.50	Xr

SUB-TOTAL : 1,402.56

JOB NATURE

0000 PB	PANEL BEATING	1100.00	700
0001 SP	SPRAYPAINT CHARGE	800.00	750
0002 20-00	TUFF COAT ON AFFECTED PARTS.	50.00	20

## REPAIR ESTIMATE

COMPANY : THIRD PARTY'S CLAIMS (CAS)  
 CUSTOMER: 7010070  
 ADDRESS : CITYCAB PTE LTD  
 383 SIN MING DRIVE  
 SINGAPORE SINGAPORE 575717  
 65551188

JOB NO : 305489358  
 REGN NO : SHA 958L  
 MILEAGE : 0000000000  
 MAKE : TOYOTA  
 MODEL : PRIUS HYBRID  
 DATE OF REGN : 09.12.2016  
 DATE/TIME IN : 04.10.2021 10:4  
 ACCIDENT DATE : 04.10.2021

JOB / PARTS DESCRIPTION	QTY	IND	UNIT-PRICE	DISC%	AMOUNT
0003 17-01 CHECK ALL LIGHTING	50.00		20		
0004 20-204 REMOVE/REFIX UPHOLSTERY REAR	120.00		40		
0005 20-05 RENEW ADVERTISEMENT STICKER-DOOR			100.00	✓	
0006 20-05 RENEW ADVERTISEMENT STICKER-FENDER			200.00	✓	
SUB-TOTAL :					2,420.00

TOTAL : 3,822.56

Jumani  
 MVA NAME & SIGNATURE  
 DATE :

AUTHORISED : YES / NO  
 SURVEYOR NAME & SIGNATURE  
 DATE :

Thuan @ Lkhayto .com  
 82235769

4/10/21 1530

L/S after repair photos  
 wp 3days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: