



Borneo Motors

Inchcape

Co. Reg No. : 196700086Z
GST Reg No. : MR-8500000-9
No. 2 PANDAN CRESCENT
SINGAPORE 128462, Tel no.: 6631 1188



TOYOTA

ESTIMATE

Account Details			Account No.		Customer Details		
MS First Capital Insurance Ltd 36 Robinson Road #16-01 City House Singapore 068877 Attn: Motor Claims Dept			S1000005 / ICFIC1		M/S Grab Rentals Pte Ltd 6 Battery Road #38-04 Singapore 049909 Work: 65703925		
			Document No. 0				
			Document Date 20/11/2021				
Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks
2017	NSP151R	CEXRKT Q1	19/06/2017	SLP7972Y	0	10364	66TP/SLP7972Y/081021
Chassis No.		Engine No.	Terms	SA / Counter	Vehicle In		Collected On
MHFB29F3202011874		2NRX158665	60	Shashitharan	12/10/2021 8.00		12/10/2021 18.00
L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount	
1	Z	BP-GRAB-DS SUNDRIES - FLASH ARRIVE: DD/MM/YY 0000HR TP VEH NO.:SHB5373X ACC DATE:07/10/21 DRIVE IN:08/10/21 DATE-IN:12/10/21 DATE SURVEY:12/10/21 NO OF REPAIR DAYS:6 BY:steve lkk AUTHORISED ON:12/10/21	*			50.00	
2	B	BP-LAB2 CHECK WIRING AND CONDUCT LEAK TEST	*			180.00	
3	B	BP-LAB2 TRANSFER LH FRT AND REAR DOOR MECHANISM	*			720.00	
4	Z	BP-SLANT SUPPLY SEALANT (NETT)2 PANEL				160.00	
5	B	BP-LAB2 REPL ACC AFF PARTS AND PANEL STRAIGHTEN AND REALIGN ACC AFF AREA	*			1800.00	
6	B	BP-RES2 RESRPAY ACC AFF AREA	*			2950.00	
7	S	BP-SUBLET RESET ECU UPON COMPLETION OF REPAIR	0742			180.00	
8	1	S75922-0D170 TAPE, BLACK OUT, NO.	1.00	48.50	10.00	43.65	
9	2	K67002-0D160 PANEL SUB-ASSY, FR D	1.00	1149.70	10.00	1034.73	
10	3	K75924-0D200 TAPE, BLACK OUT22	1.00	48.50	10.00	43.65	
11	4	S67004-0D230 PANEL ASSY,RR DR LH22	1.00	946.50	10.00	851.85	
For & on behalf of Borneo Motors (Singapore) Pte Ltd			Customer's Signature		Charge Summary		Total 8,013.88
			Please acknowledge receipt of vehicle		Parts 1,973.88		GST 7.00% 560.97
					Labour 5,860.00		Less 0.00
					Sublet 180.00		
					Lubrication/Fluid 0.00		
					Others 0.00		
					Amount Due 8,574.85		

Customer Copy