



Borneo Motors

Inchcape

Co. Reg No. : 196700086Z
GST Reg No. : MR-8500000-9
No. 2 PANDAN CRESCENT
SINGAPORE 128462, Tel no.: 6631 1188



TOYOTA

ESTIMATE

Account Details			Account No.		Customer Details		
Bodyshop Retail Cash Sales Pandan TCBC Toyota Bodyshop Retail Cash Sales Pandan TCBC Toyota			c0110038 / PBPREG		M/S Grab Rentals Pte Ltd 6 Battery Road #38-04 Singapore 049909 Work: 65703925		
			Document No. 0				
			Document Date 09/10/2021				
Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks
2017	NSP151R	CEXRKT Q1	19/06/2017	SLP7972Y	0	10364	66TP/SLP7972Y/081021
Chassis No.		Engine No.	Terms	SA / Counter	Vehicle In		Collected On
MHFB29F3202011874		2NRX158665	00	Shashitharan	--/--/----		0.00 --/--/----
L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount	
1	Z	BP-GRAB-DS SUNDRIES - FLASH ARRIVE: DD/MM/YY 0000HR TP VEH NO.:SHB5373X ACC DATE:07/10/21 DRIVE IN:08/10/21 DATE-IN: DATE SURVEY: NO OF REPAIR DAYS: BY: AUTHORISED ON:				100.00	
2	B	BP-LAB2 CHECK WIRING AND CONDUCT LEAK TEST				180.00	
3	B	BP-LAB2 TRANSFER LH FRT AND REAR DOOR MECHANISM				720.00	
4	Z	BP-SLANT SUPPLY SEALANT (NETT)2 PANEL				160.00	
5	B	BP-LAB2 REPL ACC AFF PARTS AND PANEL STRAIGHTEN AND REALIGN ACC AFF AREA				2880.00	
6	B	BP-RES2 RESRPAY ACC AFF AREA				2950.00	
7	B	BP-MECH2 RESET ECU UPON COMPLETION OF REPAIR				180.00	
8	1	S75922-0D170 TAPE, BLACK OUT, NO.	1.00	48.50	10.00	43.65	
9	2	S67002-0D300 PANEL SUB-ASSY, FR D	1.00	1149.70	10.00	1034.73	
10	3	S75924-0D200 TAPE, BLACK OUT, NO.	1.00	48.50	10.00	43.65	
11	4	S67004-0D230 L/R DOOR ASSY	1.00	946.50	10.00	851.85	
For & on behalf of Borneo Motors (Singapore) Pte Ltd			Customer's Signature		Charge Summary		Total 9,143.88
			Please acknowledge receipt of vehicle		Parts	1,973.88	GST 7.00% Less Amount Due
					Labour	7,170.00	
					Sublet	0.00	
					Lubrication/Fluid	0.00	
					Others	0.00	
							9,783.95

Customer Copy