

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE*

VEHICLE NO SPD3323H

DATE 08/10/21 07:25 PM

MAKE

06/10/17

CHIANG/AIG

MODEL TOYOTA PRIUS G4A

Qty	Parts Description/ Labour	Type	Unit Price	Amount
1	REAR BUMPER			\$458.60
1	REAR BUMPER LOWER COVER			\$552.60
1	REAR BUMPER REINFORCEMENT			\$318.80
1	REAR BUMPER UNDER SIDE COVER RH			\$232.60
1	REAR BUMPER TOW COVER			\$82.70
1	REAR BUMPER SIDE RETAINER LH/RH			\$112.70
10	REAR BUMPER CLIP			\$22.00
	SUB TOTAL			\$1,780.00
	25.00%			\$445.00
	DISCOUNTED TOTAL			\$1,335.00
1	BUMPER MAT			\$50.00
1	BUMPER REVERSE SENSOR			\$135.70
				\$185.70
	Labour Charge			
	Panel Beating			\$500.00
	Spray Painting Charge			\$300.00
	Tuff Kote			\$60.00
	Remove/Refix Reverse Sensor			\$60.00
	TOTAL LABOUR			\$920.00
	ESTIMATE TOTAL			\$2,440.70
This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.				

Tuphin 9749 5747
 WP 11/10/21 C 405
 1/3 Rising after repair
 Tuphin & 11/10/21
 02 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Date/Time: 11.10.2021 08:40

Page : 1

Team: ARC Repair TP(CLSO)1

JOB CARD Sales Order:

JC NO 305490142

Customer

Customer Name: COMFORT TRANSPORTATION PTE LTD
Customer No: 7010045
Customer Address: 383 SIN MING DRIVE
Singapore SINGAPORE 575717
L. (R) 65508755 (O)
(P)

SCOUNT CARD NO.

REGN NO.

SHD3323H

MILEAGE

MAKE

TOYOTA

FUEL

E.....1/2.....F

MODEL

PRIUS HYBRID(G4)09.10.2021 11:05

DATE/TIME IN

YR OF MANU.

06.10.2017

TARGET DATE

CHASSIS CODE

JTDKB3FU703569182

COMPLETION DATE/TIME:


JOB DESCRIPTION

Accident Date: 08.10.2021
NATURE: 3P 08.10.2021

3/NO

LABOR CODE

DESCRIPTION



CHECKED & PASSED OUT BY:

SERVICE ADVISOR

CUSTOMER'S SIGNATURE

Acknowledgement Slip

Exit Pass

Vehicle

Vehicle

Vehicle No.:

SHD3323H

CHIANG

Vehicle No.:

SHD3323H

Signature of Service Advisor

Signature/Date

Name of Service Advisor

Date

Returned to Service Reception upon collection

To be kept by Security Guard