

**KAH MOTOR CO. SDN. BHD.**

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

QUOTATION

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer	: LONPAC INSURANCE BHD 300 BEACH ROAD #17-04/07 THE CONCOURSE SINGAPORE 199555	Document No.	: SQT21003103	Page	1
Registration No	: SLL9044J	Date	: 9. Oct 2021		
Chassis No	: MRHFC5650GT001032	Customer No.	: WZL009		
Model	: CIVIC 1.6 VTI YM2016	Svc Advisor	: IVAN TEO BOON KIAT		
Owner's Name	: TEH GEK WAH	Engine No	: R16B21601331		
Ins Policy No.	:	Date Time	: 9. Oct 2021 12:12:42 PM		
Date of Accident	: 8/10/2021	Surveyor Name	:		
		Survey Date	:		
		Authorisation Date	:		

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
	TP DIRECT SETTLEMENT (J/NO:) OWNER: TEH GEK WAH OWNER INSURER: LIBERTY ACC DATE: 08/10/2021 SURVEYED BY: DATE: REF NO: TP INSURER: LONPAC TP VEH: XD7971X						
68500-TEA-N00ZZ	LID COMP TRUNK	1	554.90	25	416.17	29.13	445.30
68610-TEA-T10ZZ	HINGE COMPR.TRUNK	1	51.10	25	38.32	2.68	41.00
68660-TEA-T10ZZ	HINGE COMPL.TRUNK	1	51.10	25	38.32	2.68	41.00
74829-S84-A00	STOPPER TRUNK LID	2	5.20	25	7.80	0.55	8.35
74862-TEA-003	STRIKERTRUNK LID	1	8.10	25	6.07	0.42	6.49
74851-TEA-003	LOCK ASSYTRUNK	1	84.90	25	63.67	4.46	68.13
74865-TEA-T01	WEATHERSTRIPTRUNK LID	1	70.00	25	52.50	3.68	56.18
74890-TEA-T11ZB	GARNISH ASSYRR.LICENSE	1	114.80	25	86.10	6.03	92.13
75722-TBA-A00	EMBLEM SETRR.	1	13.40	25	10.05	0.70	10.75
75725-TEA-T01	EMBLEMRR.	1	12.50	25	9.37	0.66	10.03
34150-TEX-Y01	LIGHT ASSYR.LID	1	139.60	25	104.70	7.33	112.03
34155-TEX-Y01	LIGHT ASSYL.LID	1	139.60	25	104.70	7.33	112.03
33500-TEA-T01	TAILLIGHT ASSYR.	1	298.40	25	223.80	15.67	239.47
33550-TEA-T01	TAILLIGHT ASSYL.	1	321.10	25	240.82	16.86	257.68
39530-TBA-A01	CAMERA ASSYRR.VIEW	1	360.20	25	270.15	18.91	289.06
71500-TEC-Q00ZZ	FACE ASSY,RR.BUMPER	1	617.20	25	462.90	32.40	495.30
71502-TEX-Y00	GARNISH,RR.BUMPER LOWER	1	41.60	25	31.20	2.18	33.38
71503-TEA-T00	GARNISH,R.RR.BUMPER SIDE	1	8.90	25	6.67	0.47	7.14
71508-TEA-T00	GARNISH,L.RR.BUMPER SIDE	1	8.90	25	6.67	0.47	7.14

Printed on 9/10/2021 12:30:58 PM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

An amount of \$53.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00.

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd, it will be refunded.

**KAH MOTOR CO. SDN. BHD.**

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

QUOTATION

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer	: LONPAC INSURANCE BHD 300 BEACH ROAD #17-04/07 THE CONCOURSE SINGAPORE 199555	Document No.	: SQT21003103	Page	2
Registration No	: SLL9044J	Date	: 9. Oct 2021		
Chassis No	: MRHFC5650GT001032	Customer No.	: WZL009		
Model	: CIVIC 1.6 VTI YM2016	Svc Advisor	: IVAN TEO BOON KIAT		
Owner's Name	: TEH GEK WAH	Engine No	: R16B21601331		
Ins Policy No.	:	Date Time	: 9. Oct 2021 12:12:42 PM		
Date of Accident	: 8/10/2021	Surveyor Name	:		
		Survey Date	:		
		Authorisation Date	:		

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
71530-TEA-T00ZZ	BEAM COMPRR.BUMPER	1	188.00	25	141.00	9.87	150.87
71593-TEA-T01	SPACERR.RR.BUMPER SIDE	1	11.50	25	8.62	0.60	9.22
71598-TEA-T01	SPACERL.RR.BUMPER SIDE	1	11.50	25	8.62	0.60	9.22
91505-TM8-003	CLIP,BUMPER	7	2.30	25	12.07	0.84	12.91
04636-TEA-T00ZZ	PANEL SETR.RR.OUTSIDE	1	812.30	25	609.22	42.65	651.87
04646-TEA-T00ZZ	PANEL SETL.RR.OUTSIDE	1	812.30	25	609.22	42.65	651.87
BO-NUM-COMP-L	NUMBER PLATE WITH CASING-L(N)	1	45.00		45.00	3.15	48.15
Sum Item					3613.73	252.97	3,866.70

BOSUN	SUNDRIES	1	100.00		100.00	7.00	107.00
BML02I	INSPECT RR LIGHTING MECHANISMS. PERFORM WATER	1	280.00		280.00	19.60	299.60
BA02R	REMOVE & RENEW REVERSE SENSORS-4 PCS (N)	1	280.00		280.00	19.60	299.60
BC011R	REMOVE INSTALL & CALIBRATE REAR VIEW CAMERA	1	560.00		560.00	39.20	599.20
BC012R	RESET VEHICLE SMART ENTRY SYSTEM	1	560.00		560.00	39.20	599.20
BKTRR	REMOVE & TRANSFER ITEMS TO NEW TRUNK LID	1	560.00		560.00	39.20	599.20
BOBC	BODY UNDERSIDE COATING (N)	1	380.00		380.00	26.60	406.60
BOJSE	BODY JOINT SEALANT TRUNK LID	1	120.00		120.00	8.40	128.40
BMI03D	REMOVE & INSTALL REAR COMPARTMENT LININGS	1	650.00		650.00	45.50	695.50
BKRP21S	STRAIGHTEN ALIGN RR PANEL RR FENDER	1	5200.00		5200.00	364.00	5564.00
BP05R	SPRAY PAINTING ON REPAIRED OR REPLACED AREAS.(5P)	1	4160.00		4160.00	291.20	4451.20
Sum Labor					12850.00	899.50	13,749.50

Survey By	_____						
Date & Time	_____	Total Amount	16,463.73	1,152.47		17,616.20	
Excess	_____	Total (Inclusive of GST)				17,616.20	
Status	_____						
Signature	_____						

Printed on 9/10/2021 12:30:58 PM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

An amount of \$53.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00.

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd, it will be refunded.

**KAH MOTOR CO. SDN. BHD.**

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

QUOTATION

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer	: LONPAC INSURANCE BHD 300 BEACH ROAD #17-04/07 THE CONCOURSE SINGAPORE 199555	Document No.	: SQT21003103	Page	3
Registration No	: SLL9044J	Date	: 9. Oct 2021		
Chassis No	: MRHFC5650GT001032	Customer No.	: WZL009		
Model	: CIVIC 1.6 VTI YM2016	Svc Advisor	: IVAN TEO BOON KIAT		
Owner's Name	: TEH GEK WAH	Engine No	: R16B21601331		
Ins Policy No.	:	Date Time	: 9. Oct 2021 12:12:42 PM		
Date of Accident	: 8/10/2021	Surveyor Name	:		
		Survey Date	:		
		Authorisation Date	:		

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incl GST
------	-------------	-----	------------	--------	--------	------------------	--------------------

Printed on 9/10/2021 12:30:58 PM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

An amount of \$53.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00.

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd, it will be refunded.