Performance Motors Limited

A member of the Sime Darby Group



INDIA INTERNATIONAL INSURANCE c/o LKK Auto Consultants Pte Ltd

Your Ref : SLW8172X

Our Ref: DS/2455579/SMX2022T

"Without Prejudice"

Date: 1 December 2021

Subject: ACCIDENT INVOLVING VEHICLES SMX2022T & SLW8172X ON 26/09/21

Dear Sirs

We refer to the above matter.

The accident was caused solely by the negligence on the part of your insured. As a result of the said accident, our client has suffered losses which are set out hereunder as follows: -

Cost of Repair : \$ 9,238.86 Loss of Use : \$ 500.00 (\$100*5 days)

GIA/LTA Search: \$ 7.45

Excess

Loss of Rental: \$ -

Others

Total : \$ 9,746.31

A copy of each of the following supporting documents is enclosed:

- 1. Copy of Final Repair Bill
- 2. GIA/LTA search slip
- 3. Original Letter of Authorisation

Please note that you or your insured should send us an acknowledgement of receipt of this letter within fourteen (14) days from the date of this letter, failing which our client will have no alternative but to commence legal proceedings against you without any further notice to you or your insured.

Should you have a counterclaim against our client arising out of the accident, you are also required to send a letter giving full particulars of the counterclaim together with all relevant supporting documents within eight (8) weeks of your receipt of this letter.

For any correspondence, please contact Ms Evelyn Chan / Mr Suhaimi at 6319-0175 / Fax. 6479-4601 or email to pml-pbsp@simedarby.com.sg.

Yours/sincerely

Cresendo Lagman

Customer Service Manager, Body & Paint

Service Manager – Body & Paint

Registered office 305 Alexandra Road #02-01 Vantage Automotive Centre Singapore 159942

Fax 6344 1332

Performance Motors Limited

1800-Call-BMW

(1800-2255-269) www.pml.com.sa

303 Alexandra Road

Singapore 159941

Tel Sales 6319 0100 Tel Aftersales: 6319 0111 Fax 6474 7770

315 Alexandra Road #01-01

Tel Sales 6319 0511

Kampong Arang Rd East Coast Centre Singapore 438180 Tel Aftersales 6319 0888

Sime Darby Business Centre Singapore 159944

> Tel Aftersales 6319 0527 Fax 6479 6624

> > 280

Sime Darby Performance Centre

> Co. Reg. No: 197401559W

Performance Motors Limited A member of the Sime Darby Group

NRIC No.:



LETTER OF AUTHORISATION

ACCIDENT INVOLVING	T estex mg	_ & _	SLWSI72X	ON_	≈ .09.∂°>/
I, Tan Bon Eng hereby authorise Perform settle my claim for cost of re		mited	to submit, corr	espond	d, negotiate and
I further authorise Perforn documents whatsoever in a due to me in respect of my of	relation to this m				
I hereby declare that all act on my behalf shall be good the same had been done or	valid and effectu	al to al	l intents and pur		
I further confirm that the ac amount in respect of such o such loss and damage.					
Signed by:					
Name: Tan Boon Eng NRIC No.: (60/38)	(Date	 ^{e)} 26	/09/2021		
In the presence of:					
1 \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \	Foong Shiuh Jy rmance Motors L 03 Alexandra Ro Darby Performance	.imited ad e Cent	re		
Name:	Singapore 15994	e)			



India Ref: MFL2021D0004171

Claimant Ref: DS/2455579/SMX2022T

INDIA INTERNATIONAL INSURANCE PTE LTD

Co. Reg. No. 198703792k | GST. Reg. No. M2-0078806-X 64 | Cecil Street | #04 | #05 | #06-02 | IOB Building | Singapore 049711

Office (65) 63476100 (65) 62244174

Email insure@iii.com.sg Website www.iii.com.sg

EXPRESS SETTLEMENT

DISCHARGE VOUCHER III-Direct Settlement (PODS)

PERFORMANCE MOTORS LTD We/I. ("the workshop") hereby confirm that we/I have reached an agreement with the appointed Surveyor of India International Insurance Pte Ltd LKK AUTO CONSULTANTS PTE LTD of Surveyor) with respect to the amount claimed for S\$ 9,238.86 (repair cost), S\$ 300.00 (loss of use/rental), S\$ 7.45 (search fee), vehicle no. SMX 2022T that was damaged pursuant to the accident which occurred on 26/09/2021 (date) at TAMPINES AVE 10, FILTER LANE (location) involving vehicle no. SLW 8172X (insured vehicle). This is pursuant to the inspection conducted on 12/10/2021 (date) at "the workshop". We/I confirm that we/I are/am authorized by the owner TAN BOON ENG ("the third party claimant") of vehicle no. SMX 2022T to make the claim as set out in the above paragraph and we/I have full authority to settle the matter on his/her behalf in a manner that we/I deem fit. We/I enclose herein the letter of authority given by "the third party claimant". We/I further confirm that we/I will indemnify India International Insurance Pte Ltd for all damages, loss and/or expense that they will or have already incurred in the event that "the third party claimant" after the above said agreement lodges a further claim against the former for any loss and expenses suffered pertaining to cost of repairs and/or rental and/or loss of use pursuant to the damage to SMX 2022T (vehicle no.) as a result of the accident. We/I confirm that the agreement reached above is in full and final settlement of all claims of "the third party claimant" pursuant to the accident and that further this settlement is reached on a without prejudice and without admission of liability basis. This agreement is subject to the application of Singapore law and the Singapore Courts have exclusive jurisdiction over any dispute arising out of the same. We/lauthorize you to pay the total amount of S\$ 9,546.31 to PERFORMANCE MOTORS LTD CLAIMANT: WITNESS: 303 Alexandra Road Sime Darby Performance Centre Singapore 159941 Tel: 6319 0100 (Sales) Signature: Signature: Signed by "the workshop" (Wifference) Signed by appointed Surveyor Name: LKK AUTO CONSULTANTS PTE LTD Name: NRIC: 199607198R NRIC: Address: 51 UBI AVE 1 #01-25 PAYA LEBAR IND'L PARI Address: SINGAPORE 408933 Nationality: Nationality: Occupation:

Occupation:

Performance Motors Limited

A Sime Darby Motors Company Co. Reg. No. 197401559W GST Reg. No M2-0020081-x Toll-Free Number (1800-2255269)

303, Alexandra Road Sime Darby Performance Centre Singapore 159941 Fax. 64747770

280, Kampong Arang Road East Coast Centre Singapore 438180 Fax. 63449773

315, Alexandra Road Sime Darby Business Centre Singapore 159944 Fax 64796601 (AfterSales) 64796624 (Motorrad)



SERVICE TAX INVOICE

Repair Order No. 1600336 : B1 Page No.

Invoice Number: 2455579 / WSB : 12/10/2021

Date IN Invoice Date : 26/11/2021

Payment Terms : 30 Days From Invoice Motor Claim Advisor: Foong Shiuh Jye

Invoice By : Karen Chin Lye Peng

: 1 of 2

- CUSTOMER INFORMATION -

Mdm Tan Boon Eng

Blk 896A Tampines St 81

#02-870 Singapore

Singapore 521896

- INVOICE TO -219

India Int'L Insurance Pte Ltd

64 Cecil Street #04-05 IOB Building Singapore 049711

REGN. NO. CHASSIS NO. REGN. DATE MODEL MILEAGE 216I GT SMX2022T WBA2D920805K81141 15/08/2018 42673

To replace rear bumper and attachments, bootlid including remove attachments to facilitate repair. To respray rear bumper and bootlid. To carry out body cavity preservation. (Per panel). To remove and install rear windscreen glass to facilitate repair. To conduct water leak tests. To transfer lock mechanism from old to new bootlid including conduct check on new bootlid central locking system for proper function. To remove old PDC assembly and reconnect to new bumper including conduct check for proper function. To check electrical wiring system and lighting at the rear section for proper function. Sundries. INS CLAIMS: ACCIDENT REPAIR. DIRECT SETTLEMENT. DATE OF ACCIDENT : 26.09.2021. 3RD PARTY CAR: SLW8172X. YOUR REF NO: NIL. VEHICLE WAS SURVEYED BY MR STEVE CHEN FROM LKK
To replace rear bumper and attachments, bootlid including remove attachments to facilitate repair. To respray rear bumper and bootlid. 1,8i To carry out body cavity preservation. 1 (Per panel). 5 To remove and install rear windscreen glass to facilitate repair. 7 To conduct water leak tests. 7 To conduct water leak tests. 7 To transfer lock mechanism from old to new bootlid including conduct check on new bootlid central locking system for proper function. 7 To remove old PDC assembly and reconnect to new bumper including conduct check for proper function. 7 To check electrical wiring system and lighting at the rear section for proper function. 5 Sundries. 1 INS CLAIMS : ACCIDENT REPAIR. DIRECT SETTLEMENT. DATE OF ACCIDENT : 26.09.2021. 3RD PARTY CAR : SLW8172X. YOUR REF NO : NIL. VEHICLE WAS SURVEYED BY MR STEVE CHEN FROM LKK
remove attachments to facilitate repair. To respray rear bumper and bootlid. 1,8 To carry out body cavity preservation. 1 (Per panel). 5 To remove and install rear windscreen glass to facilitate repair. 7 To conduct water leak tests. 7 To transfer lock mechanism from old to new bootlid including conduct check on new bootlid central locking system for proper function. 7 To remove old PDC assembly and reconnect to new bumper 1 including conduct check for proper function. 7 To check electrical wiring system and lighting at the rear section for proper function. 5 Sundries. 1 INS CLAIMS: ACCIDENT REPAIR. DIRECT SETTLEMENT. DATE OF ACCIDENT : 26.09.2021. 3RD PARTY CAR: SLW8172X. YOUR REF NO: NIL. VEHICLE WAS SURVEYED BY MR STEVE CHEN FROM LKK
To respray rear bumper and bootlid. To carry out body cavity preservation. (Per panel). To remove and install rear windscreen glass to facilitate repair. To conduct water leak tests. To transfer lock mechanism from old to new bootlid including conduct check on new bootlid central locking system for proper function. To remove old PDC assembly and reconnect to new bumper including conduct check for proper function. To check electrical wiring system and lighting at the rear section for proper function. Sundries. INS CLAIMS : ACCIDENT REPAIR. DIRECT SETTLEMENT. DATE OF ACCIDENT : 26.09.2021. 3RD PARTY CAR : SLW8172X. YOUR REF NO : NIL. VEHICLE WAS SURVEYED BY MR STEVE CHEN FROM LKK
To carry out body cavity preservation. (Per panel). To remove and install rear windscreen glass to facilitate repair. To conduct water leak tests. To transfer lock mechanism from old to new bootlid including conduct check on new bootlid central locking system for proper function. To remove old PDC assembly and reconnect to new bumper including conduct check for proper function. To check electrical wiring system and lighting at the rear section for proper function. Sundries. INS CLAIMS : ACCIDENT REPAIR. DIRECT SETTLEMENT. DATE OF ACCIDENT : 26.09.2021. 3RD PARTY CAR : SLW8172X. YOUR REF NO : NIL. VEHICLE WAS SURVEYED BY MR STEVE CHEN FROM LKK
(Per panel). To remove and install rear windscreen glass to facilitate repair. To conduct water leak tests. To transfer lock mechanism from old to new bootlid including conduct check on new bootlid central locking system for proper function. To remove old PDC assembly and reconnect to new bumper including conduct check for proper function. To check electrical wiring system and lighting at the rear section for proper function. Sundries. INS CLAIMS : ACCIDENT REPAIR. DIRECT SETTLEMENT. DATE OF ACCIDENT : 26.09.2021. 3RD PARTY CAR : SLW8172X. YOUR REF NO : NIL. VEHICLE WAS SURVEYED BY MR STEVE CHEN FROM LKK
To remove and install rear windscreen glass to facilitate repair. To conduct water leak tests. To transfer lock mechanism from old to new bootlid including conduct check on new bootlid central locking system for proper function. To remove old PDC assembly and reconnect to new bumper including conduct check for proper function. To check electrical wiring system and lighting at the rear section for proper function. Sundries. INS CLAIMS : ACCIDENT REPAIR. DIRECT SETTLEMENT. DATE OF ACCIDENT : 26.09.2021. 3RD PARTY CAR : SLW8172X. YOUR REF NO : NIL. VEHICLE WAS SURVEYED BY MR STEVE CHEN FROM LKK
repair. To conduct water leak tests. To transfer lock mechanism from old to new bootlid including conduct check on new bootlid central locking system for proper function. To remove old PDC assembly and reconnect to new bumper including conduct check for proper function. To check electrical wiring system and lighting at the rear section for proper function. Sundries. INS CLAIMS : ACCIDENT REPAIR. DIRECT SETTLEMENT. DATE OF ACCIDENT : 26.09.2021. 3RD PARTY CAR : SLW8172X. YOUR REF NO : NIL. VEHICLE WAS SURVEYED BY MR STEVE CHEN FROM LKK
To conduct water leak tests. To transfer lock mechanism from old to new bootlid including conduct check on new bootlid central locking system for proper function. To remove old PDC assembly and reconnect to new bumper including conduct check for proper function. To check electrical wiring system and lighting at the rear section for proper function. Sundries. INS CLAIMS : ACCIDENT REPAIR. DIRECT SETTLEMENT. DATE OF ACCIDENT : 26.09.2021. 3RD PARTY CAR : SLW8172X. YOUR REF NO : NIL. VEHICLE WAS SURVEYED BY MR STEVE CHEN FROM LKK
To transfer lock mechanism from old to new bootlid including conduct check on new bootlid central locking system for proper function. To remove old PDC assembly and reconnect to new bumper including conduct check for proper function. To check electrical wiring system and lighting at the rear section for proper function. Sundries. INS CLAIMS : ACCIDENT REPAIR. DIRECT SETTLEMENT. DATE OF ACCIDENT : 26.09.2021. 3RD PARTY CAR : SLW8172X. YOUR REF NO : NIL. VEHICLE WAS SURVEYED BY MR STEVE CHEN FROM LKK
including conduct check on new bootlid central locking system for proper function. To remove old PDC assembly and reconnect to new bumper 1 including conduct check for proper function. To check electrical wiring system and lighting at the 1 rear section for proper function. Sundries. 1 INS CLAIMS: ACCIDENT REPAIR. DIRECT SETTLEMENT. DATE OF ACCIDENT: 26.09.2021. 3RD PARTY CAR: SLW8172X. YOUR REF NO: NIL. VEHICLE WAS SURVEYED BY MR STEVE CHEN FROM LKK
for proper function. To remove old PDC assembly and reconnect to new bumper 1 including conduct check for proper function. To check electrical wiring system and lighting at the 1 rear section for proper function. Sundries. 1 INS CLAIMS : ACCIDENT REPAIR. DIRECT SETTLEMENT. DATE OF ACCIDENT : 26.09.2021. 3RD PARTY CAR : SLW8172X. YOUR REF NO : NIL. VEHICLE WAS SURVEYED BY MR STEVE CHEN FROM LKK
To remove old PDC assembly and reconnect to new bumper 1 including conduct check for proper function. To check electrical wiring system and lighting at the 1 rear section for proper function. Sundries. 1 INS CLAIMS : ACCIDENT REPAIR. DIRECT SETTLEMENT. DATE OF ACCIDENT : 26.09.2021. 3RD PARTY CAR : SLW8172X. YOUR REF NO : NIL. VEHICLE WAS SURVEYED BY MR STEVE CHEN FROM LKK
including conduct check for proper function. To check electrical wiring system and lighting at the 1 rear section for proper function. Sundries. 1 INS CLAIMS : ACCIDENT REPAIR. DIRECT SETTLEMENT. DATE OF ACCIDENT : 26.09.2021. 3RD PARTY CAR : SLW8172X. YOUR REF NO : NIL. VEHICLE WAS SURVEYED BY MR STEVE CHEN FROM LKK
To check electrical wiring system and lighting at the rear section for proper function. Sundries. INS CLAIMS : ACCIDENT REPAIR. DIRECT SETTLEMENT. DATE OF ACCIDENT : 26.09.2021. 3RD PARTY CAR : SLW8172X. YOUR REF NO : NIL. VEHICLE WAS SURVEYED BY MR STEVE CHEN FROM LKK
rear section for proper function. Sundries. INS CLAIMS : ACCIDENT REPAIR. DIRECT SETTLEMENT. DATE OF ACCIDENT : 26.09.2021. 3RD PARTY CAR : SLW8172X. YOUR REF NO : NIL. VEHICLE WAS SURVEYED BY MR STEVE CHEN FROM LKK
Sundries. INS CLAIMS : ACCIDENT REPAIR. DIRECT SETTLEMENT. DATE OF ACCIDENT : 26.09.2021. 3RD PARTY CAR : SLW8172X. YOUR REF NO : NIL. VEHICLE WAS SURVEYED BY MR STEVE CHEN FROM LKK
INS CLAIMS : ACCIDENT REPAIR. DIRECT SETTLEMENT. DATE OF ACCIDENT : 26.09.2021. 3RD PARTY CAR : SLW8172X. YOUR REF NO : NIL. VEHICLE WAS SURVEYED BY MR STEVE CHEN FROM LKK
DATE OF ACCIDENT : 26.09.2021. 3RD PARTY CAR : SLW8172X. YOUR REF NO : NIL. VEHICLE WAS SURVEYED BY MR STEVE CHEN FROM LKK
YOUR REF NO : NIL. VEHICLE WAS SURVEYED BY MR STEVE CHEN FROM LKK
VEHICLE WAS SURVEYED BY MR STEVE CHEN FROM LKK
· · · · · · · · · · · · · · · · · · ·
CONCULTANT ON 40.40.0004 AT 4000UDG AUTHODICED
CONSULTANT ON 12.10.2021 AT 1330HRS. AUTHORISED
REPAIR BY MS SHERINI FROM INDIA INT'L INSURANCE VIA
EMAIL ON 30.09.2021.
PROPOSE LOSS OF USE = \$100X5. THE AMOUNT IS SUBJECTED TO
INSURANCE COMPANY CONFIRMATION.
LTA SEARCH FEE = \$7.45.
Total Labour 1: 5,2
Retail
PARTS Qty Price
BOOTLID 1 1,216.40 1,2
REAR BUMPER PANEL PRIMED (LINES PDC 1 1,050.65 1,0
REAR BUMPER CARRIER 1 483.40 4
REAR BUMPER TRIM STRIP (CHROM) 1 110.55

BMW Dealer

Performance Motors Limited

A Sime Darby Motors Company Co. Reg. No. 197401559W GST Reg. No M2-0020081-x Toll-Free Number (1800-2255269)

303, Alexandra Road Sime Darby Performance Centre Singapore 159941 Fax. 64747770

280, Kampong Arang Road East Coast Centre Singapore 438180 Fax. 63449773 315, Alexandra Road Sime Darby Business Centre Singapore 159944 Fax 64796601 (AfterSales) 64796624 (Motorrad)



3,357.45

SERVICE TAX INVOICE

Repair Order No. : **Bl** 1600336

Page No. : 2 of 2

Date IN

: 12/10/2021

Invoice Number: 2455579 / WSB Invoice Date: 26/11/2021

Motor Claim Advisor: Foong Shiuh Jye

Payment Terms : 30 Days From Invoice

Total Parts

Invoice By

Karen Chin Lye Peng

GROMMET	2	0.80	1.60
PLAQUE 74MM	1	71.95	71.95
(DG) CLEANER R1 (100ML)	1	26.15	26.15
(DG/SL) W/SCREEN SEALANT (COLD 1 HOUR)	2	131.55	263.10
(DG/SL)ADHESIVE PRIMER VP 206 (30ML	1	27.85	27.85
LETTERING 216 I	1	64.75	64.75
REAR LH REFLECTOR	1	39.05	39.05
EXPANDING NUT	2	1.00	2.00
			i


Labour Charges 5,127.00 Total Labour & Parts Charges S\$ 8.634.45 Parts Charges 3,357.45 Less Insurance Excess S\$ 0.00 Lubricant/Misc 150.00 Invoice Total Amount Exclude GST: S\$ 8,634.45 GST @ 7% 604.41 S\$ Invoice Total Amount Include GST: S\$ 9,238.86

Computer generated invoice. No signature is required.

Amount Payable Include GST

S\$

9,238.86



Work was carried out subject to the Company's Terms and Conditions of Service. No complaints will be entertained unless reported within seven (7) days of the date of this invoice. For credit purchases, interest @1% per month will be debited on overdue amounts.



> Back to OneMotoring

Land Transport \(\infty \) Authority

Ce= 596 28 rear boot 1 el/Burger

Land Transport Authority 10 Sin Ming Drive Singapore 575701

GST Registration No.: M4-0006529-2

Print Date/Time:

27 Sep 2021 / 16:09:21

Receipt Date/Time: 27 Sep 2021 / 16:09:21

Tax Invoice/Receipt

Receipt No.: ITNET-00000-210927-003080

Previous Receipt No.:

S/N Item Description/ Business Transaction Reference		Amount Before	GST Amount	Amount After GST
No.		GST (S\$)	(S\$)	(S\$)
Result of Insurance Enquiry - SLW8172X				
As at 26 Sep 2021/10:00:00				
Insurance Co: INDIA INT'L INS PTE LTD				
Insurance Co: MSIG INSURANCE (SINGAP	ORE) PTE LTD			
1 Insurance Enquiry - SLW8172X				
Enquiry Fee		7.00	0.49	7.49
20210927160717957134				
	Sub-Total	7.00	0.49	7.49
	Total Before Rounding	7.00	0.49	7.49
	Rounding Difference			0.04
	Total Amount Payable			7.45
	Paid By			
	542125XXXXXX4416	eNETS	Credit Card	7.45
	Total			7.45
	Cash Change			0.00
	Tendered Amount			7.45
	Excess Refundable Amount			0.00

THANK YOU AND HAVE A NICE DAY!

Please ensure that all payments to the Authority are good and promptly settled by the payment service provider / financial institution. Otherwise, the transaction and receipt is considered void and late fee may apply.

12/17/21, 12:19 PM Merimen e-Claims

Print Received Message

This mail is associated with:

*SMX2022T (MFL2021D0004171) [SLW8172X] ΤP TAN BOON ENG

Sep 26 2021 10:00AM

Performance Motors Limited

India International Insurance Pte Ltd (HQ) (III_SG), sent on 15/12/2021 15:49 PM. **From**

LKK_HQ То

Alert - Adj Mandate Approved (S\$9546.31) - SMX2022T - Claim Handler: Sherini Pillai Subject

Approved:9546.31.			