

# Performance Motors Limited

A Sime Darby Motors Company  
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X  
Toll-Free Number (1800-2255269)

303, Alexandra Road  
Sime Darby Performance Centre  
Singapore 159941  
Fax. 64747770

280, Kampong Arang Road  
East Coast Centre  
Singapore 438180  
Fax. 63449773

315, Alexandra Road  
Sime Darby Business Centre  
Singapore 159944  
Fax. 64796601 (AfterSales)  
64796624 (Motorrad)



GST REG. NO : M2 - 0020081 - X

## ESTIMATE

Estimate No. : b1 59628  
Date Estimated : 27/09/2021  
Prepared By : Foong Shiuh Jye

Page No. : 1 of 5

### - ESTIMATE REPAIR FOR -

Tan Boon Eng  
Blk 896A Tampines St 81  
#02-870  
Singapore  
Singapore 521896

### - ACCOUNT - 219

India Int'L Insurance Pte Ltd  
64 Cecil Street  
#04-05 IOB Building  
Singapore 049711

| REGN. NO. | CHASSIS NO.       | REGN. DATE | MODEL   | MILEAGE |
|-----------|-------------------|------------|---------|---------|
| SMX2022T  | WBA2D920805K81141 | 15/08/2018 | 216i GT | 41269   |

| DESCRIPTION                                                                                                                           | VALUE         |
|---------------------------------------------------------------------------------------------------------------------------------------|---------------|
| To replace rear bumper, boot lid including to knock out dented area caused by the accident                                            | 1700 2,550.00 |
| To respray rear bumper and boot lid                                                                                                   | 1826 1,923.00 |
| To carry out body cavity preservation.<br>(Per panel).                                                                                | 112 118.00    |
| To remove and install rear windscreen glass to facilitate repair.                                                                     | 574.00        |
| To conduct water leak tests.                                                                                                          | 75.00         |
| To supply and install rear windscreen solar film.                                                                                     | 531.00        |
| To transfer lock mechanism from old to new bootlid including conduct check on new bootlid central locking system for proper function. | 504 531.00    |
| To remove old PDC assembly, replace damaged parts and reconnect to new bumper including conduct check for proper function.            | 168 177.00    |
| To check electrical wiring system and lighting at the rear section for proper function.                                               | 168 177.00    |
| Sundries.                                                                                                                             | 150.00        |

Total Labour 1: 6,806.00

| DESCRIPTION                   | QTY | PRIC     | VALUE    |
|-------------------------------|-----|----------|----------|
| # BOOTLID                     | 1   | 1,216.40 | 1,216.40 |
| REAR BUMPER CARRIER           | 1   | 483.40   | 483.40   |
| SUPPORT                       | 1   | 45.75    | 45.75    |
| RR BUMPER LH INNER SIDE GUIDE | 1   | 161.15   | 161.15   |

# Performance Motors Limited

A Sime Darby Motors Company  
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X  
Toll-Free Number (1800-2255269)

303, Alexandra Road  
Sime Darby Performance Centre  
Singapore 159941  
Fax. 64747770

280, Kampong Arang Road  
East Coast Centre  
Singapore 438180  
Fax. 63449773

315, Alexandra Road  
Sime Darby Business Centre  
Singapore 159944  
Fax. 64796601 (AfterSales)  
64796624 (Motorrad)



GST REG. NO : M2 - 0020081 - X

## ESTIMATE

Estimate No. : b1 59628  
Date Estimated : 27/09/2021  
Prepared By : Foong Shiuh Jye

Page No. : 2 of 5

| REGN. NO. | CHASSIS NO.       | REGN. DATE | MODEL   | MILEAGE |
|-----------|-------------------|------------|---------|---------|
| SMX2022T  | WBA2D920805K81141 | 15/08/2018 | 216i GT | 41269   |

| DESCRIPTION                            | QTY | PRIC     | VALUE    |
|----------------------------------------|-----|----------|----------|
| RR BUMPER RH INNER SIDE GUIDE          | 1   | 161.15   | 161.15   |
| REAR BUMPER TRIM STRIP (CHROM)         | 1   | 110.55   | 110.55   |
| # REAR BUMPER PANEL PRIMED (LI         | 1   | 1,050.65 | 1,050.65 |
| LETTERING 216 I                        | 1   | 64.75    | 64.75    |
| GROMMET                                | 2   | 0.80     | 1.60     |
| PLAQUE 74MM                            | 1   | 71.95    | 71.95    |
| # REAR WINDOW ESG                      | 1   | 657.60   | 657.60   |
| HOOK AND LOOP FASTENER                 | 6   | 2.20     | 13.20    |
| REAR BUMPER HEAT INSULATION            | 1   | 77.30    | 77.30    |
| REAR LH REFLECTOR                      | 1   | 39.05    | 39.05    |
| (DG) CLEANER R1 (100ML)                | 1   | 26.15    | 26.15    |
| (DG/SL) W/SCREEN SEALANT (COLD 1 HOUR) | 2   | 131.55   | 263.10   |
| (DG/SL)ADHESIVE PRIMER VP 206 (30ML    | 1   | 27.85    | 27.85    |

Total Parts : 4,471.60

Steve (LKK)  
12/10/21, 1.30pm

WKL RL  
P/P  
by Bel Smy  
5 d/1

LKK Auto  
the Rep  
• To resur  
• To displ  
• Parts pro  
• Third pa  
• No illeg  
• Supple  
is subject to the terms and conditions of the warranty  
Acknowledged by Repairer  
Signature:  
Date:



|                |   |           |
|----------------|---|-----------|
| Labour 1       | : | 6,806.00  |
| Parts          | : | 4,471.60  |
| Labour 2       | : | 0.00      |
| Excess         | : | 0.00      |
| Total GST @ 7% | : | 789.43    |
| Grand Total    | : | 12,067.03 |

\*\* THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY\*\*

\*\* PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE \*\*