

Team AutoPro Pte Ltd 160 Sin Ming Dr, #02-12 Sin Ming AutoCity Singapore 575722

Tel: 8269-9999 Email: estimate.tap@gmail.com / teamautopl@gmail.com

SJE :

Vehicle Nos : **SMW 4949 L**

Date of Survey :

Model : Nissan Sylphy

Date of ReSurvey:

After-Paint:

Year : 2014

Contacts :

Chassis No : MNTBBAB17Z0019258

*** AGREED Cost Of Repair and Repair Day/s with SJE ***

Amount:

Working Day:

2014

Nos.	PARTS	Qty	Unit S\$	TOTAL S\$	
1	Bootlid	1	\$ 1,250.10	\$ 798.00 1,250.10	BT✓
2	Bootlid logo	1	\$ 108.90	\$ 45.00 108.90	NECV
3	Bootlid emblem 'SYLPHY'	1	\$ 118.60	\$ 42.00 118.60	
4	Bootlid emblem 'XTRONIC CVT'	1	\$ 84.90	\$ 45.00 84.90	
5	Bootlid lamp	2	\$ 241.60 445.50	\$ 483.20 891.00	BR✓
6	Bootlid outer chrome garnish	1	\$ 258.00	\$ 158.00 258.00	BR✓
7	Bootlid outer chrome lower garnish	1	\$ 125.30	\$ ✓ 125.30	CTV
8	Bootlid inner trim board	1	\$ 198.30	\$ 198.30 198.30	NDX
9	Bootlid weatherstrip	1	\$ 286.30	\$ 91.10 286.30	TNV
10	Bootlid lock	1	\$ 107.90	\$ ✓ 107.90	JMV
11	Rear bumper	1	\$ 879.90	\$ 518.80 879.90	DDV
12	Rear bumper side retainer	2	\$ 36.30 87.40	\$ 72.60 174.80	NECV
13	Rear bumper inner sponge centre	1	\$ 68.30	\$ ✓ 68.30	BR✓
14	Rear bumper inner sponge side	2	\$ 151.84	\$ ✓ 303.68	NSX
15	Rear bumper reinforcement stopper	2	\$ 52.80	\$ 105.60 105.60	NDX
16	Rear bumper reflector	2	\$ 75.90	\$ 151.80 151.80	NDX
17	Rear end panel	1	\$ 783.60	\$ 454.30 783.60	DD✓
18	Rear end panel top garnish	1	\$ 108.40	\$ 108.40 108.40	NDX
19	Taillamp	2	\$ 471.90 658.80	\$ 943.80 1,317.60	BR✓
Parts Sub Total :				\$ 3953.30 7,322.98	
10% Discount :				\$ 395.33 732.30	
				\$ 3557.97 6,590.68	

Nos.	SPECIAL NETT	Qty	Unit S\$	TOTAL S\$
1	Sundries	1	\$ 80.00	\$ 80.00
2	Bootlid sealant	1	\$ 100.00	\$ 30.00 100.00
3	Bootlid lamp seal	2	\$ 60.00	\$ 120.00
4	Bootlid lamp clips	2	\$ 50.00	\$ 20.00 100.00
5	Bootlid outer chrome garnish clips	1	\$ 50.00	\$ 20.00 50.00
6	Bootlid outer chrome lower garnish clips	1	\$ 50.00	\$ 20.00 50.00
7	Bootlid inner trim board clips	1	\$ 50.00	\$ 50.00
8	Rear bumper clips	1	\$ 50.00	\$ 30.00 50.00
9	Rear bumper reverse sensor	2	\$ 250.00	\$ 200.00 500.00
10	Rear end panel sealant	1	\$ 100.00	\$ 100.00
11	Rear end panel top garnish clips	1	\$ 50.00	\$ 50.00
12	Taillamp clips	2	\$ 50.00	\$ 100.00
13	Taillamp seal	2	\$ 60.00	\$ 120.00
14	Rear number plate w/casing	1	\$ 80.00	\$ 80.00
SPECIAL NETT TOTAL :				\$ 320.00 1,550.00

NNX
NECV
NSX
NECV
NECV
NECV
NNX
NECV
SCV
NNX
NNX
NSX
NSX
NNX

Nos.	LABOUR	S\$
1	R&R bootlid component	\$ 80.00 150.00
2	R&R rear bumper reverse sensor	\$ 60.00 100.00
3	upholstery	\$ 300.00
4	Check wiring	\$ 100.00
5	Panel beating	\$ 800.00 1,600.00
6	Rust proofing	\$ 200.00
7	Spray painting	\$ 600.00 1,600.00
LABOUR TOTAL :		\$ 1540.00 4,050.00

Survey 14/10/2021
Resurvey 15/10/2021
1460hrs 1535hrs
TGM hr TGM hr

PARTS TOTAL : \$ 6,590.68
SPECIAL NETT TOTAL : \$ 1,550.00
LABOUR TOTAL : \$ 4,050.00
GRAND TOTAL : \$ 12,190.68

Parts 3557.97
SN 320.00
Labour 1540.00
5417.97
@20% 1083.59
4334.38

Lump sum repair
Repair days 6

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

LS 4350/2 TGM hr