

HOCK WAH MOTOR WORKSHOP PTE LTD

BLK 3011 BEDOK INDUSTRIAL PARK E
 BEDOK NORTH AVE 4,
 #01-2008/10/12 SINGAPORE 489977
 TEL : 6441 5655 FAX : 6441 5355/6243 8121
 R.O.C No : 200104141D GST Reg. No. 20-0104141-D

TO : SXXX8085B
 HO HENG CHIP
 BLK 772 BEDOK RESERVOIR VIEW
 #08-141
 SINGAPORE 470772
 TEL : FAX :
 PH : 97307944
 ATTN :

ESTIMATE BILL

Number : EB00005810
 Date : 12/11/2021
 Case No : AD00012104
 Vehicle No : SMK8589D
 Chassis : GK82001222
 Year of Mfr : 2018
 Policy No : 5108970168-02
 Model : HONDA SHUTTLE
 1.5G CVT

Term:

Sn	DESCRIPTION	QTY	U_PRICE	DISC	AMOUNT
1	REAR BUMPER INNER SPONGE LH <i>Torn</i>	1.0	40.00	(15)	46.00
2	TAILGATE WINDSCREEN MOULDING TOP <i>net</i>	1.0	20.00	(15)	23.00
3	TAILGATE WINDSCREEN MOULDING BOTTOM <i>net</i>	1.0	40.00	(15)	46.00
Nett Price - Parts Sub Total					115.00
Parts Total					115.00
SINGAPORE DOLLARS : ONE HUNDRED TWENTY-THREE AND CENTS FIVE ONLY			Less Excess		0.00
			SUBTOTAL		115.00
			GST 7.00%		8.05
			TOTAL		123.05

Date of accident : 08/10/2021 02:00 PM. Place : BEDOK NORTH AVE 3 TOWARDS BEDOK RESERVOIR

E. & O. E.

HOCK WAH MOTOR WORKSHOP PTE LTD

CUSTOMER SIGNATURE

AUTHORISED SIGNATURE