

國際汽車維修 KT MOTORWERK

Blk 3012 Bedok Ind. Park E #01-2020 Singapore 489978.
(Bedok North Ave. 4) Tel: 98287487 Fax: 6448 5177
Email: ktmotorwerk@hotmail.com
Reg. No.: 53373462B

Vehicle Number : SMH3237T
Vehicle Model : HONDA STREAM
Accident Date : 06.10.2021
Original Reg Date : 25.07.2007

Date : 07.10.2021
Chassis : JHMRN68407S200236
TP Ins. CHINA
TAIPING

Xiao Teng.

ESTIMATE

1	1 pc	Tailgate Assy <i>Distorted</i>		982.60	✓ 903.
2	1 pc	Tailgate Badge <i>new</i>		95.20	+
3	1 pc	Tailgate Emblem (STREAM) <i>new</i>		94.30	✓ 48
4	1 pc	Tailgate outer Garnish <i>new</i>		198.80	+
5	1 set	Tailgate Outer Garnish Clips <i>new</i>		30.00	+
6	1 pc	Tailgate Windscreen Moulding <i>3/4 new</i>		96.30	✓
7	1 pc	Tailgate Windscreen Inner Seal		60.00	✓
8	1 set	Tailgate Windscreen Clips <i>new</i>		30.00	+
9	1 pc	Tailgate Inner Lock <i>Damaged</i>		185.70	✓
10	1 pc	Tailgate Lock Catch <i>new</i>		36.20	+
11	1 pc	Tailgate Lock Actuator <i>new</i>		168.90	+
12	1 pc	Tailgate Weatherstrip <i>cut</i>		192.30	✓
13	1 pc	Tailgate Inner Trim <i>cracked</i>		325.80	✓
14	1 set	Tailgate Inner Trim Clips <i>new</i>		40.00	✓
15	1 pc	Tailgate Pocker Holder <i>new</i>		70.50	+
16	2 pcs	Taillamps <i>Lt cracked</i>	458.60	917.20	✓ 368
17	2 pcs	Taillamps Inner Sealer <i>new</i>	35.00	70.00	+
18	2 set	Taillamps Clips <i>new</i>	25.00	50.00	✓ 10
19	2 pcs	Taillamps Lower Retainers <i>new</i>	58.30	116.60	+
20	1 pc	End Panel (Bottom) <i>Distorted</i>		208.60	✓
21	1 pc	End Panel (Outer) <i>Distorted</i>		465.80	✓
22	1 pc	End Panel Top Trim <i>Distorted</i>		189.50	✓
23	1 set	End Panel Top Trim Clips <i>new</i>		30.00	✓ 10
24	1 pc	Vehicle Jack Cover <i>Distorted</i>		136.20	✓
25	1 set	Vehicle Jack Cover Clips <i>new</i>		25.00	+
26	2 pcs	Rear Fender Inner Trim <i>Lt cracked</i>	312.50	625.00	✓ 312.50
27	2 set	Rear Fender Inner Trim Clips <i>new</i>	30.00	60.00	✓ 30
28	1 pc	Rear Floor Panel Top Board <i>new</i>		198.70	+
29	1 pc	Rear Bumper <i>Distorted</i>		746.30	✓ 683
30	2 pcs	Rear Bumper Side Retainers <i>new</i>	65.20	130.40	✓
31	1 pc	Rear Bumper Tow Cover <i>Missing</i>		48.90	✓
32	2 pcs	Rear Bumper Stay <i>new</i>	22.00	44.00	✓
33	1 set	Rear Bumper Clips <i>new</i>		50.00	✓ 30
34	1 pc	Spare Tyre Carrier <i>new</i>		198.70	✓

35	1 pc	Spare Tyre Carrier Bolt		86.50	x
36	1 pc	Spare Tyre Carrier Nut		38.70	x
37	1 pc	Rear Exhaust Silencer		596.80	x
38	2 pcs	Rear Exhaust Mountings	48.00	96.00	x
39	1 pc	Rear Exhaust Gasket		46.50	x

7,782.00

Less 20% 1,556.40

6,225.60

451800

361440.4

Special Nett

1	1 pc	Rear Windscreen Sealant		60.00	✓
2	1 pc	Rear Number Plate with Cover		50.00	x
3	1 set	Body Panel Joint Sealant		120.00	60
4	1 set	Reverse Sensor		250.00	200

260

Labour charge

Panel Beating		1,800.00	820
Spray painting		1,800.00	850
Check Wiring on tailamps		120.00	30
Anti rust		100.00	60
Remove and install rear winscreen.		140.00	120
Remove and install tailgate parts.		120.00	60
Remove and install carpet and seat.		120.00	60
Remove and install reverse sensor		120.00	50
Remove and install rear exhaust silencer.		120.00	x

\$ 11,145.60

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Adrian G
A/s 08/10/21.

06 Days.

Total: 6004.40

A/s: 4.8K

4.810