

Our Job Ref No : 305489351

Date : 07/10/21

FINALIZATION FORM

To : LKK

Fax :

Attn : Mr Thevan

Vehicle Reg No : SHD6667X CTPL

03/10/2021

The survey and estimates of the repairs of the above-mentioned vehicle are as follows:-

1. The repair job shall bill to: CHINA TAIPING --- SLJ3689Z
2. The finalized amount shall be:
- (a) Spare Parts after List discount _____
- (b) Labour Charges _____
- Total for Part-By-Part Repair Cost** \$0.00
- (c) Lumpsum Repair (if applicable)
- Total for Lumpsum repair cost after Less: 20% _____
- Final Lumpsum Repair cost** \$2,400.00

3. Estimated normal period for repairs: 3 working days.4. **We shall treat the above amount as Correct and Confirmed if there is no reply from you within 7 working days**

5. Thank you for your assistance.


We confirm the estimates and finalized amount

Signature : 

Name : MS. LOKE YY

Tel : 62148355

Fax : 65468156

Signature : 

Name : Thevan

Date : 15/10/21

For Official Use Only

Item	Amount	Document Attached Yes or No	Confirm By (Signature)	Remarks
1. Rental Rate P/Day		YES		
2. Loss of Income Paid		NO		
3. Survey Fees				
4. LTA Search Fee	\$7.49 / \$2.00			
5. Medical Fees (on behalf of driver, if applicable)				
6. Overrun				

Remarks:

COMFORTDELGRO
ENGINEERING

VEHICLE I SHD6667X
CHINA TAIPING
305489351

TYPE OF C: TP
SURVEY B: LKK/ THEVAN
DATE : 08/10/21

SUPPLEMENTARY OF PARTS AND LABOUR COSTS

DESCRIPTION	QTY	ESTIMATE	\$	REMARKS
FRT BUMPER SPONGE	1		\$99.20	✓ cut
		TOTAL	\$99.20	

COMFORT TRANSPORTATION PTE LTD

REPAIR ESTIMATE

Vehicle No. : SHD6667X ✓

Make : HYUNDAI

Model : I-40

Date: 04/10/2021

Insurance: CHINA TAIPING

MVA: MS. LOKE YY

Qty	Parts Description / Labour	Type	Unit Price	Amount
1	REAR BUMPER COVER			\$553.00 /cut
1	REAR BUMPER CLIPS			\$22.00 /NIC
1	REAR BUMPER LOWER COVER			\$228.00 /cut
1	REAR BUMPER REFLECTOR LAMP LH			\$32.00 /scr
1	EXHAUST SILENCER LH			\$967.70 /r
1	EXHAUST PIPE CENTRE			\$730.10 /r
1	REAR BUMPER REINFORCEMENT			\$428.40 7. XSVc
1	REAR BUMPER REINFORCEMENT BRACKET LH			\$160.60 7. XSVc
1	FRT BUMPER COVER			\$1,052.20 /r /cut
10	FRT BUMPER CLIPS			\$22.00 /nec
1	RADIATOR GRILLE			\$1,480.00 /XSVc
1	FRT BUMPER CENTRE GRILLE			\$114.00 /XSVc
	SUB TOTAL			\$5,790.00
	LESS 25% $\times 1040$			\$1,447.50
	DISCOUNTED TOTAL			\$4,342.50
	FRT NUMBER PLATE WITH TRIM COVER			\$55.00 /ate DD
	REAR BUMPER RUBBER MAT			\$50.00 /NIC
	REAR BUMPER REVERSE SENSOR			\$135.70 /cut
				\$240.70
	Labour Charge			\$60.00 30
	CHL ALL LIGHTING			\$150.00 50
	REMOVE AND REFIX EXHAUST PIPE			\$900.00 560
	PANEL BEATING			\$600.00 500
	SPRAY PAINTING CHARGE			
	TOTAL LABOUR			\$1,710.00
	ESTIMATE TOTAL			\$6,293.20

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor surveyor appointed by the insurance company.

LKK Auto Consultants hence notify

the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Thuan@Lkhauto.com

82235769

4/10/21 1615

L/S after repair photo

wp 3days