

55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SLF 6888 S

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING AID.	S/N \$ 480.00	✓ ✓
2	TO REMOVE AND TRANSFER RHS HEADLIGHT'S CONTROL UNIT AND POWER MODULE.	S/N \$ 400.00	250 ✓
3	TO RENEW AND REINSTALL AIRCON CONDENSER, CHARGED AIR COOLER AND RADIATOR. CHECK ELETRICAL FANS AND CONTROL UNIT. PRESSURISE COOLING SYSTEM. TO CARRY OUT VACUUM AND REGAS.	S/N \$ 1,700.00	✓ ✓
4	TO DISMANTLE RENEW FRONT BUMPER, RHS FRONT FENDER, BONNET AND RHS HEADLIGHT. TO RENEW FRONT LOCK CARRIER AND ALIGN TO POSITION. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$ 5,600.00	2750 3000
5	TO REPSRAY FRONT BUMPER, FRONT BUMPER LOWER SPOILER, RHS FRONT FENDER, BONNET AND BOTH FRONT WHEEL ARCH TRIM.	\$ 4,800.00	2250 ✓ Bumper 550 Fender 550 Bonnet 550 Spoiler 200 Air Trim 200 x 2 = 400
6	TO CARRY OUT PRE/POST DIAGNOSTIC CHECK .	S/N \$ 384.00	✓
TOTAL LABOUR CHARGES		: \$ 13,364.00	2250

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SLF 6888 S

S/N	PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES	
			S/NETT	REMARKS
1	FRONT BUMPER <i>Dehnd</i>	1 S	1,362.00	✓ 1089.60
2	FRONT BUMPER CONNECTING PIECE <i>Nec Nec</i>	1 S	205.00	✓ X
3	FRONT BUMPER FIXING PARTS <i>new</i>	1 S	293.00	+
4	FRONT BUMPER SECURING STRIP - RH <i>new</i>	1 S	38.00	✓ X
5	FRONT BUMPER CLOSING ELEMENT - RH <i>Dehnd</i>	1 S	113.00	✓ 90
6	FRONT BUMPER GRILLE - CENTER <i>new</i>	1 S	144.00	+
7	FRONT BUMPER SPOILER <i>torn</i>	1 S	763.00	✓ 610
8	FRONT BUMPER UNDERRUN BAR <i>new</i>	1 S	518.00	✓ X
9	FRONT BUMPER CLOSING ELEMENT <i>Dehnd</i>	1 S	173.00	✓ 138.40
10	FRONT RADIATOR GRILLE <i>new ut</i>	1 S	3,530.00	✓ 2824
11	QUATTRO EMBLEM <i>new</i>	1 S	106.00	+
12	FRONT RADIATOR STRIKER PLATE <i>cracked</i>	1 S	244.00	✓ 194.80
13	FRONT BUMPER AIR GUIDE GRILLE - RH <i>Dehnd</i>	1 S	581.00	✓ 464.40
14	FRONT BUMPER AIR GUIDE END CAP - RH <i>Dehnd</i>	1 S	92.00	✓ 73.20
15	FRONT BUMPER FOAM FILLER PIECE <i>Dehnd</i>	1 S	177.00	✓ 141.60
16	FRONT BUMPER CARRIER <i>Dented</i>	1 S	981.00	✓ 784.40
17	FRONT BUMPER CARRIER BRACKET - RH <i>new</i>	1 S	257.00	✓ X
18	FRONT BUMPER CARRIER GUIDE SECTION - RH <i>Nec Nec</i>	1 S	39.00	✓ X
19	FRONT BUMPER TOP COVER <i>Dehnd</i>	1 S	129.00	✓ 102.80
20	CAUTION STICKER <i>Nec</i>	1 S	14.00	✓ 10.88
SUB TOTAL SPARE PARTS		:	\$	<u>9,759.00</u>

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SLF 6888 S

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
21	AIR CONDITIONER STICKER <i>Nec</i>	1	\$ 20.00 ✓	15.52
22	HORN <i>Nec Nec</i>	1	\$ 195.00 +	
23	FRONT PARKING AID SENSOR - RH INNER	1	TBC	x
24	FRONT PARKING AID SENSOR - RH OUTER	1	TBC	x
25	FRONT PARKING AID SENSOR SEAL	4	\$ 14.00	x
26	FRONT BUMPER WIRING SET	1	\$ 409.00	+
27	FRONT FENDER - RH <i>Buckled</i>	1	\$ 1,427.00 ✓	1141.60
28	FRONT FENDER ATTACHEMENT PART <i>Nec m</i>	1	\$ 66.00	+
29	FRONT FENDER BRACE - RH <i>? bent</i>	1	\$ 225.00	✓ 179.60
30	FRONT FENDER BRACKET - RH <i>? nn</i>	1	\$ 18.00	x
31	FRONT FENDER TOP COVER - RH <i>Nec m</i>	1	\$ 31.00	+
32	FRONT FENDER PANEL COVER - RH <i>Nec m</i>	1	\$ 40.00	+
33	FRONT BONNET <i>Dented</i>	1	\$ 4,058.00	✓ 3246.40
34	FRONT BONNET ATTACHEMENT PART <i>Nec nec</i>	1	\$ 141.00	+
35	FRONT BONNET IMPACT PROTECTION - LH / RH <i>Nec</i>	1	\$ 56.00	✓ 43.68
36	FRONT BONNET STRIKER - RH <i>? Nec m</i>	1	\$ 120.00	+
37	FRONT BONNET LOCK	1	\$ 214.00	+
38	FRONT BONNET BOWDEN CABLE	1	\$ 58.00	x
39	FRONT BONNET RELEASE CABLE COVER <i>? Nec</i>	1	\$ 10.00	x
40	FRONT BONNET RELEASE LEVER <i>Nec</i>	1	\$ 14.00	x
TOTAL SPARE PARTS		:	\$ 7,116.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHALI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG


MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SLF 6888 S

S/N	PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES	
			S/NETT	REMARKS
41	MOUNTING FOR HEADLIGHT - RH <i>cauled</i>	1	\$ 118.00	✓ 94.40
42	HEADLIGHT - RH <i>cauled</i>	1	\$ 8,191.00	✓ 6552.80
43	HEADLIGHT POWER MODULE - RH	1	\$ 758.00	+
44	HEADLIGHT LED WITH HEAT SINK - RH	1	\$ 1,098.00	✓
45	HEADLIGHT CONTROL UNIT	1	\$ 736.00	✓
46	HEADLIGHT HOSE - RH	1	\$ 39.00	+
47	HEADLIGHT LIFT CYLINDER - RH <i>Nec</i>	1	\$ 140.00	? X
48	HEADLIGHT WASHER HOSE - RH <i>new</i>	1	\$ 125.00	+
49	FRONT WHEEL HOUSNG LINER - RH <i>new</i>	1	\$ 278.00	+
50	FRONT WHEEL HOUSING LINER ATTACHMENT PART <i>new</i>	1	\$ 38.00	+
51	FRONT WHEEL SPOILRT <i>new</i>	1	\$ 155.00	? 123.60
52	FRONT WHEEL COVER - LH / RH <i>new</i>	2	\$ 1,264.00	✓ 1011.20
53	S LINE EMBLEM <i>new</i>	1	\$ 128.00	✓ 102
54	RADIATOR LOCK CARRIER <i>cauled</i>	1	\$ 1,400.00	✓ 1120
55	RADIATOR LOWER BRACE - RH <i>new</i>	1	\$ 57.00	? X
56	RADIATOR BRACKET <i>new</i>	1	\$ 16.00	? X
57	INTER COOLER HOSE - RH <i>new</i>	1	\$ 315.00	+
58	COOLANT <i>new</i>	6	\$ 266.00	✓ 212.64
59	FRONT RADIATOR AIR GUIDE - RH <i>new</i>	1	\$ 58.00	? X
60	FRONT RADIATOR AIR GUIDE - UPPER / LOWER <i>new</i>	2	\$ 96.00	? X
TOTAL SPARE PARTS			\$ 15,276.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SLF 6888 S

S/N	PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES	
			S/NETT	REMARKS
61	FRONT RADIATOR AIR GUIDE - CENTER <i>New</i>	1	\$ 42.00	<i>X</i>
62	FRONT RADIATOR ASSEMBLY <i>New</i>	1	\$ 534.00	<i>X</i>
63	NOISE INSULATION <i>New</i>	1	\$ 915.00	<i>X</i>
64	FRONT NO PLATE NEC <i>NEC</i>	S/N	\$ 60.00	<i>X</i> 60
65	SUNDRIES <i>Nec.</i>		\$ 400.00	<i>X</i> 30.88
TOTAL SPARE PARTS		:	\$ 34,102.00	
TOTAL LABOUR CHARGES		:	\$ 13,364.00	
GRAND TOTAL		:	\$ 47,466.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

 PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME
SURVEYED DATE
AUTHORISED DATE
EXCESS COST
LIABILITY
REMARKS

: Adrian Ling
: 11/10/21
:
:
:
: Not Authorised, 09 Days.
: R.S.

PLEASE NOTE

: THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE
AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER
LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF
REPAIR, WE SHALL INFORM YOU ACCORDINGLY.
FOR INSPECTION OF VEHICLE, PLEASE REFER TO
MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR
APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT