



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL : NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/0825/2021/JT
DATE : 8-Oct-21
WIP : 48104

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 11/10/21

AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY

#07-16 AIG BUILDING

SINGAPORE 079120

Attn: Motor Claims Dept

Tel: 6880 4602 - Fax: 6880 4838

OWNER'S NAME : MR CHEW SIN WAN (ZHOU XINHUAN)
ADDRESS : 532 JOO CHIAT ROAD
#18-01
SINGAPORE 427711
TELEPHONE : HP +65 92707582
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : 1900167318-01
VEHICLE NO : **SLF 6888 S**
MODEL CODE : AUDI Q5 SPORT 2.0 TFQI QU
MODEL YEAR : 27/9/2019
ENGINE NO : DAX 057355
CHASSIS NO : WAUZZZFY1K2110123
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 4-Oct-21
PLACE OF ACCIDENT : URBAN VISTA

55 UBI ROAD 1, SINGAPORE 408699

TEL: 6366 2323 FAX: 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SLF 6888 S

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING AID.	S/N \$ 480.00 ✓	
2	TO REMOVE AND TRANSFER RHS HEADLIGHT'S CONTROL UNIT AND POWER MODULE.	S/N \$ 400.00 250	
3	TO RENEW AND REINSTALL AIRCON CONDENSER, CHARGED AIR COOLER AND RADIATOR. CHECK ELETRICAL FANS AND CONTROL UNIT. PRESSURISE COOLING SYSTEM. TO CARRY OUT VACUUM AND REGAS.	S/N \$ 1,700.00 ✓	
4	TO DISMANTLE RENEW FRONT BUMPER, RHS FRONT FENDER, BONNET AND RHS HEADLIGHT. TO RENEW FRONT LOCK CARRIER AND ALIGN TO POSITION. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$ 5,600.00 2750	
5	TO REPSRAY FRONT BUMPER, FRONT BUMPER LOWER SPOILER, RHS FRONT FENDER, BONNET AND BOTH FRONT WHEEL ARCH TRIM.	\$ 4,800.00 2250	Bumper 550 Fender 550 Bonnet 550 Spoiler 200 Air Trim 200 x 2 = 400
6	TO CARRY OUT PRE/POST DIAGNOSTIC CHECK.	S/N \$ 384.00 ✓	
TOTAL LABOUR CHARGES		: \$ 13,364.00	2250

55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SLF 6888 S

S/N	PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES		REMARKS
			S/NETT		
1	FRONT BUMPER <i>Dehnd</i>	1	\$	1,362.00	✓
2	FRONT BUMPER CONNECTING PIECE ?	1	\$	205.00	?
3	FRONT BUMPER FIXING PARTS <i>neu</i>	1	\$	293.00	+
4	FRONT BUMPER SECURING STRIP - RH ?	1	\$	38.00	?
5	FRONT BUMPER CLOSING ELEMENT - RH ?	1	\$	113.00	?
6	FRONT BUMPER GRILLE - CENTER <i>neu</i>	1	\$	144.00	+
7	FRONT BUMPER SPOILER ?	1	\$	763.00	?
8	FRONT BUMPER UNDERRUN BAR ?	1	\$	518.00	?
9	FRONT BUMPER CLOSING ELEMENT ?	1	\$	173.00	?
10	FRONT RADIATOR GRILLE <i>neu</i>	1	\$	3,530.00	+
11	QUATTRO EMBLEM <i>neu</i>	1	\$	106.00	+
12	FRONT RADIATOR STRIKER PLATE <i>neu</i>	1	\$	244.00	+
13	FRONT BUMPER AIR GUIDE GRILLE - RH ? <i>Dehnd</i>	1	\$	581.00	✓
14	FRONT BUMPER AIR GUIDE END CAP - RH	1	\$	92.00	✓
15	FRONT BUMPER FOAM FILLER PIECE <i>Dehnd</i>	1	\$	177.00	✓
16	FRONT BUMPER CARRIER <i>Dented</i>	1	\$	981.00	✓
17	FRONT BUMPER CARRIER BRACKET - RH ?	1	\$	257.00	?
18	FRONT BUMPER CARRIER GUIDE SECTION - RH ?	1	\$	39.00	?
19	FRONT BUMPER TOP COVER <i>Dehnd</i>	1	\$	129.00	✓
20	CAUTION STICKER <i>neu</i>	1	\$	14.00	✓
SUB TOTAL SPARE PARTS			:	\$ 9,759.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SLF 6888 S

S/N	PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES	
			S/NETT	REMARKS
21	AIR CONDITIONER STICKER <i>nec</i>	1	\$ 20.00	✓
22	HORN <i>Nec Nec</i>	1	\$ 195.00	+
23	FRONT PARKING AID SENSOR - RH INNER	1	TBC	+
24	FRONT PARKING AID SENSOR - RH OUTER	1	TBC	+
25	FRONT PARKING AID SENSOR SEAL	4	\$ 14.00	+
26	FRONT BUMPER WIRING SET	1	\$ 409.00	+
27	FRONT FENDER - RH <i>Buckled</i>	1	\$ 1,427.00	✓
28	FRONT FENDER ATTACHEMENT PART <i>Nec m</i>	1	\$ 66.00	+
29	FRONT FENDER BRACE - RH	1	\$ 225.00	+
30	FRONT FENDER BRACKET - RH	1	\$ 18.00	+
31	FRONT FENDER TOP COVER - RH <i>nec m</i>	1	\$ 31.00	+
32	FRONT FENDER PANEL COVER - RH <i>nec m</i>	1	\$ 40.00	+
33	FRONT BONNET <i>Dented</i>	1	\$ 4,058.00	✓
34	FRONT BONNET ATTACHEMENT PART <i>Nec nec</i>	1	\$ 141.00	+
35	FRONT BONNET IMPACT PROTECTION - LH / RH <i>Nec</i>	1	\$ 56.00	✓
36	FRONT BONNET STRIKER - RH	1	\$ 120.00	+
37	FRONT BONNET LOCK	1	\$ 214.00	+
38	FRONT BONNET BOWDEN CABLE	1	\$ 58.00	+
39	FRONT BONNET RELEASE CABLE COVER	1	\$ 10.00	+
40	FRONT BONNET RELEASE LEVER	1	\$ 14.00	+
TOTAL SPARE PARTS		:	\$ 7,116.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHA1@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SLF 6888 S

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
41	MOUNTING FOR HEADLIGHT - RH ?	1 \$	118.00 ?	
42	HEADLIGHT - RH <i>cancelled</i>	1 \$	8,191.00 ✓	
43	HEADLIGHT POWER MODULE - RH	1 \$	758.00 +	
44	HEADLIGHT LED WITH HEAT SINK - RH } <i>not</i>	1 \$	1,098.00 ✓	
45	HEADLIGHT CONTROL UNIT } <i>not</i>	1 \$	736.00 +	
46	HEADLIGHT HOSE - RH	1 \$	39.00 +	
47	HEADLIGHT LIFT CYLINDER - RH ?	1 \$	140.00 ?	
48	HEADLIGHT WASHER HOSE - RH <i>not</i>	1 \$	125.00 +	
49	FRONT WHEEL HOUSNG LINER - RH <i>not</i>	1 \$	278.00 +	
50	FRONT WHEEL HOUSING LINER ATTACHMENT PART <i>not</i>	1 \$	38.00 +	
51	FRONT WHEEL SPOILRT ?	1 \$	155.00 ?	
52	FRONT WHEEL COVER - LH / RH <i>not</i>	2 \$	1,264.00 ✓	
53	S LINE EMBLEM <i>not</i>	1 \$	128.00 ✓	
54	RADIATOR LOCK CARRIER <i>cancelled</i>	1 \$	1,400.00 ✓	
55	RADIATOR LOWER BRACE - RH ?	1 \$	57.00 ?	
56	RADIATOR BRACKET ?	1 \$	16.00 ?	
57	INTER COOLER HOSE - RH <i>not</i>	1 \$	315.00 +	
58	COOLANT <i>not</i>	6 \$	266.00 ✓	
59	FRONT RADIATOR AIR GUIDE - RH ?	1 \$	58.00 ?	
60	FRONT RADIATOR AIR GUIDE - UPPER / LOWER ?	2 \$	96.00 ?	

TOTAL SPARE PARTS

: **\$ 15,276.00**

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.



55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SLF 6888 S

S/N	PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES		REMARKS
			S/NETT		
61	FRONT RADIATOR AIR GUIDE - CENTER <i>new</i>	1	\$	42.00	<i>x</i>
62	FRONT RADIATOR ASSEMBLY <i>new</i>	1	\$	534.00	<i>x</i>
63	NOISE INSULATION <i>new</i>	1	\$	915.00	<i>x</i>
64	FRONT NO PLATE <i>new</i>	S/N	\$	60.00	<i>x</i>
65	SUNDRIES <i>?</i>		\$	400.00	<i>?</i>
TOTAL SPARE PARTS		:	\$	34,102.00	
TOTAL LABOUR CHARGES		:	\$	13,364.00	
GRAND TOTAL		:	\$	47,466.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME : *Adrian King*
SURVEYED DATE : *11/10/21*
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS : *Not All Authorised, 09 Days.*

PLEASE NOTE : THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY. FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT