

**TSL Auto Garage**  
**Blk 4 Joo Chiat Complex**  
**#12-1171 Joo Chiat Road**  
**Singapore 420004**

**SJS6912K Volkswagen Golf**

No	Qty	Parts Description	Estimated Parts Price
1	1	Front left headlamp	\$ 1,297.30 <i>209 ✓ 975.80</i>
2	1	Front bumper assy	\$ 1,500.80 <i>711 - 992</i>
3	1	Front bumper left side retainer	\$ 143.80 <i>ne -</i>
4	1	Front left fender	\$ 688.80 <i>bd -</i>
5	1	Front left fender inner cowling	\$ 188.80 <i>711 ✓</i>
6	1	Front left wing mirror complete assy	\$ 908.80 <i>X n^</i>
7	1	Front left suspension assy	\$ 1,190.70 <i>X 711</i>
8	1	Front left wheel hub bearing	\$ 361.80 <i>✓ 711 - 350</i>
9	1	Front left knuckle arm	\$ 864.50 <i>711 ✓ 525</i>
10	1	Front left lower arm carrier	\$ 637.20 <i>711 ✓ 445</i>
11	1	Front left tie rod end	\$ 169.40 <i>X</i>
12	1	Front left ball joint	\$ 150.20 <i>X</i>
13	1	Front left stabilizer bar	\$ 488.80 <i>X</i>
14	1	Front left stabilizer bar linkage	\$ 169.90 <i>X</i>
15	1	Front power steering rack and pinion assy	\$ 3,200.90 <i>X n^</i>
16	1	Front left ABS Sensor	\$ 198.80 <i>✓</i>
17	1	Front left drive shaft	\$ 1,288.90 <i>X</i>
18	1	Front left brake disc	\$ 268.70 <i>X</i>
			\$ 13,718.10
		less 10%	\$ 1,371.81
			\$ 12,346.29
		<u>Special Nett Items</u>	
1	10	Front bumper clips	\$ 60.00 <i>30 ne ✓</i>
2	4	Front left fender inner cowling clips	\$ 40.00 <i>10 ne ✓</i>
3	1	Front left sports rim	\$ 950.00 <i>cut 600</i>
4	1	Front left tyre	\$ 450.00 <i>X n^</i>
5	1	Front no plate with garnish	\$ 100.00 <i>X n^</i>
			\$ 1,600.00
		<b>Total parts</b>	\$ 13,946.29 <i>640</i>

4321 ~~4107.20~~  
3888.90 ~~2198.28~~

~~2964.20~~  
~~3387.78~~

**TSL Auto Garage**  
**Blk 4 Joo Chiat Complex**  
**#12-1171 Joo Chiat Road**  
**Singapore 420004**

**SJS6912K Volkswagen Golf**

No	Description	Labour Charges
1	Labour for panel beating, cut, weld, straighten front left affected area and replace front left damaged parts.	\$ 1,200.00 <del>400</del> 500
2	To putty and spray painting front left portion.	\$ 1,200.00 500
3	To check wiring and focus front headlamp.	\$ 50.00 30
4	To apply anti rust proofing to front left affected area.	\$ 140.00 30
5	To remove and install front left undercarriage parts.	\$ 350.00 150? p. work ✓
6	To balance front left wheel.	\$ 50.00 30
7	To conduct wheel alignment.	\$ 120.00 80 report
8	To synchronise front left wing mirror for function.	\$ 100.00 x nn
9	Towing service.	\$ 100.00 x nn.
<b>Total labour :</b>		<b>\$ 3,310.00</b> 1320

**Total parts : \$ 13,946.29**

**Total labour : \$ 3,310.00**

**Total repair cost : \$ 17,256.29**

Tanpin 97495746  
 Wp' 12/10/21 @ 1150  
 L/S Resurvey after repair  
 Tanpin C/Khanduon  
 04 days

3888.90  
 640  
 1320  
 5848.90  
 4/5 \$ 4700  
 4 days #

18 18  
 0  
 8 8  
 4/5 0 1/2 0  
 8

**LKK Auto Consultants** hence notify  
**the Repairer of the following:**

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: