

Progressive Car Care Pte Ltd

Blk 3022A Ubi Road 1 #01-45/46 Singapore 408716
TEL: 6741 5336 FAX: 6741 7208 Email: claims@procarcare.com.sg
GST:201006949C RCB NO:201006949C

not follow
Link
12/10/21
Amplitude Atherap
2/5 * 5000/
4 days.

M/S : KOH BOCK SWI
40 METROPOLE DRIVE
SINGAPORE 456717

Estimate No: EST1507411
Date: 09 Oct 2021
Policy No: MT/00771902
Veh Reg No: SFH419M
Make/Model: TOYOTA ESTIMA
AERAS PREMIUM 2.4 A
Chassis No: ACR500194367
Engine No: 2AZ4A17434
Reg. Date: 31/03/2016

ATTN: MS FIRST CAPITAL INSURANCE LTD

Your Ref No: TP 1021-6519
Claim Type: Third Party
Accident Date: 08/10/2021
TP Veh Reg No: YL7737C

Estimate Repair Cost to Vehicle No :SFH419M

Description	U/Price	Quantity	Price S\$	Amount S\$
List Price				
1 REAR BOOT <i>Body</i>	1,753.600	1 PC	1,753.60	✓
2 REAR BOOT GLASS <i>moulding</i>	101.6000	1 PC	101.60	✓
3 REAR BOOT TOP LOCK <i>no/shld</i>	490.3000	1 PC	490.30	✓
4 REAR BOOT BOTTOM LOCK <i>no</i>	80.9000	1 PC	80.90	X
5 REAR BOOT RUBBER <i>no</i>	371.7000	1 PC	371.70	X
6 REAR BOOT TOYOTA LOGO <i>no</i>	72.2000	1 PC	72.20	✓
7 REAR BOOT ESTIMA WORDING <i>no</i>	72.2000	1 PC	72.20	✓
8 REAR BOOT TURBO WORDING <i>no</i>	82.5000	1 PC	82.50	✓
9 REAR BOOT AERAS WORDING <i>no</i>	71.4000	1 PC	71.40	✓
10 REAR BOOT REFLECTOR - LH <i>no</i>	362.8000	1 PC	362.80	X
11 REAR BOOT OUTER CHROME <i>scr</i>	210.7000	1 PC	210.70	✓
12 REAR BOOT INNER SIDE SENSOR - LH/RH <i>n/s shld o/s n</i>	1,292.200	2 PC	2,584.40	✓
13 REAR BUMPER <i>no/scr</i>	450.7000	1 PC	450.70	✓
14 REAR BUMPER CLIPS <i>no</i>	5.5000	10 PC	55.00	✓
15 REAR BUMPER SIDE HOLDER - LH/RH <i>no</i>	79.8000	2 PC	159.60	✓
16 REAR BUMPER FOAM - LH/RH <i>no</i>	105.6000	2 PC	211.20	X
17 REAR BUMPER TOW COVER - LH/RH <i>no</i>	38.7000	2 PC	77.40	X
<i>1 set</i> 18 REAR BUMPER SENSOR <i>shld</i>	418.7000	1 PC	1,674.80	250 s/n
19 REAR BUMPER SENSOR COVER <i>no</i>	50.6000	4 PC	202.40	X
20 REAR BUMPER TOP GARNISH <i>no</i>	280.6000	1 PC	280.60	X
21 REAR PANEL ASSY <i>R</i>	755.4000	1 PC	755.40	X
22 REAR PANEL LOWER MEMBER <i>R</i>	480.7000	1 PC	480.70	X
23 TAIL LAMP - LH <i>no</i>	319.5000	1 PC	319.50	X
24 TAIL LAMP LOWER PANEL - LH <i>R</i>	480.7000	1 PC	480.70	X
			11,402.30	
Less 25%			2,850.58	8,551.73
Special Net				
25 REAR BOOT LOGO <i>no</i>	120.0000	1 SET	120.00	✓
26 BODY STICKER <i>no</i>	350.0000	1 SET	350.00	120
27 REAR BOOT CAMERA <i>one/shld</i>	350.0000	1 SET	350.00	300
<i>Ree</i> 28 SPONGE TAPE <i>no</i>	20.0000	1 PC	20.00	✓
<i>Ree</i> 29 SEALANT <i>no</i>	20.0000	2 PC	40.00	✓
30 REAR NUMBER PLATE WITH CASING <i>scr</i>	35.0000	1 PC	35.00	✓
			915.00	915.00

Labour

Progressive Car Care Pte Ltd

Blk 3022A Ubi Road 1 #01-45/46 Singapore 408716
TEL: 6741 5336 FAX: 6741 7208 Email: claims@procarcare.com.sg
GST:201006949C RCB NO:201006949C

M/S : KOH BOCK SWI
40 METROPOLE DRIVE
SINGAPORE 456717

Estimate No: EST1507411
Date: 09 Oct 2021
Policy No: MT/00771902
Veh Reg No: SFH419M
Make/Model: TOYOTA ESTIMA
AERAS PREMIUM 2.4 A
Chassis No: ACR500194367
Engine No: 2AZ4A17434
Reg. Date: 31/03/2016

ATTN:

Your Ref No: TP 1021-6519
Claim Type: Third Party
Accident Date: 08/10/2021
TP Veh Reg No: YL7737C

Estimate Repair Cost to Vehicle No :SFH419M

Description	U/Price	Quantity	Price	Amount
			SS	SS
31 TO KNOCK OUT DENTS, CUT/WELD REAR PANEL, REMOVE, REPLACE ACCIDENT PARTS	1,100.000	1 JOB	1,100.00	600
32 TO RESPRAY PAINT ON ACCIDENT PORTIONS	1,200.000	1 JOB	1,200.00	800
33 TO CHECK WIRING	50.0000	1 JOB	50.00	20
34 TO TUFF-KOTE	100.0000	1 JOB	100.00	40
35 TO REMOVE AND REFIT REAR END PANEL LINING AND GARNISH TO FACILITATE REPAIR	80.0000	1 JOB	80.00	✓
36 TO REMOVE, REPLACE REAR BUMPER SENSOR	50.0000	1 JOB	50.00	✓
37 TO REMOVE, REFIX REAR WINDSCREEN	150.0000	1 JOB	150.00	120
38 TO REMOVE, TRANSFER FRONT REAR BOOT	80.0000	1 JOB	80.00	60
39 TO RESET FAULT CODE	150.0000	1 JOB	150.00	X
			2,960.00	2,960.00
Total			SS 12,426.73	
Add GST @ 7%			869.87	
Total Amount Payable			SS 13,296.60	

TOTAL: SINGAPORE DOLLAR THIRTEEN THOUSAND TWO HUNDRED NINETY SIX AND CENTS SIXTY ONLY

For Progressive Car Care Pte Ltd

AUTHORISED SIGNATURE

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

S.N - H81
L - 1770
6264