

REPAIR ESTIMATE*

VEHICLE NO SHD4779U ✓

29.09.21

P/P

MAKE 13.02.2020

CHIANG/NTUC

MODEL ONIQ G2

Qty	Parts Description/ Labour	Type	Amount
1	REAR BUMPER		\$459.40 ✓
1	REAR BUMPER SIDE BRACKET LH/RH		\$55.80 111.60 \$55.80 X SVC
1	REAR BUMPER REINFORCEMENT		\$394.80 X SVC
1	REAR BUMPER STAY LH		\$138.10 X SVC
10	REAR BUMPER CLIPS		\$2.20 \$22.00 MIC
1	REAR BUMPER CENTRE MOULDING		\$451.25 Def
1	REAR BUMPER LOWER COVER		\$155.00 X SVC
1	BUMPER TOW COVER		\$98.80 X SVC
1	REAR BUMPER REFLECTOR LH		\$41.45 X SVC
1	REAR BUMPER FOG LAMP		\$201.10 X SVC
	SUB TOTAL		\$2,017.70
	20.00%		\$403.54
	DISCOUNTED TOTAL		\$1,614.16
1	REAR NUMBER PLATE W/HOLDER		\$55.00 ✓ Scr
1	REAR REVERSE SENSOR		\$180.00 X (100) SVC
			\$235.00 SVC
	Labour Charge		
	Panel Beating		\$560.00 350
	Spray Painting Charge		\$300.00 250
	Check Wiring and Lighting		\$60.00 20
	Tuff Kote		\$60.00 20
	Remove/refix Reverse sensor		\$60.00 10
	TOTAL LABOUR		\$1,040.00
	ESTIMATE TOTAL		\$2,889.16 2933.80
This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.			

Thevan@LKKauto.com

82235769

4/10/21 1745

P/P before paint photo

w/p 2 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: