Our J	lob Re	1 No 30	5489066			ENGINEERING
Date		: 0	8/10/21		Co: 59	nfortDelGro Engineering Pte Ltd Loyang Drive Singapore 508989
FINA	LIZAT	ION FORM			Fer	6546 8156
To	; _		LKK		Fex:	
Attn	:		THEVAN		, ,	
		: SHD	6583D		DOA	01/10/21
The s	urvev					
			the repairs of the ab	ove-mentione	ed vehicle are	as follows:-
1.	The	epair job shall bi	ll to:	NTUC		SLS7259H
2.	The f	inalized amount	shall be:			
	(a)	Spare Parts aft	er List discount			
	(b)	Labour Charge	S			
		Total for Part-	By-Part Repair Cos	t		
	(c.)	Lumpsum Repartotal for Lumpsur Final Lumpsur	air (if applicable) sum repair cost after n Repair cos t	Less: <u>20%</u>	_	\$900.00
3.	Estim	nated normal peri	od for repairs:	w	orking days	
4.	We s withi	hall treat the ab n 7 working day	ove amount as Corr s	rect and Conf	firmed if there	is no reply from you
5.	Than	k you for your as	sistance.		e confirm the alized amount	estimates and
	Signa	ature :	W	_ Si	gnature;	Ø
	Name : JUMANI			_ Na	ame :	THEVAN
	Tel	: 6214 83	15	_ Da	ate :	15/10/21
	Fax	: <u>6546815</u>	6	_		
For O	fficial	Use Only				
		ltem	Amount	Document Attached Yes or No	Confirm By (Signature)	Remarks
1. Re	ental R	ate P/Day		YES		
		ncome Paid	•	N		
3. Su	rvey F	ees	-	-		
		rch Fee	7.49 / 2.00	YES		
		ees (on behalf if applicable)				
6 Ov		-,,/-/				

Remarks:

ENCINEERING

VEHICLE NO. :	SHD6583D	TYPE OF CASE	:	NTUC
JOBCARD NO.	305489066	SURVEY BY	:	LKK - THEVAN
ACC.DATE	01/10/21	DATE	:	

SUPPLEMENTARY OF PARTS AND LABOUR COSTS						
DESCRIPTION	QTY	ESTIMATE	REMARKS			
REAR LH DOOR RUBBER SEAL	1	\$402.30	cut			
CHECK ITEM						
	1					
ABOUR						
	TOTAL:	\$402.30	JUMANI			

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE

Mul- (Us)

Date: 02.10.2021 Time: 11:51:52

Page: 1

COMPANY: THIRD PARTY'S CLAIMS (CAS)

CUSTOMER: 7010045

ADDRESS: COMFORT TRANSPORTATION PTE LTD

383 SIN MING DRIVE

SINGAPORE SINGAPORE 575717

65508755

JOB NO REGN NO 305489066 SHD6583D

MILEAGE

0000000000

MAKE

MERCEDES BENZ

MODEL DATE OF REGN

E220CDI(E6) 23.03.2016

DATE/TIME IN

02.10.2021 09:00

ACCIDENT DATE

01.10.2021

JOB / PARTS DESCRIPTION

OTY IND UNIT-PRICE DISC% AMOUNT

PART REQUISITION

0001 04-01-0202-0596-G REAR DOOR LEFT

1 L 2,870.00 20.00 2,296.00 XV

0002 28-01-0299-0020-A LOGO'COMFORTDELGRO* MOQ30

1 N 80.00 10.00 72.00/N(C

0003 28-01-0299-2007-A LOGO LIMO CAB BIG

1 N 80.00 10.00 72.00 /

SUB-TOTAL : 2,440.00

JOB NATURE

0000 PB

PANEL BEATING

0001 SP

SPRAYPAINT CHARGE

300.00 Z 50

SUB-TOTAL : 700.00

TOTAL : 3,140.00

AUTHORISED: YES / NO

Jumani

SURVEYOR NAME & SIGNATURE

DATE:

MVA NAME & SIGNATURE 10 DATE:

Thevan@LAhauto.lom 87235769 4(10)21 1515 US 9-flu repair photos UP 2 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed <u>and</u> is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: