

Our Job Ref No : 305489350
Date : 07/10/21

COMFORTDELGRO ENGINEERING

ComfortDelGro Engineering Pte Ltd
59 Loyang Drive Singapore 509999
Fax: 6546 8156

FINALIZATION FORM

To : LKK
Attn : Mr Thevan
Vehicle Reg No. : NTUC CTPL

Fax :

02/10/2021

The survey and estimates of the repairs of the above-mentioned vehicle are as follows:-


1. The repair job shall bill to: NTUC --- YN9110L
2. The finalized amount shall be:
 - (a) Spare Parts after List discount
 - (b) Labour Charges
 - Total for Part-By-Part Repair Cost** \$0.00
 - (c.) Lumpsum Repair (if applicable)
Total for Lumpsum repair cost after Less: 20%
Final Lumpsum Repair cost \$3,700.00


3. Estimated normal period for repairs: 3 working days.

4. We shall treat the above amount as Correct and Confirmed if there is no reply from you within 7 working days

5. Thank you for your assistance.

We confirm the estimates and finalized amount

Signature : 
Name : MS. LOKE YY
Tel : 62148355
Fax : 65468156

Signature : 
Name : Thevan
Date : 15/10/21

For Official Use Only

Item	Amount	Document Attached Yes or No	Confirm By (Signature)	Remarks
1. Rental Rate P/Day		YES		
2. Loss of Income Paid		NO		
3. Survey Fees				
4. LTA Search Fee	\$7.49 / \$2.00			
5. Medical Fees (on behalf of driver, if applicable)				
6. Overrun				

Remarks:

COMFORT TRANSPORTATION PTE LTD

REPAIR ESTIMATE

Vehicle No. : SHD 6765x
Make : MERCEDES
Model : E220

2/10/2021
Date: 05/07/2021

Insurance: NTUC
MVA: MS. LOKE YY

Qty	Parts Description / Labour	Type	Unit Price	Amount
1	FRONT BUMPER ASSY			\$1,890.50
10	BUMPER CLIPS			\$22.00
1	FRT BUMPER CENTRE GRILLE			\$290.50
1	HEADLAMP ASSY LH			\$2,380.00
1	RADIATOR GRILLE			\$1,220.00
1	RADIATOR GRILLE SUPPORT			\$339.00
1	RADIATOR GRILLE ADJUSTER BRACKET			\$685.70
1	RADIATOR TOP PANEL			\$330.50
1	BONNET ASSY			\$2,850.60
1	BONNET LOCK SENSOR			\$285.50
1	BONNET INSULATOR			\$235.40
SUB TOTAL				\$10,529.70
LESS 20%				\$2,105.94
DISCOUNTED TOTAL				\$8,423.76
FRT NUMBER PLATE WITH TRIM COVER				\$55.00
				\$55.00
Labour Charge				
PANEL BEATING				\$800.00
SPRAY PAINTING CHARGE				\$600.00
CHECK ALL LIGHTING				\$60.00
TOTAL LABOUR				\$1,460.00
ESTIMATE TOTAL				\$9,938.76

This is an initial estimate based on a visual inspection of the above vehicle. The final repair estimate will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

Thuan @ Lkhauto . com
82235769
4/10/21 1500
L/S after repair photo
wp 3 days

The final repair estimate will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: