



REF: SMR/ 21010724/Ku

Mailing address: Blk 225 #07-579 Ang Mo Kio Ave 1 Singapore 560225
H/p 91082728

Fax : 64816131

Tan Wee Seng
53 Surin Ave
Singapore 565644

Not Ashamed
61 Reg. & 7350h
Burning After Pains
5 days.

Vehicle No : SJS 8581 T
Make : Mercedes B180
Year : 2009

WDO 2452322 J 509575

Qty	Description	Unit Price	Amount
-----	-------------	------------	--------

Estimate Cost Of Repair

1 pc	Front n/s door assy → 2100
1 pc	Front n/s door outer protector
1 pc	Front n/s door weatherstrip
1 pc	Front n/s door frame black sticker
1 pc	Front n/s door inner trim board → 1915
1 pc	Front n/s door glass regulator/motor
1 pc	Front n/s door inner lock
1 pc	Rear n/s door assy → 2195
1 pc	Rear n/s door outer protector
1 pc	Rear n/s door weatherstrip
1 pc	Rear n/s door frame black sticker
1 pc	Rear n/s door inner trim board
1 pc	Rear n/s door glass regulator/motor
1 pc	Rear n/s door inner lock
1 pc	Rear n/s fender protector
1 pc	N/S rocker panel garnish

	B ₇	\$2,100.00	✓
	M ₁	\$155.00	✓
168IN	M ₂	\$328.00	508IN ✓
	M ₃	\$105.00	✓
	MY CM	\$1,920.00	✓
	CM	\$855.00	✓
	n	\$455.00	x
	M ₇	\$2,195.00	✓
	m/s	\$135.00	✓
168IN	M ₈	\$328.00	508IN ✓
	M ₉	\$105.00	✓
	S ₁	\$1,920.00	x
	S ₂	\$855.00	x
	n	\$455.00	x
	S ₃	\$85.00	x
	Net / CM	\$550.00	✓
		\$12,546.00	
	Less 10 %	\$1,254.60	
		<u>\$11,291.40</u>	

Labour Charges

Remove/renew the above parts including knocking, cutting & welding etc.

\$1,200.00 600

To putty & spray paint on accident affected portion.

\$1,200.00 Jan

Check/reconnect wiring.

\$45.00 20

To spray anti rust on accident affected portion.

\$150.00 601

Remove/refit front & rear n/s door glass, mechanism, inner lock, trim board to new door. • To resurvey before/after spray painting

\$180.00 12¢

Total	\$14,066.40
-------	-------------

LKK Auto Consultants hence notify
the Repairer of the following:

- To preserve and/or replace spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature: _____

Date: