

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CC4/AIG21010466/UPA3Q2**Date:** 07/02/2023REFERENCE

|                              |                                      |                             |              |
|------------------------------|--------------------------------------|-----------------------------|--------------|
| Handling Insurer:            | AIG Asia Pacific Insurance Pte. Ltd. | Policy No:                  | 1900252193   |
| <b>Claimant Vehicle No :</b> | FBJ1109M                             | <b>Insured Vehicle No :</b> | SMD899Z      |
| Date of Loss:                | 30/09/2021                           | Nature of Claim:            | TP           |
|                              |                                      | Claim No:                   | 1810651155SG |

DESCRIPTION & IDENTIFICATION OF VEHICLE

|                             |                                   |             |                   |
|-----------------------------|-----------------------------------|-------------|-------------------|
| Reg No:                     | <b>FBJ1109M</b>                   | Engine No:  | M688M1001828      |
| Make & Model:               | PIAGGIO VESPA LX, 155cc I.E. 3V   | Chassis No: | ZAPM6840000003583 |
| Reg. Date:                  | 06/01/2014 (Man. Year: 2013)      | Odometer:   | 98940 km          |
| Colour:                     | Red                               |             |                   |
| Engine Capacity:            | 155 cc                            |             |                   |
| Market Value/New Car Price: | N/A                               |             |                   |
| Sum Insured (S\$):          | <b>Market Value/New Car Price</b> |             |                   |

CONDITION OF VEHICLE AT THE TIME OF SURVEY

|                          |                         |                      |                          |                         |
|--------------------------|-------------------------|----------------------|--------------------------|-------------------------|
| General Condition:       | Steering (Serviceable): | Yes                  | Footbrake (Serviceable): | Yes                     |
| Handbrake (Serviceable): | Yes                     | Engine Modification: | No                       | Pre-accident Condition: |

CONDITION OF TYRES

|                   |               |                  |               |
|-------------------|---------------|------------------|---------------|
| Front Tyre Size:  | 110-70 -11    | Rear Tyre Size:  | 120-70-10     |
| Front Left Side:  | Michelin 7 mm | Rear Left Side:  | Michelin 7 mm |
| Front Right Side: | 0 mm          | Rear Right Side: | 0 mm          |

*The above values represent the remaining tyre treads depth*

| <b>COST OF CLAIMS</b>                           | <b>Repairer's</b> | <b>Adjuster's</b> | <b>Difference</b> | <b>Diff %</b> |
|-------------------------------------------------|-------------------|-------------------|-------------------|---------------|
| Parts                                           | 5,959.00          | 1,981.30          | 3,977.70          | 66.75         |
| Miscellaneous Items                             | 0.00              | 0.00              | 0.00              |               |
| Labour                                          | 2,160.00          | 1,050.00          | 1,110.00          | 51.39         |
| Paintwork Labour                                | 0.00              | 0.00              | 0.00              |               |
| Towing                                          | 0.00              | 0.00              | 0.00              |               |
| <b>Calculated Gross Total (S\$)</b>             | <b>8,119.00</b>   | <b>3,031.30</b>   | <b>5,087.70</b>   | <b>62.66</b>  |
| <b>Approved Total (Overridden) (S\$)</b>        |                   | <b>2,400.00</b>   |                   |               |
| <b>Nett Amount (S\$)</b>                        | <b>8,119.00</b>   | <b>2,400.00</b>   | <b>5,719.00</b>   | <b>70.44</b>  |
| <b>+ Loss of Use (5.0 x S\$20.00/day) (S\$)</b> |                   | 100.00            |                   |               |
| <b>Nett Liability (S\$)</b>                     |                   | <b>2,500.00</b>   |                   |               |
| <b>Global Sum Settlement (S\$)</b>              |                   | <b>2,500.00</b>   |                   |               |

INSPECTION

|                             |                          |                                                    |
|-----------------------------|--------------------------|----------------------------------------------------|
| Date of Assignment:         | 12/10/2021               | Erofia Motor Trading Pte Ltd - (kaki Bukit) (HQ)   |
| Date Inspected:             | 12/10/2021 Inspected At: | 1 Kaki Bukit Avenue 6, #02-62 AutoBay @ Kaki Bukit |
| Estimated Period of Repair: | 4.0 days                 | Singapore 417883                                   |

**Adjuster:** MARCUS CHUA**Manager:** CHEW HSIAO TONG

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Recommended Parts

| No. | Qty | Part No. | Particulars              | Condition                   | Repairer's | Amount     |
|-----|-----|----------|--------------------------|-----------------------------|------------|------------|
| 1   | 1   |          | *FRONT FENDER            | Cut                         | 220.00 FL  | *220.00 FL |
| 2   | 1   |          | *FRONT FORK ASSY         | Serviceable                 | 880.00 FL  | *- FL      |
| 3   | 1   |          | *FRONT SHOCK ABSORBER    | Not Necessary               | 380.00 FL  | *- FL      |
| 4   | 1   |          | *FRONT FORK CHROME COVER | Cut                         | 120.00 FL  | *120.00 FL |
| 5   | 1   |          | *FRONT RIM               | Not Necessary               | 580.00 FL  | *- FL      |
| 6   | 1   |          | *FRONT BRAKE DISC        | Not Necessary               | 280.00 FL  | *- FL      |
| 7   | 1   |          | *HANDLE BAR              | Not Necessary               | 320.00 FL  | *- FL      |
| 8   | 1   |          | *SET HAND GRIP           | Torn                        | 180.00 FL  | *180.00 FL |
| 9   | 1   |          | *FRONT SIGNAL -L/H       | Cracked                     | 180.00 FL  | *105.00 FL |
| 10  | 1   |          | *SIDE MIRROR             | N/S Cut / O/S Not Necessary | 310.00 FL  | *120.00 FL |
| 11  | 1   |          | *FRONT SIDE LIVING       | Cut                         | 240.00 FL  | *240.00 FL |
| 12  | 1   |          | *BRAKE LEVER             | Cut                         | 135.00 FL  | *58.00 FL  |
| 13  | 1   |          | *REAR FOOTREST -L/H      | Cut                         | 180.00 FL  | *49.00 FL  |
| 14  | 1   |          | *REAR LOWER COVER        | Cut                         | 180.00 FL  | *180.00 FL |
| 15  | 1   |          | *BELT COVER              | Cut                         | 680.00 FL  | *680.00 FL |
| 16  | 1   |          | *REAR SIGNAL -L/H        | Cracked                     | 180.00 FL  | *105.00 FL |
| 17  | 1   |          | *MAIN STAND              | Repair                      | 145.00 FL  | *- FL      |
| 18  | 1   |          | *SET NUMBER PLATE        | Necessary                   | 38.00 FS   | *10.00 FS  |
| 19  | 1   |          | *SET STEERING CONE       | Not Necessary               | 120.00 FS  | *- FS      |
| 20  | 1   |          | *REAR BOX                | Repair                      | 650.00 FS  | *- FS      |
| 21  | 1   |          | *REAR BOX BRACKET        | Not Necessary               | 180.00 FS  | *- FS      |
| 22  | 1   |          | *E.R.P IU                | Not Necessary               | 180.00 FS  | *- FS      |
| 23  | 1   |          | *VESPA EMBLEM            | Necessary                   | 120.00 FS  | *120.00 FS |

F=Franchise part. S=SpcNett. L=ListItemDisc.

|                                                            |                 |                 |
|------------------------------------------------------------|-----------------|-----------------|
| <b>Sub Total (\$\$)</b>                                    | <b>6,478.00</b> | <b>2,187.00</b> |
| <b>- List Item Discount on L Items 10.00/10.00% (\$\$)</b> | 519.00          | 205.70          |
| <b>Total Parts (\$\$)</b>                                  | <b>5,959.00</b> | <b>1,981.30</b> |

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

| No                             | Particulars                                 | Lab.Type | Repairer's      | Amount          |
|--------------------------------|---------------------------------------------|----------|-----------------|-----------------|
| <b>Labour Items</b>            |                                             |          |                 |                 |
| 1                              | TO PROVIDE TOWING SERVICE (LOD)             | New      | 50.00           | 50.00           |
| 2                              | TO CHECK WIRING AND RESET HEADLAMP FOCUSING | New      | 80.00           | 0.00            |
| 3                              | TO PROVIDE LABOUR                           | New      | 480.00          | 400.00          |
| 4                              | TO REPAIR BODY FRAME                        | New      | 550.00          | 0.00            |
| 5                              | TO RE-SPRAY PAINTING                        | New      | 1,000.00        | 600.00          |
| <b>Gross Labour Cost (S\$)</b> |                                             |          | <b>2,160.00</b> | <b>1,050.00</b> |

Report was unsubmitted during this print-out.

< END OF ESTIMATES >