



LIU'S BROTHER AUTO ENGINEERING WORKSHOP

No. 1 Kaki Bukit Avenue 6 #01-01 Auto Bay @ Kaki Bukit Singapore 417883
ROB No: 53291793J . Tel: 6741-1730 / 731 . Email: liusbro@gmail.com

Invoice/Ref No GBC6449K210810

Estimate

Customer

Name: MSIG Insurance (Singapore) Pte Ltd

Address: Motor Claims Department

4 Shenton Way #21-01

SGX Centre 2

Singapore 068807

Date: 11-10-21

Vehicle No: GBC6449K

Model/Make: Toyota Hiace
Manual

Item No.	Descriptions Of Parts	Original Quotation / Estimation	Revised Quotation / Cost Of Repair
1	Rear Rh Fender <i>R</i>	\$ 1,308.30	
2	Fender Outer Panel <i>R</i>	\$ 517.00	
3	Sliding Door <i>body</i>	\$ 1,594.50	
4	Sliding Door Lock <i>11</i>	\$ 288.10	
5	<i>1 set</i> "Corporate" Advertisement & Artwork <i>1 set</i>	\$ 1,400.00	
6			
	To remove, replace and transfer Sliding door panel, fitting and mechanisms	\$ 80.00	<i>50</i>
	Labor for Panel Beating, Cut, Weld, Straighten & Replacing Parts Etc	\$ 1,200.00	<i>600</i>
	To putty & spray painting & including touch up paint on accident affected areas	\$ 800.00	<i>500</i>
	To apply Rust Proofing, reseal tuff-coating treatment on accident area	\$ 60.00	<i>30</i>

Total Parts & Labour of estimate for damaged vehicle

\$ 7,247.90

Total amount in Lump Sum Basis for repaired vehicle

SDLS:



M/s Liu's Bro Auto Engrg Wks

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Submit to insurance

not Authorised
all
11/10/21
2/3 @ 2600
4 days
the photo up

P-1453.1
262
P-1091.32
SN-1000
L-1170
3211.32