



CHENG HOE MOTOR PTE LTD

Blk 1019, Yishun Industrial Park A, #01-374/382, Singapore 768761
Tel : 67556142 Fax : 67557719
Email: chmotor@singnet.com.sg

TP INSURER:

--

China Taiping Insurance (Singapore) Pte. Ltd. (HQ)

Singapore

PARTICULARS OF CLAIM

Claim Type:	THIRD PARTY	Ref. No:	TP/CHINA(GBH4521X)
Policy No:		Date of Loss:	10/10/2021
Vehicle Reg. No.:	GBD7946E	Driveable?	
Party At Fault:	UNKNOWN		
Driver (TP):	CHANG CHON YONG RANDY	Driver (Insured):	GLENN QUAH HUI JING
Make/Model:	MERCEDES-BENZ CITAN 109 CDI VAN, 1.5 EXTRA LONG 2 SEATERS (A)	Vehicle Reg. Date:	29/04/2015
Vehicle Colour:	BLACK		
Engine No:	K9KB608D454770	Chassis No:	WDF4156052U158343
Odometer:	0 KM		
Paint Type:			
Total Loss?	NO		
Est. Duration of Repair (day)	0		
Description of Accident/Loss	REFER TO GIA REPORT ATTACHED.		
Remarks:	VEHICLE CURRENTLY LYING YISHUN WORKSHOP.		
Present Location:	CHENG HOE MOTOR PTE LTD (YISHUN)		

*Not Authorised
L11ny \$2400
Recovery After Paint
5 days*

COST OF CLAIMS

	Amount
Parts	
Miscellaneous Items	2,201.00
Labour	80.00
Paintwork Labour	1,480.00
Wing	0.00
	0.00
Gross Total (S\$)	3,761.00
+ GST 7.00% (S\$)	263.27
Nett Amount (S\$)	4,024.27

claim is handled by: SHARON CHIONG BENG CHOON

Generated using Merimen e-Claims Internet Estimation & Adjusting System

REPAIR DETAILS

Reference

Part Source: (Last Synchronised: 12 Oct 2021)
 Parts: N/A MERCEDES-BENZ CITAN 109 CDI VAN 1.5 EXTRA LONG 2 SEATERS (A) (Model not available in database)
 Labour: Repairer's (Price-denominated Standard List)
 Print Code: (Unsubmitted, no print-code for GBD7946E)
 Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
 Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

GBD7946E
 TP/CHINA

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*1 PC RH TAILGATE	0.00	0.00	*580.00 F ✓
2	1		*1 PC RH TAILGATE EMBLEM (109 CDI)	0.00	0.00	*35.00 F ✓
3	1		*1 PC LH TAILGATE THIRD LIGHT	0.00	0.00	*105.00 F ✓
4	1		*1 PC LH TAILGATE LOGO	0.00	0.00	*38.00 F ✓
5	1		*1 PC LH TAILGATE EMBLEM (CITAN)	0.00	0.00	*35.00 F ✓
6	1		*1 PC LH TAILGATE GLASS	0.00	0.00	*230.00 F ✓
7	1		*1 PC REAR BUMPER	0.00	0.00	*650.00 F ✓
8	1		*1 PC REAR BUMPER REINFORCEMENT	0.00	0.00	*290.00 F ✓
9	1		*1 PC LH TAILLAMP	0.00	0.00	*210.00 F ✓
10	1		*1 PC LH TAILGATE WIPER NOZZLE	0.00	0.00	*28.00 F ✓
Total Parts (S\$)						2,201.00

F=Franchise part.

Report was unsubmitted during this print-out.
 Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

No	Qty	Particulars	Amount
1	1	1 PC STICKER - 4 PAX	10.00 ✓
2	1	1 PC STICKER - 70KM/H	10.00 ✓
3	1	2 PCS TAILGATE GLASS GUM @30/PC	60.00 ✓
Sub Total (S\$)			80.00

Estimates on Labour

No	Particulars	Lab.Type	Amount
1	REMOVE & REFIX LH TAILGATE GLASS	New	80.00 ✓
2	REMOVE & REFIX RH TAILGATE GLASS	New	70.00 ✓
3	REMOVE & REFIX RH TAILGATE ASSY, THIRD BRAKE LIGHTS, REAR WIPER ASSY, LOCK ASSY, REAR BUMPER, TO KNOCK & REPAIR LH TAILGATE, REAR END PANEL & REALIGN THE SAME	New	700.00 ✓
4	PUTTY & RESPRAY ON TAILGATES & ALL AFFECTED AREAS	New	600.00 ✓
5	RUSTPROOFING	New	30.00 ✓
Gross Labour Cost (S\$)			1,480.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

Report was unsubmitted during this print-out.
 Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >