

ASS. REQ. BY: Kenneth REF: CT2 / 21010473/Kg y3

ASSIGNMENT JKO 22374

From: _____ Date: _____

Estimated Cost: _____

QD / TP / WS / TP RES / QD RES / EVA / INV / MY

To Inspect Vehicle No: _____

at Workshop m/s: Mon Hoang

of 547

Insured: _____

Policy No: _____

Claims No: SNM21D205760/C02

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: _____

DAC Accident Rpt: _____ Consistent?: Yes or No

IA / PR Seen: _____ Consistent?: Yes or No

st. Repairs: 8 days Res.: Yes or No

m Sum: 20 % 3 Val.: Yes or No

REV / REP / 24 HRS 08/30

Person Contacted: _____ Vehicle: IN / OUT

te / Time Action / Instruction

1 Err not ready, Bootlid jammed

The U/C / Chassis frame / Body Structure affected due to collision.

26/10/21 @ 4.25pm revised to Adeline Chng via Merimen.
Kenneth confirmed LS \$8200 (Red \$9903.11, 55%)

26/10 Typist

Days Of Repair: 8

Resurvey No. of Trlp: _____

Survey Fee: _____

Transportation: _____

S - RS. \$ _____

Site Insp (\$ _____)

Interview (\$ _____)

Tech Invs (\$ _____)

Weekend (\$ _____)

Others _____

TOTAL _____

Format: MER-TP

LumP Sum \$8200