

SUPREME AUTO SERVICE PTE LTD

176 SIN MING DRIVE #02-01 SINGAPORE 575721
TEL: 64520715 FAX: 64529250

ESTIMATE

EL & ASSOCIATES
c/o 46 Lenton Plain
Singapore 786548

Date: 3-May-17

QUANTITY	PARTICULARS	AMOUNT (\$)
RE: TOYOTA COROLLA ALTIS / SKZ8790H		
1 pc	front door protector / CMT	208.30
1 pc	rear door / 00	1,293.80
1 pc	rear door protector / CMT	175.90
1 pc	rear door regulator gear / QT	369.70
1 pc	rear door regulator motor / NM	468.90
1 pc	rear shock absorber / NM	138.50
1 pc	rear bumper / OR	437.20
1 pc	rear bumper side retainer / OR	89.50
1 pc	side kit (left) / R	586.50
sub-total		3,768.30
less 25%		942.08
sub-total		2,826.23
1 pc	ally rim / P-1785-45	350.00
sub-total		3,176.23
To remove and replace all the parts mentioned above, knocking and straighten up the necessary affected areas.		500 600.00
To spray painting on affected areas.		600.00
To transfer door accessories.		50 90.00
To remove and install rear undercarriage parts to enable repair.		20 80.00
To replace alloy rim & perform wheel balancing.		50.00
total		4,596.23

LKK Autos' services hereby notify the Repairer of the following:
• To rectify before the repair work commences.
• To display damaged parts during repair work.
• Parts to be replaced to complete the repair.
• 1pc alloy rim / P-1785-45
• No damage to the car body is allowed.
• Supreme Auto Service Pte Ltd must be notified and approval from insurance company is subject to final approval from insurance company.

Acknowledged by Repairer:

Signature:

Date:

To remove and replace all the parts mentioned above, knocking and straighten up the necessary affected areas.

To spray painting on affected areas.

To transfer door accessories.

To remove and install rear undercarriage parts to enable repair.

To replace alloy rim & perform wheel balancing.

L/S-2684.36
= 2700

P-1785-45
N-750
L-1220
3355-45

total

1270

4 days