



# Wah Hong Motors & Credit Pte Ltd

Enterprise Hub 38 Toh Guan Road East #01-57 S(608581)

Email: motor@wahhong.sg

(199806235M)

Vehicle No. SMN9161G HONDA CITY 1.5

Page No. 1

QTY	DESCRIPTION	CONDITION	REPAIRER'S ESTIMATE(S\$)	SURVEYOR'S ADJUSTMENT	
<b><u>PARTS (LIST ITEMS)</u></b>					
1	Rear fender LH <i>blue ✓</i>		1064.00		
1	Rear windscreen moulding <i>✓</i>		119.00		
1	Rear bumper (Repair refer to labour)		0.00		
		Part Items Total:	1183.00		
			-20%		-236.60
					946.40
<b><u>SPECIAL NETT ITEMS</u></b>					
1	Rear fender shield clips LH <i>✓</i>		25.00 ✓	} 125	
1	Rear windscreen sealant <i>✓</i>		50.00 ✓		
1	Rear fender sealant LH <i>✓</i>		50.00 ✓		
		SN Items Total:	125.00		
		Total Parts	1071.40		



# Wah Hong Motors & Credit Pte Ltd

Enterprise Hub 38 Toh Guan Road East #01-57 S(608581)

Email: motor@wahhong.sg

(199806235M)

Vehicle No. SMN9161G HONDA CITY 1.5

Page No. 2

S/N	DESCRIPTION	REPAIRER'S ESTIMATE (\$\$)	SURVEYOR'S ADJUSTMENT
<b>LABOUR</b>			
1	To remove the affected parts & fittings to commence repairs; panel beat & reshape the affected areas and replace the damaged parts and components	<del>600.00</del>	400
2	To supply paint materials, expandable items & putty, respray paint on parts replaced & repaired	<del>600.00</del>	200/400
3	To remove/refix/replace wiring system at accident damaged area and check for all electrical proper function	30.00 X	
4	To perform anti-rust treatment on affected areas	30.00 ✓	
5	To remove and refit rear seat in order to repair	<del>100.00</del>	60
6	To remove and refit roots lining & upholster garnish	<del>100.00</del>	60
7	To remove and replace rear windscreen	<del>150.00</del>	120
8	Wheel alignment (copy)	<del>80.00</del>	60
Labour Total :		1610.00	
TOTAL (PARTS & LABOUR):		2681.40	

1183  
125  
1130  
-----  
2438  
20%  
1950.40

4/8-1950

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:  
Date:

Rasul  
Hp 900 00068  
4 days  
4/8  
18/10/21 @ 1210  
Resurvey after repair