

Ume Cecilia

not Allowed

due

12/10/21

2/5840.00 5 days

FASTECH AUTO PTE LTD

1 Kaki Bukit Ave 6 #01-48 Autobay

Singapore 417883

Tel No: 67452063/ 67467158 Fax No: 67458520

Tax Reg No : 200006262D

VEHICLE No: SMT 9594J

1PC	BOOTLID	R		\$1,455.30	X
1PC	BOOTLID REAR LOGO	neu		\$52.80	/
1PC	BOOTLID 'ACCENT' EMBLEM	neu	50.00	\$65.00	/
1PC	BOOTLID WEATHERSTRIP	neu/TW	48.00	\$182.00	/
1PC	BOOTLID INNER LOCK	nn	166.20	\$199.00	X
1PC	BOOTLID OUTER CHROME MOULDING	nn		\$282.00	X
1PC	REAR BUMPER	nn	485.30	\$745.00	/
1PC	REAR BUMPER REFLECTOR N/S	neu	85.00	\$110.00	/
1PC	REAR BUMPER BEAM	neu	376.50	\$382.00	/
2PCS	REAR BUMPER BEAM BRACKETS @\$30.00	TW		\$60.00	/
2PCS	REAR BUMPER SIDE RETAINERS @\$38.00	N/S TW 0/5nn		\$76.00	1pc
1SET	REAR BUMPER CLIPS	neu		\$50.00	/
2PCS	REAR BUMPER PDC SENSORS @\$225.00	n/s shared 145		\$450.00	1pc
1PC	TAILLAMP N/S	scn/cna	366.50	\$482.00	/
1PC	REAR END PANEL	nn	599.30	\$615.00	/
1PC	REAR END PANEL TOP GARNISH	TW	182.20	\$208.00	/
1PC	REAR FLOOR PANEL	R		\$1,280.00	X
1PC	REAR FLOOR PANEL TOP BOARD	wagel	515	\$685.00	/
1PC	REAR FENDER N/S	R		\$1,722.00	X
				\$9,101.10	

TO CHECK WIRING

TO DISMANTLE & REPLACED REAR PDC SENSOR

TO DISMANTLE & REFIX BOOTLID MECHANISM

TO DISMANTLE & REFIX CUSHION UPHOLSTERY

TO DISMANTLE & REFIX FUEL TANK

TO RESET & REPROGRAMME SYSTEM

TO SPRAY RUST PROOFING

LABOUR FOR PANEL BEATING & REPLACED PARTS

TO PUTTY & SPRAY PAINTING

\$50.00 20

\$80.00 50

nn \$80.00 X

\$120.00 80

nn \$100.00 X

\$120.00 50

\$100.00 50

\$1,500.00 1000

\$1,500.00 1200

TOTAL

\$12,751.10

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

3167

502

7-1583.5

2-2450

4033