

Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200616038C
GST Registration No. : 200616038C

RUSSELL TSAO SHENG KAI
BLK 113C MCNAIR ROAD #04-262
SINGAPORE 324113

Contact : 93394798

TP chin
Derise

TAX INVOICE

Repair Code : CLM16962

Date in : 11/10/2021

Vehicle Num. : SKM274C

Model : MERCEDES BENZ A200 (BI-XENON)

Chassis/Eng# : WDD1760432J218756/27091030314160

Parts and Labour Assesment

Description of part	Qty	Unit Price	Amount
FRONT RH DOOR OUTER MOULDING <i>new</i>	1	158.00	<i>+</i> 158.00
REAR RH DOOR <i>Buckled</i>	1	1880.85	<i>✓</i> 1,880.85
REAR RH DOOR GLASS GUIDE CHANNEL SEAL <i>at</i>	1	193.00	<i>—</i> 193.00
REAR RH DOOR INNER INSULATOR PADDING <i>new</i>	1	46.00	<i>+</i> 46.00
REAR RH DOOR INNER TRIM BOARD <i>Delid</i>	1	1060.00	<i>✓</i> 1,060.00
REAR RH DOOR LOWER HINGE <i>new</i>	1	122.10	<i>+</i> 122.10
REAR RH DOOR OUTER MOULDING <i>new</i>	1	162.00	<i>+</i> 162.00
REAR RH DOOR UPPER HINGE <i>Payd</i>	1	125.45	<i>✓</i> 125.45
REAR RH DOOR VERTICAL GARNISH <i>new</i>	1	105.00	<i>+</i> 105.00
REAR RH DOOR WEATHER STRIP SEAL <i>new</i>	1	349.80	<i>✓</i> 349.80
RH SIDE CENTER PILLAR <i>the new</i>	1	820.00	<i>+</i> 820.00

Subtotal before discount

5,022.20

Percentage discount 10%

502.22

Sub-total 1

4,519.98

FRONT RH DOOR INNER TRIM BOARD CLIPS - SET <i>new</i>	1	50.00	<i>30</i> 50.00
FRONT RH DOOR OUTER MOULDING WRAP 3M STICKER <i>new</i>	1	150.00	<i>70</i> 150.00
FRONT RH DOOR WRAP 3M STICKER <i>new</i>	1	800.00	<i>300</i> 800.00
REAR RH DOOR INNER TRIM BOARD CLIPS - SET <i>new</i>	1	50.00	<i>30</i> 50.00

*** This is a computer-generated document which requires no signature.***

Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200616038C
GST Registration No. : 200616038C

RUSSELL TSAO SHENG KAI
BLK 113C MCNAIR ROAD #04-262
SINGAPORE 324113

Contact : 93394798

TAX INVOICE

Repair Code : CLM16962

Date in : 11/10/2021

Vehicle Num. : SKM274C

Model : MERCEDES BENZ A200 (BI-XENON)

Chassis/Eng# : WDD1760432J218756/27091030314160

REAR RH DOOR OUTER MOULDING WRAP 3M STICKER	1	150.00	70	150.00
REAR RH DOOR WRAP 3M STICKER	1	800.00	300	800.00
Subtotal before discount				2,000.00
Percentage discount 0%				0.00
Sub-total 2				2,000.00
Parts-total				6,519.98

LABOUR

To reset system after repair works

To remove, reinstall roof top trim upholstery, cushion seat, trim garnish, trim liner carpet. (to FR)

To transfer door glass, regulator gear, motor, railing, channel, trim board, mechanism lock and handle.

To re-spray painting on the change bodyparts, repair portion, and where consistent to the accident.

To provide labour, workmanship to change the above damaged bodyparts, repair, re-construct and re-align body structure, body alignments and damaged consistent to the accident.

To apply anti-rust chemical on repaired and replaced panel.

Labour Total

Parts & Labour Total

300.00

120.00

200.00

1,200.00

1,000.00

100.00

2,920.00

9,439.98

*** This is a computer-generated document which requires no signature.***

page 2

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Adrian L
13/10/21

04 Days.

15078.19

L/S: HK

4ic.