

ASS. REC. BY: Marcus

REF:

CS/SMD21010483/UVf3

ASSIGNMENT

From: Date:

Estimated Cost:

OD / IP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SMD 64496

at Workshop m/s

of

Insured:

Policy No.

Claims No. CMTD2103033/AGC

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

3

days

Res.:

Yes or No

Lum Sum:

F87

%

3 Val.:

Yes or No

CA / REV / REP. / 24 HRS

7850

Vehicle: IN / OUT

Date:

Person Contacted:

LTA 36487

Veh No: SMD 64496 Yr Regn: 28/11/19

Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

CA

Make:

KIA Cerato LX

c.c 1591

Colour:

Grey

A/C: Insured / Std / NI / NA

Sp. Reading

182484

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

KNAF1416ML5058017

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

205/55R16

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Continental

Front

6

Rear

6

R/Bal.

mm

R/Bal.

mm

L/Bal.

6 mm

L/Bal.

mm

D.O.A.

10/10/11

D.O.I.

13/10/11

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

O/S S. dy.

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

04/10/11

06:1277

16/10/11 P/P 1712.80 confirmed with myraiz (Red 2897.70,62%)

Date/Time, File Pass to?

☐

: Preli. Report

1)

☐

: Final Report

Date/Time, File Return to?

2) 18/10/21-typist

Days Of Repair: 3

Resurvey No. of Trip: 2

Survey Fee:

Transportation:

) S + RS. SI

) Photos

) Others

Report Format: TP

Lump Sum / I.B.I: (\$ 1712.80)

Add Fee:

☐

: Site Insp (\$)

☐

: Interview (\$)

☐

: Tech. Invs (\$)

☐

: Weekend (\$)

TOTAL

Regn No : SMQ6449G

Chassis No: KNAF1416ML5058017
 Vehicle Make & Model : KIA Cerato

ITEM NO	DESCRIPTION OF ITEMS	QUANTITY (Piece/Set)	UNIT PRICE (S\$)	AMOUNT (S\$)	
Nett					
Standard Items:					
1	Front door RH <i>Body RD</i>	1	\$ 1,277.00	\$ 1,277.00	✓
2	Front door handle RH <i>^^</i>	1	\$ 58.00	\$ 58.00	X
3	Front door rubber RH <i>^^</i>	1	\$ 80.50	\$ 80.50	X
4	Front door hinge RH <i>^^</i>	2	\$ 35.00	\$ 70.00	X
5	Front door lock <i>^^</i>	1	\$ 400.00	\$ 400.00	X
6	Front door outer moulding RH <i>^^</i>	1	\$ 80.50	\$ 80.50	X
7	Front wing mirror assembly RH <i>^^</i>	1	\$ 559.00	\$ 559.00	X
8	Front door inner trim board RH <i>^^</i>	1	\$ 699.00	\$ 699.00	X
9	Front door power window regulator <i>^^</i>	1	\$ 241.00	\$ 241.00	X
10	Front door power window motor <i>^^</i>	1	\$ 165.00	\$ 165.00	X
11	Front door tape <i>^^</i>	1	\$ 15.00	\$ 15.00	✓
Sub-total				\$ 3,465.00	
Less 10%				\$ 346.50	
List Items Total				\$ 3,118.50	

Special Nett Items:

1	Front door inner trim board clips <i>1M</i>	8	\$ 4.00	\$ 32.00	X
S/Nett Items Total				\$ 32.00	

Labour Charge Items:

2	To checking electrical wiring and check functions	\$	60.00	20
4	To remove, refix front door components and replace front door, check alignment	\$	400.00	X
7	To respray undercoating/rust proofing	\$	100.00	300
8	To respray painting & etc	\$	500.00	300
9	Panel beating, cut, weld, remove and replacing above parts	\$	400.00	200
Labour Charge		Total	\$	1,460.00

Estimate Parts & Labour

Grand total \$ 4,610.50

*not Authorized
 here*

13/10/21

P/P # 1712-80

3 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature: _____
 Date: _____

P-1182

102

P-1162-80

2-550

1712-80