

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/AIG21010488/BPA3Q2**Date:** 18/05/2023**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2100138880
Claimant Vehicle No :	SKW2614P	Insured Vehicle No :	SJR134J
Date of Loss:	11/10/2021	Nature of Claim:	TP
		Claim No:	7425813403SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKW2614P		
Make & Model:	NISSAN SYLPHY, 1.5 4AT ABS D/AB 2WD 4DR (A)	Engine No:	HR15328414B
Reg. Date:	05/03/2010 (Man. Year: 2010)	Chassis No:	JN1BAAG11Z0110869
Colour:	Grey	Odometer:	145986 km
Engine Capacity:	1498 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	Firenza 5 mm	Rear Left Side:	Firenza 5 mm
Front Right Side:	Firenza 5 mm	Rear Right Side:	Firenza 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	7,566.03	1,952.64	5,613.39	74.19
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,200.00	1,140.00	3,060.00	72.86
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	11,766.03	3,092.64	8,673.39	73.72
Approved Total (Overridden) (\$\$)		2,450.00		
(\$\$)	11,766.03	2,450.00	9,316.03	79.18
+ GST 7.00/7.00% (\$\$)	823.62	171.50	652.12	79.18
Nett Amount (\$\$)	12,589.65	2,621.50	9,968.15	79.18
+ Car Rental (7.0 x \$S\$100.00/day) (\$\$)		700.00		
+ Doc/Search Fee (\$\$)		7.45		
Nett Liability (\$\$)		3,328.95		
Global Sum Settlement (\$\$)		3,320.00		

INSPECTION

Date of Assignment: 12/10/2021

Date Inspected: 12/10/2021 Inspected At:

Estimated Period of Repair: 5.0 days

Team Autopro Pte Ltd - Sin Ming (HQ)
 160 SIN MING DRIVE #02-12 SIN MING
 AUTOCITY
 Singapore 575722

Adjuster: Lim Teow Guan

Manager: CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BOOTLID	Not Damaged	1,086.20 FL	*- FL
2	1		*BOOTLID LOGO	Not Necessary	256.30 FL	*- FL
3	1		*BOOTLID EMBLEM SYLPHY	Not Necessary	172.90 FL	*- FL
4	1		*BOOTLID ANTENNA SENSOR	Not Damaged	385.60 FL	*- FL
5	1		*REAR BUMPER	Broken	752.40 FL	*620.00 FL
6	2		*REAR BUMPER RETAINER	Necessary	152.80 FL	*113.80 FL
7	2		*REAR BUMPER BRACKET	No such part	236.00 FL	*- FL
8	1		*REAR BUMPER REFLECTOR	N/S Broken	372.80 FL	*80.00 FL
9	1		*REAR BUMPER SPONGE CENTRE	Not Damaged	204.60 FL	*- FL
10	2		*REAR BUMPER SPONGE SIDE	Not Damaged	307.40 FL	*- FL
11	1		*REAR BUMPER CHROME PROTECTOR	Dented	246.10 FL	*200.40 FL
12	1		*REAR END PANEL	Repair	698.30 FL	*- FL
13	1		*REAR END PANEL TOP GARNISH	Not Damaged	265.20 FL	*- FL
14	1		*TAIL LAMP LH	Broken	853.40 FL	*283.20 FL
15	1		*REAR FENDER INNER TRIM BOARD LH	Not Damaged	354.20 FL	*- FL
16	1		*REAR EXHAUST PIPE	Dented	758.90 FL	*468.60 FL
17	2		*REAR EXHAUST PIPE MOUNTING	Necessary	103.60 FL	*103.60 FL
18	1		*BOOTLID SEALANT	Not Necessary	100.00 FS	*- FS
19	1		*REAR BUMPER CLIPS	Necessary	50.00 FS	*30.00 FS
20	2		*REAR BUMPER REVERSE SENSOR	Scratched	500.00 FS	*200.00 FS
21	1		*REAR END PANEL SEALANT	Necessary	100.00 FS	*20.00 FS
22	1		*REAR END PANEL TOP GARNISH CLIPS	Not Necessary	50.00 FS	*- FS
23	1		*SPARE TYRE PANEL SEALANT	Not Necessary	100.00 FS	*- FS
24	1		*TAIL LAMP CLIPS	Necessary	50.00 FS	*20.00 FS
25	1		*TAIL LAMP SEAL	Not Necessary	80.00 FS	*- FS
26	1		*REAR FENDER INNER TRIM BOARD CLIPS	Not Necessary	50.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	8,286.70	2,139.60
- List Item Discount on L Items 10.00/10.00% (S\$)	720.67	186.96
Total Parts (S\$)	7,566.03	1,952.64

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	R&R BOOTLID COMPONENT	New	150.00	0.00
2	R&R REAR BUMPER REVERSE SENSOR	New	100.00	60.00
3	R&R REAR EXHAUST PIPE	New	150.00	80.00
4	CHECK WIRING	New	100.00	0.00
5	UPHOLSTERY	New	300.00	0.00
6	PANEL BEATING	New	1,600.00	600.00
7	RUST PROOFING	New	200.00	0.00
8	SPRAY PAINTING	New	1,600.00	400.00
Gross Labour Cost (\$)			4,200.00	1,140.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >