

Our Job Ref No : 305489963

Date : 14/10/21

ENGINEERING

Com-Kin-Dat Engineering Pte Ltd
59 Loyang Drive Singapore 508969
Fax: 6548 8158

FINALIZATION FORM

To : LKK

Fax :

Attn : THEVAN

Vehicle Reg No. SHB6353L

08/10/21

The survey and estimates of the repairs of the above-mentioned vehicle are as follows -

2 The repair job shall bill to: ECICS SJU9707G

2. The finalized amount shall be:

(a) Spare Parts after List discount

(b) Labour Charges

Total for Part-By-Part Repair Cost

(c) Lumpsum Repair (if applicable)

Total for Lumpsum repair cost after Less:

Final Lumpsum Repair cost

\$1200.00

3. Estimated normal period for repairs: 2 working days.

4. We shall treat the above amount as Correct and Confirmed if there is no reply from you within 7 working days

5. Thank you for your assistance.

We confirm the estimates and finalized amount

Signature :

Name : CHIANG

Tel : 62148314

Fax : 65468156

Signature :

Name : THEVAN

Date : 21/10/21

For Official Use Only

Item	Amount	Document Attached Yes or No	Confirm By (Signature)	Remarks
1. Rental Rate P/Day		YES		
2. Loss of Income Paid	-	N		
3. Survey Fees	-	-		
4. LTA Search Fee	\$7.49/\$2.00			
5. Medical Fees (on behalf of driver, if applicable)				
6. Overrun				

Remarks:

TYPE OF C: TP

SURVEY BY: LKK/THEVAN

DATE : 08/10/21

[illegible]

REPAIR ESTIMATE*

VEHICLE NO 86353L ✓

08/10/21

MAKE 30.04.2019

CHIANG/ECICS

MODEL IONIQ G2

Qty	Parts Description/ Labour	Type	Amount
1	REAR BUMPER		\$459.40
1	REAR BUMPER SIDE BRACKET LH/RH		\$55.80 \$111.60
10	REAR BUMPER CLIPS		\$2.20 \$22.00
1	REAR BUMPER CENTRE MOULDING		\$451.25
1	REAR BUMPER REFLECTOR RH		\$41.45
	SUB TOTAL		\$1,085.70
	20.00%		\$217.14
	DISCOUNTED TOTAL		\$868.56
1	REAR BUMPER MAT		\$50.00
1	REAR REVERSE SENSOR		\$180.00
			\$230.00
	Labour Charge		
	Panel Beating		\$450.00
	Spray Painting Charge		\$300.00
	Check Wiring and Lighting		\$60.00
	Remove/refix Reverse sensor		\$60.00
	TOTAL LABOUR		\$870.00
	ESTIMATE TOTAL		\$1,968.56
This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.			

Thuan@Lkhqauto.com
82235769

12/10/21 1615

2 days up

L/S before after repair photo

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: