

ASS. REC. BY:

REF:

ASM/ 21010494/KV

Kenneth

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____


Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.Bal. or Market Value: 511K

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 3-4 days Res.: Yes or NoLum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SLA 58600 Regn: 03, 16Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Honda Vezel c.c. 1496Colour: Black A/C: Insured / Std / NI / NASp. Reading: 155289 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: BU1 1109341Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModl: NI / S/Rlm / STD A/Rlm orTyre Size: F: 215/60R16

R: _____

BS / DUN / EXNOVA GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal. 7 mmL/Bal. 7 mmD.O.A. 11/10/21

Rear

R/Bal. 8 mmL/Bal. 8 mmD.O.I. 15/10/2021

Survey held at _____

Des. of Damages: Front / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

Data/Time, File Pass to?

☐ : Prel. Report

1)

☐ : Final Report

Data/Time, File Return to?

2)

Days Of Repair: _____

Resurvey No. of Trip: _____

Survey Fee:

Transportation:

S - RS - SI

Fees

Others

TOTAL

Add Fee: ☐ : Site Insp (\$☐ : Interview (\$☐ : Tech Invs (\$☐ : Weekend (\$

Report Format :

Lump Sum / I.B.I: (\$

AUTOWORX HOUSE

176 SIN MING DRIVE #02-01 SINGAPORE 575721
TEL: 64528211 FAX: 64517420

ESTIMATE

YANG YIANXIN

c/o 46 Lenton Plain
Singapore 786548

Not Authorised
11 Sep &
Resurvey After Painting
3-4 day

Date : 15/10/2021

QUANTITY	PARTICULARS	AMOUNT (\$)
	RE : HONDA VEZEL / SLA 5860 D	
1 pc	rear boot lid	1,264.90 X
1 pc	rear boot emblem "LOGO"	62.80
1 pc	rear bumper	895.70
1 pc	rear bumper side pad	456.20
1 pc	rear bumper side retainer	65.40
1 pc	rear bumper dust cover	130.10 X
1 pc	rear bumper lower dust cover	315.60 X
1 pc	rear bumper reflector	316.50
1 pc	rear end panel	577.60
1 pc	rear wheel arch protector	419.40
1 pc	rear end panel garnish	473.20 X
	LKK Auto Consultants hence notify the Repairer of the following: • To resurvey before/after spray painting • To display damaged part(s) during resurvey • Parts prices are subject to confirmation • Third party survey is on a "Without Prejudice" basis • No illegal modification(s) is allowed • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company	
	sub-total	4,977.40
	less 20%	995.48
	sub-total	3,981.92
1 pc	windscreen glass sealant	60.00 X
1 pc	reverse sensor	400.00 X
	To remove and replace all the parts mentioned above, knocking and straighten up the necessary affected areas.	800.00
	To check wiring system.	50.00
	To apply putty & spray painting on affected areas.	650.00
	To apply rust proofing on affected areas.	100.00
	To apply water proof sealant on affected areas.	100.00 X
	To replace rear windscreen glass.	140.00 X
	total	1,840.00

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission 12/10/2021 10:23 (SGT)
Date of Accident 11/10/2021 09:40 (SGT)
Exact Location of Accident Near PIE, Singapore
Additional Location Information PIE (EXIT 35) TOWARDS TUAS
Country/State of Loss Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number SLA5860D

INSURED/POLICYHOLDER

Is company? No
Name Of Registered Owner YANG TIANXIN
NRIC No SXXXX658A
Email Address tianxin11907@gmail.com
Mobile Phone No (Phone) +65-96452968
Alternative Phone No +65-96452968

VEHICLE PARTICULARS

Manufacturer Honda
Model Vezel
Variant -
Exact purpose for which vehicle was being used at time of accident Private use
Are you claiming under your own insurance policy for repair to your vehicle? No - Claiming third party
Vehicle Category Private car
Transmission Auto
CC 1500

INSURANCE COMPANY

Name of Insurance Company NTUC Income Insurance Co-operative Ltd
Type of Coverage Comprehensive
Fleet Policy No
Policy Number 5116298951-01
Cover Note Number -

DRIVER

Name of Driver YANG TIANXIN
NRIC No SXXXX658A

IMPORTANT NOTICE

- 

Witnessed by Reporting Centre
Personnel

(A) SLA speed
 (B) SG 4513 L
 (C) unknown

DFB records T was
 (EX07 35