



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
AXA INSURANCE PTE LTD		Ref:	CS3/ASM21010495/y3
8 SHENTON WAY #24-01		Date:	12/10/2021
AXA TOWERSINGAPORE 068811		Code:	ASM
<b>1. Policy Particulars :- (THIRD PARTY CLAIM)</b>			
Insured Veh.	SH 7448D	Veh. Inspected	GBK 8035R
Policy No.		Coverage (\$)	0.00
Claim No.	S1M03JPE	Excess (\$)	0.00
Assign From	LOH CYNTHIA	Assign Date	12/10/2021
<b>2. Vehicle Particulars &amp; Condition</b>			
Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			
<b>3. Conditions of Tyres</b>			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
<b>4. Description of Damages</b>			
<b>5. General Information</b>			
Accident Date	09/10/2021	Inspection Date	13/10/2021
Survey held at	5 Yishun Ind Street #01-20 North Spring BizHub		
Repairer	ONE ZONE AUTOMOTIVE LLP		
<b>5a. Remarks</b>			
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.			