

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE

DATE: 11/10/21

3P INSURANCE: NTUC

MODEL: HYUNDAI I40

SURVEYOR: NA

VEH NO.: SH 9940K

MVA: LIM T S

PART NO.	DESCRIPTION	QTY	LIST PRICE	REMARKS
	Bootlid	1		\$2,609.80x
	Bootlid Hinge (LH/RH)	2	\$142.30	284.60x
	Bootlid 'H' Emblem	1		\$28.70x
	Bootlid CRDI Plate	1		\$27.90x
	Bootlid I40 Emblem	1		\$27.90x
	Bootlid Moulding	1		\$85.00x
	Bootlid Lower Outer Garnish	1		\$227.90x
	Rear Bumper	1		\$553.00 de
	Rear Bumper Reinforcement	1		\$428.40 xuy
	Rear Bumper Clip (10 pcs)	10	\$2.20	\$22.00 xuy
	Rear Bumper Side Bracket RH/LH	2	\$35.60	\$71.20 xuy
	Rear Bumper Sponge	1		\$119.50 xuy
	Rear Bumper Under Cover	1		\$228.00 de
	Exhaust Muffler LH	1		\$967.70 R bt
	Exhaust Centre Pipe	1		\$730.10 A bt
	SPARE PARTS SUB TOTAL			\$6,411.70
	LESS 20%			\$1,282.34
	DISCOUNTED TOTAL			\$5,129.36
	Bootlid ComfortDelGro	1		\$30.00 xuy
	Bootlid 65521111	1		\$30.00 xuy
	Reverse Sensor	1		\$135.70 xuy
	S/NETT TOTAL			\$195.70
	LESS 10%			\$19.57
	DISCOUNTED TOTAL			\$176.13
	Rear Bumper Mat	1		\$50.00 xuy
	Rear Fender Adv.Sticker RH/LH	2	\$100.00	\$200.00 xuy
	Rear Bumper Adv.Sticker	1		\$50.00 xuy
	NETT TOTAL			\$300.00
	SPARE PARTS & OTHERS TOTAL			\$5,605.49
	Panel Beating			\$800.00 x 250
	Spray Painting Charge			\$600.00 250
	Check Lightings			\$40.00 xuy
	Tuff Kote			\$40.00 xuy
	Remove/Refix Reverse Sensor			\$120.00 30
	Remove/Refix Exhaust System			\$100.00 60
	LABOUR TOTAL			\$1,700.00
	ESTIMATE TOTAL			\$7,305.49

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

2500.80
2000.64

MLKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

\$00

620

Taylor 97495744
wpr 11/10/21 @ 430
US resurvey after repair
Taylor 11/10/21 @ 430
2 days