

ASS. REC. BY: Tang JH

REF:

INC

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD/TP/WS/TP RES/OD RES/EVA/INV/MV

To inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS WPDate: _____ Person Contacted: LIM TS

Vehicle: IN / OUT

Veh No: SH9940K Yr Regn: 2017 Dec

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Hyundai 140 c.c. 1685Colour: Blue A/C: Insured / Std / NI / NASp. Reading: 625918 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: UM H L B 41 9 4 4 4 0 9 8 3 6Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modl: NII / S/Rim / STD A/Rim or

Tyre Size: F: 205/60R16

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Wetlake

Front: _____ Rear: _____

R/Bal. 6 mm R/Bal. 6 mmL/Bal. 6 mm L/Bal. 6 mmD.O.A. _____ D.O.I. 11/10/21Survey held at Comfort Lodge

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

Date/Time, File Pass to?

☐ : Prel. Report1) _____
Date/Time, File Return to?☐ : Final Report

2) _____

Report Format: _____

Lump Sum / L.B.R. (%) _____

Days Of Repair: _____

Resurvey No. of Trip: _____

Survey Fee: _____

Transportation: _____

Add Fee: ☐ : Site Insp (\$ _____)☐ : Interview (\$ _____)☐ : Tech. Invs (\$ _____)☐ : Weekend (\$ _____)

S + RS. SI

Photos

Others

TOTAL

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE

DATE: 11/10/21

MODEL: HYUNDAI I40

VEH NO.: SH 9940K

3P INSURANCE: NTUC

SURVEYOR: NA

MVA: LIM T S

PART NO.	DESCRIPTION	QTY	LIST PRICE	REMARKS
	Bootlid	1		\$2,609.80 x
	Bootlid Hinge (LH/RH)	2	\$142.30	284.60 x
	Bootlid 'H' Emblem	1		\$28.70 x
	Bootlid CRDI Plate	1		\$27.90 x
	Bootlid I40 Emblem	1		\$27.90 x
	Bootlid Moulding	1		\$85.00 x
	Bootlid Lower Outer Garnish	1		\$227.90 x
	Rear Bumper	1		\$553.00 de
	Rear Bumper Reinforcement	1		\$428.40 ?
	Rear Bumper Clip (10 pcs)	10	\$2.20	\$22.00 nh
	Rear Bumper Side Bracket RH/LH	2	\$35.60	\$71.20 ?
	Rear Bumper Sponge	1		\$119.50 ?
	Rear Bumper Under Cover	1		\$228.00 de
	Exhaust Muffler LH	1		\$967.70 R
	Exhaust Centre Pipe	1		\$730.10 x
	SPARE PARTS SUB TOTAL			\$6,411.70
	LESS 20%			\$1,282.34
	DISCOUNTED TOTAL			\$5,129.36
	Bootlid ComfortDelGro	1		\$30.00 x
	Bootlid 65521111	1		\$30.00 x
	Reverse Sensor	1		\$135.70 nh
	S/NETT TOTAL			\$195.70
	LESS 10%			\$19.57
	DISCOUNTED TOTAL			\$176.13
	Rear Bumper Mat	1		\$50.00 nh
	Rear Fender Adv. Sticker RH/LH	2	\$100.00	\$200.00 nh
	Rear Bumper Adv. Sticker	1		\$50.00 nh
	NETT TOTAL			\$300.00
	SPARE PARTS & OTHERS TOTAL			\$5,605.49
	Panel Beating			\$800.00 x 250
	Spray Painting Charge			\$600.00 250
	Check Lightings			\$40.00 x
	Tuff Kote			\$40.00 x
	Remove/Refix Reverse Sensor			\$120.00 30
	Remove/Refix Exhaust System			\$100.00 60? photo
	LABOUR TOTAL			\$1,700.00
	ESTIMATE TOTAL			\$7,305.49

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Tan Jie 97495749
wpr 11/10/21 @ 430
1/5 resurvey after repair
Tan Jie @ 11/10/21 @ 430
2 days

Date/Time: 11.10.2021 09:32

Page : 1

m: ARC Repair TP(CLSO)1

JOB CARD Sales Order:

JC NO:305490143

MER

COMFORT TRANSPORTATION PTE LTD

7010045

MER NO.

SS 383 SIN MING DRIVE
Singapore SINGAPORE 575717

65508755

(O)

3)

JNT CARD NO.

REGN NO.:

SH 9940K

MILEAGE

MAKE:

HYUNDAI

FUEL

E.....1/2.....F

MODEL

I-40

DATE/TIME IN
11.10.2021 09:15

YR OF MANU.

20.12.2017

TARGET DATE

CHASSIS CODE

KMHLB41UMHU099836

COMPLETION DATE/TIME:

JOB DESCRIPTION


Ident Date: 08.10.2021

URE: 3P 08.10.2021

IO

LABOR CODE

DESCRIPTION



ED & PASSED OUT BY:

SERVICE ADVISOR

CUSTOMER'S SIGNATURE

gement Slip

Exit Pass

SH 9940K

LIMITS

Vehicle No.:

SH 9940K

ervice Advisor

Signature/Date

Name of Service Advisor

Date

and to Service Reception upon collection

To be kept by Security Guard