

COMFORT TRANSPORTATION PTE LTD

REPAIR ESTIMATE

Vehicle No. : SHA6575T

Make : HYUNDAI

Model : IONIQ(G2)

Date: 09/10/21

Insurance: NTUC

MVA: MS. LOKE YY

Qty	Parts Description / Labour	Type	Unit Price	Amount
1	REAR BUMPER COVER			de \$459.40
10	REAR BUMPER CLIPS			u/c \$22.00
1	REAR BUMPER CENTRE MOULDING ASSY			de \$451.25
1	REAR BUMPER REINFORCEMENT			\$394.80
1	ANTENNA SMARTKEY			\$40.50
1	REAR BUMPER FOG LAMP			\$201.50
1	LICENCE LAMP			X \$85.30
	SUB TOTAL		932.65	\$1,654.75
	LESS 25%	20%	746.12	\$413.69
	DISCOUNTED TOTAL			\$1,241.06
1	REAR NUMBER PLATE WITH TRIM COVER	-10.00%	235	over \$55.00
1	REAR BUMPER REVERSE SENSOR	-10.00%	20% - 216.50	u/c \$180.00
				\$235.00
	Labour Charge			
	PANEL BEATING			350 \$400.00
	SPRAY PAINTING CHARGE			250 \$300.00
	REMOVE/REFIX REVERSE SENSOR		630	30 \$80.00
	TOTAL LABOUR			\$780.00
	ESTIMATE TOTAL		\$1587.62	\$2,256.06
			2 delays	

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

Tuphi 97495749
 WRT 11/10/21 4pm
 p/p survey before paint
 Tuphi 11/10/21 4pm
 2 delays

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: