Soon Bee Vehicle & Bodywork Maintenance

10 Anson Road #33-17 International Plaza Singapore 079903.

Tel: 90036715 Fax: 62256130 Email: soonbee_vehicle@yahoo.com.sg

GST Registration No: 53076555A

Our Ref No.:

SB-19447

Date:

11-Oct-21

AMK Workshop. Foreman: Li Ming FAX: 64562752

QUOTATION FOR ACCIDENT REPAIR ON BUS NO:

SBS6009M

We are pleased to offer our best proposal to provide our services of labour for repair of above mentioned vehicle at SBS Transit, Ang Mo Kio Workshop.

1)	Vehicle No :	SBS6009M			
	Model :	SD			
2)	Total Cost :	- Material & Parts Cost	;		
		- Labour Cost	: \$	750.00) /
			GST (7%) : _\$	52.50	<u>) </u>
			Total: \$	802.50)
		Work Scopes			
		Dismantle and replace o/s No. 7 window glass			
		Repair o/s fuel tank cover			
		Repair o/s/r corner dome panel			
		Dismantle and replace o/s/r cor	ner bumper	Name of the last	
		Repair o/s/r radiator access doo Touch up putty on accidy area	or		
		Respray accident area			- A-7-1
		Respiray accident area		5011	58
					all a
		sas Transit	Marine YA		
		- Comments	manual and a second		
			automition of the second		
			Supply workers for	19	ManHour
				VELUCI	EC
		TERM OF PAYMENT: 30 DAYS UPON DELIVERY OF VEHICLES Vehicle Electric and wiring system not included			
		Vehicle Electric and wiring syste	LKK Auto Co	naultants h	ence notify
		(B) Materials and Parts:	the Repairer		
		- Supply by SBS Transit	• To resurvey be		
		Cappi, by Cab Harris	To display dar		
		C) Mechanical/Engine Effect	Parts prices a		
		- ŃA	Third party su No illegal mod	ivey is on a "W	ithout Prejudice" basis
					nowed be resurveyed and
_		id for 1 Month only enerated document. No signature	a Sunglamantar	W Haterry at 1 movement	Park Printer of Section 1974 Avenue