



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
LONPAC INSURANCE BHD			Ref:	CS3/LPC21007599/R1uf3e2-1
300 BEACH ROAD			Date:	09/11/2021
#17-04/07 THE CONCOURSESINGAPORE 199555			Code:	LPC2
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	GZ 9354A	Veh. Inspected	FBH 2411T	
Policy No.		Coverage (\$)	0.00	
Claim No.	20/21/21/VC00/024706	Excess (\$)	0.00	
Assign From	KENNY LIM	Assign Date	13/10/2021	
2. Vehicle Particulars & Condition				
Make & Model	HONDA CBF150	c.c	149	
Engine No.	HIDDEN	Year of Reg.	2013	
Chassis No.	LALKC11B0C3300441	Colour	MULTI COLOUR	
Odometer	-	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	FAIR			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	80/90-18	GOLDEN BOY	4 mm	
L/H Front Tyre			mm	
R/H Rear Tyre	3.60-18	GOLDEN BOY	4 mm	
L/H Rear Tyre			mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE N/S BODY.				
DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	26/06/2021	Inspection Date	14/07/2021	
Survey held at	AH HWA MOTOR SERVICING 1016 YISHUN INDUSTRIAL PARK A, #01-228, YISHUN INDUSTRIAL PARK A, SINGAPORE 768758			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			4 Working Days	