

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/0836/2021/JT
DATE : 12-Oct-21
WIP : 48493

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 12/10/21

AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY

#07-16 AIG BUILDING

SINGAPORE 079120

Attn: Motor Claims Dept

Tel: 6880 4602 - Fax: 6880 4838

Hi Adrian

5 days exclude 1 Sunday

Johnny Boo 9 Nov 21

OWNER'S NAME : MR YIEU WING FOOK
ADDRESS : 25 LI HWAN CLOSE
SINGAPORE 557148
TELEPHONE : HP +65 96156898
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : 1800055340-03
VEHICLE NO : **SJV 6766 A**
MODEL CODE : A5 SB 2.0 TFSI S
MODEL YEAR : 16/5/2019
ENGINE NO : CVK 059040
CHASSIS NO : WAUZZZF54JA088886
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 10-Oct-21
PLACE OF ACCIDENT : 25 LI HWAN CLOSE

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SJV 6766 A

S/N	NATURE OF JOBS		ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE AND REINSTALL REAR PARKING AID AND REAR LID KICK SENSOR.CHECK FUNCTION.	S/N \$	360.00	\$ 360.00
2	TO DISLODGE AND REINSTALL REAR WIRE HARNESS FOR LIGHTS, BATTERY MANAGER, FUSE AND RELAY TRAYS, ELECTRICAL AND AUDIO EQUIPMENT. INSPECT FOR DAMAGE AND RENEW WHERE NECESSARY.	S/N \$	480.00	
3	TO DISMANTLE AND RENEW REAR BUMPER. TO CUT OUT AND WELD REAR END PANELLING AND LHS TAILLAMP PANEL. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$	5,600.00	\$ 500.00
4	TO RESPRAY REAR BUMPER, LHS TAILLAMP PANEL, REAR END PANELLING AND SPARE WHEEL HOUSING.	\$	3,500.00	\$ 550.00
5	TO RENEW BOTH REAR EXHAUST SILENCER AND CENTRE SILENCER. TO ALIGN TO POSITION.	S/N \$	480.00	\$ 480.00
6	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$	192.00	\$ 192.00
TOTAL LABOUR CHARGES		:	\$ 10,612.00	\$ 2,082.00

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SJV 6766 A

			DAMAGED PARTS & PRICES		
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS	
1	REAR BUMPER	1	\$ 2,504.00	\$	2,003.20
2	REAR BUMPER FIXING PARTS	1	\$ 165.00		
3	REAR BUMPER SECURING STRIP	1	\$ 223.00	\$	178.00
4	REAR BUMPER CHROME TRIM	1	\$ 1,016.00	\$	812.80
5	REAR BUMPER REFLECTOR - LH	1	\$ 41.00	\$	32.56
6	REAR TAIL LIGHT - LH	1	\$ 1,142.00	\$	913.60
7	REAR TAIL LIGHT TRIM - LH	1	\$ 30.00		
8	REAR BUMPER CARRIER	1	\$ 940.00		
9	REAR BUMPER CARRIER SEAL	2	\$ 28.00		
10	REAR BUMPER GUIDE SECTION - LH	1	\$ 44.00		
11	REAR BUMPER TOP GUIDE SECTION - LH / RH	2	\$ 46.00		
12	REAR BUMPER PARKING AID SENSOR	2	TBC	\$	195.12
13	REAR BUMPER PARKING AID SENSOR SEAL RING	4	\$ 14.00		
14	REAR BUMPER WIRING SET	1	\$ 671.00		
15	OPENING BOOTLID CONTROL UNIT	1	\$ 411.00		
16	REAR LID KICK SENSOR	1	\$ 206.00		
17	AERIAL RETAINER	1	\$ 26.00		
18	TELEPHONE AERIAL	1	\$ 174.00		
19	TAIL LAMP PANEL	1	\$ 164.00		
20	REAR CROSS PANEL	1	\$ 360.00		
SUB TOTAL SPARE PARTS		:	\$ 8,205.00	\$	4,135.28

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APROVED
 SPARE PARTS ARE SPECIAL NETT.

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SJV 6766 A

			DAMAGED PARTS & PRICES		
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS	
		C/F		\$	4,135.28
21	REAR CROSS PANEL REINFORCEMENT	1	\$ 632.00		
22	REAR SILENSER - LH	1	\$ 883.00	\$	706.40
23	REAR SILENSER - RH	1	\$ 883.00		
24	DUAL CLIP	2	\$ 104.00	\$	82.88
25	REAR SILENCER BRACKET	2	\$ 83.00	\$	66.40
26	CENTRE SILENCER	1	\$ 896.00	\$	716.40
27	CENTRE SILENCER DUAL CLIP	1	\$ 59.00	\$	47.12
28	HEAT SHEILD - LH	1	\$ 152.00		
29	HEAD SHIELD - CENTER	1	\$ 69.00		
30	EXHAUST CHROME TRIP	1	\$ 153.00	\$	122.40
31	ACRYLIC SEALANT	S/N	\$ 180.00		
32	CRAVITY WAX	S/N	\$ 140.00		
33	STONE CHIP TREATMENT	S/N	\$ 180.00		
34	METAL FILLER POWDER	S/N	\$ 280.00		
35	SUNDRIES		\$ 350.00		
TOTAL SPARE PARTS		:	\$ 13,249.00	\$	5,876.88
TOTAL LABOUR CHARGES		:	\$ 10,612.00	\$	2,082.00
GRAND TOTAL		:	\$ 23,861.00	\$	7,958.88

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APROVED
 SPARE PARTS ARE SPECIAL NETT.
 BL-03/11/21



PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME :
SURVEYED DATE :
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS :

PLEASE NOTE :

THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY.
FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT