COMFORTDELGRO ENGINEERING PTE LTD

SMS-KIV)

REPAIR ESTIMATE

LKK-

DATE:

11-Oct-21

MODEL:

Toyota Prius

VEHICLE NO.: SHB3269S - CityCab

INSURANCE: NTUC CLS

MVA: LIM T S

PART NO.	DESCRIPTION	THE PROPERTY AND ADDRESS OF THE PARTY ADDRESS OF THE PARTY AND ADDRESS OF THE PARTY ADDRESS OF THE PARTY AND ADDRESS OF T	QTY	UNIT PRICE	AMOUNT	
	Rear Trunk Outer Garnish		1		\$889.70	4
	Rear Trunk Lid Logo (Prius) Rear Trunk Lid Logo (Hybrid)		1	,	\$60.80 he	
			1		\$52.40 pl	
	Rear Trunk Lid Logo (Toyota S	1		\$52.90 ×		
	Rear Bumper	1		\$458.60 d	<i>{</i>	
	Rear Bumper Re-Inforcement		1		\$318.80 <i>h</i>	()
	Rear Bumper Lower Cover-Black		1		\$552.60 d	2/
	Rear Bumper Side Retainer LH		1		\$112.70 L	
	Rear Bumper Clips		10	\$2.20	\$22.00 4	
	Rear Bumper Lower Extension LH		1		\$232.00	<i>(</i>
	Taillamp Upper LH		1		\$557.90	m
Y	Tailliamp Lower LH		1		\$548.40 0	
			7			2411.20
	SUB TOTAL LESS 25%				\$3,858.80	1808.40
ł				\$964.70	,,,	
}	DISCOU	NTED TOTAL		i '	\$2,894.10	
]				\$135.70	·un
1	Reverse Sensor		1		\$135.70 \(\sigma \)	
	Rear Trunk ComfortDelGro		1		\$30.00	/
	Rear Trunk 65521111		1		\$40.00	
	Rear Trunk APPS		1	i	\$40.00 ~	<u>C</u> ,-
1	000	NETT TOTAL			\$235.70	100
	SUB NETT TOTAL LESS 10%				\$23.57	(00)
		NETT TOTAL			\$212.13	
		NEII IOIAL			Ψ212.10	
	TOTAL S	PARE PARTS			\$3,106.23	
	Labour Charge	LKK Auto Cons	ultants henc	e notify		2.~
	Panel Beating	the Repairer of	the following	:	\$800.00 5	U.S
	Spray Painting Charge	To resurvey before			\$600.00	00 _
	Wiring Charge	 To display damag Parts prices are s 			\$40.00 5	0
	Tuff Kote	Third party survey			\$40.00 ×	0
	Remove/Refix Reverse Sens	or • No illegal modifica	tion(s) is allow	d	\$120.00 1	J
	TOTAL	 Supplementary its 		esurveyed and rsurance Company		1085
	то	TAL LABOUR		Istrance Company	\$1,600.00	(00:
		Acknowledged by R	epairer			2. 2
	EST	MATE TOTAL			\$4,706.23	2993.40 45\$2400
	LOI	Date:				
	L			 		. 1. 1.

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

Taylor 97497747 cls hism after report taylor 932day. 🔉 2deys.

Pg 1 of 8